MACADAM

Skoda Enyaq '21 BEV

Vehicle information

Make:	**Skoda**	License:	**N736FP**
Gearbox:	**Automatic**	Body color:	
Model:	**Enyaq '21 BEV**	VIN:	**TMBJB7NY6NF018285**
Fuel type:	**Electric**	Power:	**132 kW**
Version:	**Enyaq iV60**	First registration	**15/10/2021**
Mileage:	**137051 km**	N° of doors:	

Damage summary

- **Front** 2
- **Interior** 1
- **Left** 1
- **Rear** 3
- **Right** 2

Commercial pictures





















SOS
Noodoproepfunctie is beperkt.
Werkplaats opzoeken, alstublieft.
PARK
137051 km
28 %
108 km
SOS


LEES EERST


TMBJB7NY6NF018285


















Smitspol
13:56
15.0°
Let op omgeving en klaar om te remmen!
19.5°
Home
Favorieten
Menu
ECO


Smitspol
13:54
15.5°
Reisdoelen
Kaart
Setup
50
19.5°
ECO


Batterijcertificaat
Datum van diagnose: 28/10/2026
90,69%
Status van de gezondheid (SOH)*
Skoda Enyaq 60
VIN : TMBJB7NY6NF018285
Kilometerstand : 137.051 km
* SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA
Approved Battery Health-Check





Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Hook	**Yes**	Panoramic roof	**Yes**	Radio multimedia	**Yes**
Rear view camera	**Yes**	Sun Roof electric	**Yes**	Telephone equipment	**Yes**

Damages

Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right




Bumper F
Scratch(es)
Repair and paint (complete)
Front









Bumper R
Scratch(es)
Repair and paint (complete)
Rear







Bumper RM
Scratch(es)
Replace
Rear





Bumper trim F
Scratch(es)
Replace
Front





Door RL
Dent(s)
Repair and paint (complete)
Left







Fuel cap cover
Deformed / Strained
Replace and paint
Right





Interior
Stain
Cleaning
Interior





Tailgate / Boot

Dent(s) and scratch(es)

Repair and paint (complete)

Rear









Tyres

Front Left	
Summer	
235/50/20/100/T	
Bridgestone	
3.2 mm	
Front Right	
Summer	
235/50/20/100/T	
Bridgestone	
2.7 mm	
Rear Left	
Summer	
235/50/20/100/T	
Bridgestone	
2.4 mm	
Rear Right	
Summer	
235/50/20/100/T	
Bridgestone	
2.7 mm	

Checks

CO2 Emission	**0**	Digital maintenance	**Yes**
Luggage cover	**Yes**	Number head rests	**5**
Number of charging cables (rapid charge)	**1**	Number of keys total	**2**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Service book	**N/A**
User's manual	**Yes**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.