TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48216816
Order No. / Reference: 27054385
Inspection date: 16 Oct 2026

Manufacturer: Hyundai	Model: IONIQ 5 77,4 kWh Techniq
VIN: KMHKN81EFPU178984	





Vehicle details

Manufacturer / Type / Model / Equipment	
Hyundai IONIQ 5 77,4 kWh Techniq	
Vehicle Identification number	KMHKN81EFPU178984
Mileage (Read)	52,655 km
First registration	25 Jul 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	07/2028
Fuel type	Electric
Power	56 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	SUV
Colour / colour code	Atlas White
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	10,802 km
Last service on / at	09/2025 at 33,457 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV786083
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8252 / ALB 00003		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,450 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105W	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	235/55 R19 105W	Summer tyres on Light alloy	Michelin	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105H	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	235/55 R19 105H	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments (storage pocket on the back of the front seats - compartment in the front center armrest - compartment below the dashboard - compartments in the doors - compartments in the center console - front/rear cup holders)
- Active Lane Keeping Assist (LKA)
- Alarm system (including occupant alarm (RSA))
- Lead Vehicle Approach Warning (LVDA)
- Assistant: Attention Assistant (DAW)
- Assistant: Autonomous Emergency Braking (FCA-JC) including forward collision warning (pedestrian/cyclist detection - turning and intersection function)
- Electrically adjustable, heated, and foldable exterior mirrors (painted in body color)
- Battery heating system
- Hill Start Assist (HAC)
- Roof spoiler with 3rd brake light
- Drive Modes (Eco, Normal, Sport) and CUSTOM Mode
- Door sill trims in aluminum look
- Electronic Stability Control (ESC)
- Electric rear windows
- High Beam Assist (HBA)
- Luggage net
- Transmission: Direct drive shift-by-wire
- Heated rear window with automatic shut-off
- Intelligent Traffic Sign Recognition (ISLA)
- Child safety lock for rear doors (manual)
- 2-zone automatic climate control (automatic interior fogging control - rear air outlet nozzles)
- Paint finish: Lucid Blue mineral effect paint
- Charging: 800-volt technology (charging from 10% auf 80% in 18 minutes at appropriate charging point)
- Charging: Type 2 charging cable
- LED taillights in pixel design (brake and driving lights)
- Steering wheel: Leather steering wheel
- Headlight range adjustment, manual
- light sensor
- Center console is adjustable
- Navigation system: Navigation system with 12.25-inch touchscreen (DAB radio - RDS radio)
- Upholstery: Fabric/leather combination
- Rear Cross Traffic Alert System with Emergency Braking Function (RCCA)
- Radio accessories: Bluelink telematics services
- Radio accessories: USB charging ports front/rear (2x)
- Tire repair kit
- Wheels: 19-inch alloy wheels (235/55 7.5x R 19 tires)
- Power steering
- Safety steering column, adjustable longitudinally and tilting
- Seats: Heated front seats
- Seats: Passenger seat electrically adjustable
- Adaptive Cruise Control (ASCC) (with distance control and stop function)
- Airbags: (Center airbag between driver and front passenger - Front airbags for driver and front passenger (passenger airbag can be deactivated) - Side airbags for driver and front passenger - Curtain airbags extending to the rear)
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD).
- Assistant: Parking aid, front
- Assistant: Blind Spot Assistant Active (BCA)
- Exit Warning (SEW)
- Exterior mirrors with integrated turn signals
- Underside of exterior mirrors in high-gloss black
- Rear trunk light
- Adaptive Brake Light (ESS)
- Digital cockpit with 12.25-inch display
- Rear parking sensors
- Electric parking brake
- Emergency Call System (eCall)
- Electric front windows (with automatic up/down function and anti-pinch protection)
- luggage compartment cover
- Glove compartment drawer
- Interior mirror, automatically dimming
- Isofix child seat attachment at the rear (on the outer seats including top tether anchor points)
- Headrests (5) front and rear height adjustable (length adjustable front)
- Charging: 3-phase onboard charger
- Charging: ICCB emergency charging cable (with Schuko plug)
- LED lighting for the trunk and interior
- LED daytime running lights
- Steering wheel: Two-spoke multifunction steering wheel (heated - paddle shifters for adjusting recuperation)
- front/rear center armrest
- Multi-collision brake (MCB)
- Package: LED package (full LED projection headlights in pixel design - V-shaped LED light strip at the front - front/rear turn signals in LED technology)
- Radio accessories: 6 loudspeakers
- Radio accessories: Apple CarPlay, Android Auto
- Radio accessories: Bluetooth hands-free system
- Rain sensor
- Tire pressure monitoring system (TPMS)
- Rear view camera
- Safety belts (front three-point belt system with belt tensioner and belt force limiter - rear three-point belt system - belt warning on all seats - front height adjustable)
- Seats: Driver's seat electrically adjustable
- Seats: Electrically adjustable lumbar support - passenger seat

- Seats: Driver's seat/passenger seat height adjustable
- Seats: Electrically adjustable lumbar support - driver's seat
- Seats: Sliding rear bench seat
- Seats: Heated rear seats (outer seats)
- Seats: Heated front seats
- Lane Following Assist (LFA)
- 12V socket - front
- Phone: Smartphone tray with wireless charging function (IQ Standard)
- Tinted glazing all around
- Glazing: Dark tinted windows from the B-pillar back.
- Electronic immobilizer
- Central locking with remote control and smart key system (including start/stop button)
- Seats: Rear seat backrest asymmetrically split and foldable
- Sun visor, driver and passenger, with mirror, illuminated
- 12V power outlet in the luggage compartment
- 230V power outlet under the rear seat
- Door handles painted in car color
- Manually foldable door handles
- Glazing: Acoustic windshield
- Glazing: heat-insulating windshield
- heat pump

Extra equipment

- Trailer hitch
- Paint finish: Solid special color
- Roof support beam, aluminum
- Package: BOSE sound system (acoustic laminated glass front and rear - 8 speakers including subwoofer and amplifier - BOSE sound system)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Front bumper	Spoiler - Scratch(es) - Smart repair
2	Rear bumper	Spoiler (+ Blende rechts gebrochen erneuern) - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - No deduction
2	Trailer hitch	Trailer hitch - Corrosion - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Roof rack system

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Damage 1: Front bumper: Spoiler - Scratch(es) - Smart repair



Damage 1: Front bumper: Spoiler - Scratch(es) - Smart repair



Damage 2: Rear bumper: Spoiler (+ Blende rechts gebrochen erneuern) - Scratch(es) - Paint



Damage 2: Rear bumper: Spoiler (+ Blende rechts gebrochen erneuern) - Scratch(es) - Paint



Damage 2: Rear bumper: Spoiler (+ Blende rechts gebrochen erneuern) - Scratch(es) - Paint



Damage 2: Rear bumper: Spoiler (+ Blende rechts gebrochen erneuern) - Scratch(es) - Paint



Damage 2: Rear bumper: Spoiler (+ Blende rechts gebrochen erneuern) - Scratch(es) - Paint



Wear and tear 2: Trailer hitch: Trailer hitch - Corrosion - No deduction



Wear and tear 2: Trailer hitch: Trailer hitch - Corrosion - No deduction