MACADAM

BMW X2

Vehicle information


Brand:	**BMW**	License plate:	**2BRY169**
Gearbox:		Body color:	
Model:	**X2**	LEVEL:	**WBAYK510005V08672**
Fuel type:		Power:	**100 kW**
Version:	**BMW X2 2.0 SDRIVE18D AUTO 100KW**	First registration	**02/03/2022**
Mileage:	**128920 km**	Number of doors:	

Summary of damages

- **Back** 1
- **Before** 1
- **RIGHT** 1
- **LEFT** 1
- **Interior** 1
- **Roof & other** 1


Commercial photos
































Options according to the inspector

GPS	**Yes**

Damages

Bodywork

Damaged - Acceptable.

Roof & other
















Damaged **Interior** - Acceptable

Interior






Polished front right alloy wheel
with scratches on
the left - Repair and paint (complete)






Polished front left alloy wheel
with scratches
on the left - Repair and paint (complete
)

Rear bumper,
claw(s)
, paint
the rear








Front bumper,
scratch(es),
paint
front







Tires

Front Left
Summer
Aluminum
225/50/18/99/W
Continental
6.0 mm
Front Right
Summer
Aluminum
225/50/18/99/W
Continental
6.0 mm
Left Back
Summer
Aluminum
225/50/18/99/W
Continental
7.0 mm
Rear Right
Summer
Aluminum
225/50/18/99/W
Continental
7.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**P/A**	Vehicle inspection	**OK**
Vehicle inspection	**02/03/2027**	Interview	**OK**
Interview	**in 4300 km**	Repair kit	**P/A**
Number of charging cables (220V)	**0**	Number of charging cables (fast charging)	**0**
Total number of keys	**2**	Factory reset	**Yes, the vehicle has been reset to factory settings.**
Type of maintenance log	**Digital interview**		

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.