MERCEDES-BENZ A-CLASS (W177)

Vehicle information

Brand:	**MERCEDES-BENZ**	License plate:	**2BBV843**
Gearbox:		Body color:	
Model:	**CLASS A (W177)**	LEVEL:	**W1K1770861J316645**
Fuel type:		Power:	**118 kW**
Version:	**A 250 e PHEV Business Solution**	First registration	**23/09/2021**
Mileage:	**106848 km**	Number of doors:	

Summary of damages


Before	2
RIGHT	1
LEFT	1
Interior	1
Roof & other	1

Commercial photos
































Options according to the inspector

GPS	**Yes**

Damages

Bodywork


Damaged -



Acceptable.

Roof & other








Damaged **Interior**

- Acceptable

Interior







Polished front right alloy wheel
with scratches on
the left - Repair and paint (complete)





AV Forced E **Brand Monogram**
- Replace
Before





Front bumper,
scratch(es),
paint
front







Left-hand door.
Dent(s) and scratch(es) .
Paint.





Tires

Front Left
Winter
Aluminum
205/55/17/95/H
Continental
7.0 mm

Front Right
Winter
Aluminum
205/55/17/95/H
Continental
7.0 mm

Left Back
Winter
Aluminum
205/55/17/95/H
Michelin
6.0 mm

Rear Right
Winter
Aluminum
205/55/17/95/H
Michelin
5.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Vehicle inspection	**OK**
Vehicle inspection	**23/09/2027**	Interview	**OK**
Interview	**A + 16168 km**	Repair kit	**Yes**
Number of charging cables (220V)	**1**	Number of charging cables (fast charging)	**1**
Total number of keys	**2**	Charge level	**30**
Factory reset	**Yes, the vehicle has been reset to factory settings.**	Type of maintenance log	**Digital interview**

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.