PEUGEOT 5008

Vehicle information


Brand:	**PEUGEOT**	License plate:	**2CQC890**
Gearbox:		Body color:	
Model:	**5008**	LEVEL:	**VF3MRHNSMNS110129**
Fuel type:		Power:	**96 kW**
Version:	**1.2 PURETECH 130 GT**	First registration	**14/10/2022**
Mileage:	**67355 km**	Number of doors:	


Summary of damages

Back	1
RIGHT	1
LEFT	1
Interior	1
Roof & other	1

Commercial photos





















Options according to the inspector

GPS	**Yes**

Damages

Bodywork

Damaged -

Acceptable.

Roof & other



















Damaged **Interior**

- Acceptable

Interior







Polished front right alloy wheel
with scratches on
the left - Repair and paint (complete)





Polished front left alloy wheel
with scratches
on the left - Repair and paint (complete
)




Rear **right inner wheel arch -**
Dent(s) and scratch(es)
- Repair and paint (complete)




Tires

Front Left
4 Seasons
Aluminum
225/55/18/102/V
Goodyear
5.0 mm
Front Right
4 Seasons
Aluminum
225/55/18/102/V
Goodyear
5.0 mm
Left Back
4 Seasons
Aluminum
225/55/18/102/V
Goodyear
7.0 mm
Rear Right
4 Seasons
Aluminum
225/55/18/102/V
Goodyear
7.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Interview	**OK**
Interview	**in 1200 km**	Repair kit	**Yes**
Number of charging cables (220V)	**0**	Number of charging cables (fast charging)	**0**
Total number of keys	**2**	Factory reset	**Yes, the vehicle has been reset to factory settings.**
Type of maintenance log	**Digital interview**		

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.