# Audi

VIN: WAUZZZF31N1091975

Estimated repair cost

374.26 EUR
TOTAL



## Description

| | | |
|---|---|---|
| **Registration number**<br>2ELE862 | **Registration date**<br>- | **Odometer**<br>49792 km |
| **Color**<br>- | **Year**<br>- | **Upholstery**<br>- |
| **Number of doors**<br>- | **Number of seats**<br>- | **Generation**<br>- |

## Statement details

**Inspection loc**
PARC LIZY


## Control

**Detected issues**

| | | | |
|---|---|---|---|
| Engine / Sound | ✓ Ok | Vehicle leak proofness | ✓ Ok |
| Exhaust / Clarity | ✓ Ok | | |

## Defects & corrections

| # | Element | Defect | Correction | net cost |
|---|---|---|---|---|
| 001 | Lower bumper / Back<br>Painted : No | Scratched | Acceptable | - |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | - |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

DEKRA

| | | | | |
|---|---|---|---|---|
| 002 | Tailgate / Boot door / -<br>Material : Metal / Windowed : Yes | Dent | Acceptable | - |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | - |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 003 | Rim / Front Left<br>Material : Aluminium alloy / Rim/Tyre diameter : 19 " / Surface : Painted | Scratched | Acceptable | - |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | - |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 004 | Interior roof lining / Front Left<br>Trim material : Fabric | Scratched | Smart repair | 68.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | **68.00 EUR** |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 005 | A-pillar trim / Front Left<br>Trim material : Fabric | Scratched | Replace | 79.76 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| **0.30 h** | - | **57.26 EUR** | - |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| **22.50 EUR** | - | - | |

| | | | | |
|---|---|---|---|---|
| 006 | Seat / Front Left<br>Trim material : Fabric | Burn mark | Smart repair | 68.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | **68.00 EUR** |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 007 | Carpet / Front Left | Burn mark | Smart repair | 68.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | **68.00 EUR** |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 008 | Carpet / Back Left | Burn mark | Smart repair | 68.00 EUR |

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | 68.00 EUR |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 009 | Interior roof lining / Back<br>Sunroof : No / Trim material : Fabric | Stained | Cleaning | 22.50 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| 0.30 h | - | - | - |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| 22.50 EUR | - | - | |

## Loose Items

- Quick charging cable (Type 2, Mode 3)
- Document holder
- Registration certificate owner
- Refill tyre repair kit
- Spare Key
- Tyre repair kit complete
- Triangle
- User manual
- Charging cable bag
- Slow charging cable (Type 2, Mode 2)
- Compressor tyre repair kit
- First aid kit
- Rear parcel shelf
- Registration certificate

## Main set of tyres

| | | | |
|---|---|---|---|
| **Front Left** | HANKOOK | 235/50/19 103 W<br>All-season | 5 mm |
| **Front Right** | HANKOOK | 235/50/19 103 W<br>All-season | 5 mm |
| **Back Left** | HANKOOK | 235/50/19 103 W<br>All-season | 5 mm |
| **Back Right** | HANKOOK | 235/50/19 103 W<br>All-season | 5 mm |

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

## Pictures


Front left



Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment



Front right




Odometer


Spare Tyre


Cable


Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Other




Lower bumper / Back / Scratched




Lower bumper / Back / Scratched




Lower bumper / Back / Scratched




Tailgate / Boot door / - / Dent



Tailgate / Boot door / - / Dent



Rim / Front Left / Scratched




Rim / Front Left / Scratched



Interior roof lining / Front Left / Scratched



A-pillar trim / Front Left / Scratched



A-pillar trim / Front Left / Scratched



A-pillar trim / Front Left / Scratched



Seat / Front Left / Burn mark



Seat / Front Left / Burn mark



Carpet / Front Left / Burn mark

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Carpet / Front Left / Burn mark



Carpet / Back Left / Burn mark



Carpet / Back Left / Burn mark



Interior roof lining / Back / Stained



Interior roof lining / Back / Stained

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.