PEUGEOT 3008

Vehicle information

Brand:	**PEUGEOT**	License plate:	**2CFV375**
Gearbox:		Body color:	
Model:	**3008**	LEVEL:	**VF3M4DGZUNS086527**
Fuel type:		Power:	**133 kW**
Version:	**1.6 PHEV 225 E-AUTO8 ALLURE PACK**	First registration	**07/07/2022**
Mileage:	**57669 km**	Number of doors:	

Summary of damages

Before 1

RIGHT 1

Interior 1


Roof & other 1

Commercial photos






























Options according to the inspector

GPS	**Yes**

Damages


Bodywork
Damaged -
Acceptable.
Roof & other











Damaged **Interior**
- Acceptable
Interior









Front right wing molding, Smart repair
claw(s) , right





Front bumper,
scratch(es),
paint
front







Tires

Front Left
4 Seasons
Aluminum
225/55/18/102/V
Michelin
3.0 mm
Front Right
4 Seasons
Aluminum
225/55/18/102/V
Michelin
3.0 mm
Left Back
4 Seasons
Aluminum
225/55/18/102/V
Michelin
4.0 mm
Rear Right
4 Seasons
Aluminum
225/55/18/102/V
Michelin
4.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Vehicle inspection	**OK**
Vehicle inspection	**07/07/2028**	Interview	**20/10/2027**
Interview	**OK**	Interview	**29700.0**
Repair kit	**Yes**	Number of charging cables (220V)	**1**
Number of charging cables (fast charging)	**1**	Total number of keys	**2**
Charge level	**0**	Factory reset	**Yes, the vehicle has been reset to factory settings.**
Type of maintenance log	**Digital interview**		

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.