TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48519576
Order No. / Reference: 27213577
Inspection date: 3 Nov 2026

Manufacturer: Mercedes-Benz	Model: 315 CDI Sprinter Standard HA 9G-TRONIC Kasten
VIN: W1V9076331P500416	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz 315 CDI Sprinter Standard HA 9G-TRONIC Kasten	
Vehicle Identification number	W1V9076331P500416
Mileage (Read)	208,204 km
First registration	24 Feb 2023
Number of holders	1
Next periodical technical inspection	02/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	ARKTIKWEISS
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	395 Tag(e)
Last service on / at	11/2025 at 159,681 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GU418412
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / BLJ 08226		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 121R	Winter tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	235/65 R16 121R	Winter tyres on Steel rim with wheel cover	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E				

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment above windshield
- Rear towing eye
- ADAPTIVE ESP (latest generation) with load- and speed-dependent driving dynamics control (Anti-lock Braking System (ABS) - Traction Control System (ASR) - Electronic Brakeforce Distribution (EBD) - Hydraulic Brake Assist (BAS) - Load Adaptive Control (LAC) - Roll Over Mitigation (ROM) - Roll Movement Intervention (RMI) - Enhanced Understeering Control (EUC) - Brake Disc Wiping/Drying (BDW) - Electronic Brake Prefill (EBP) - Easy Lane Change (ELC))
- Tachometer
- Driving light assistant
- Generator 14 V / 200 A
- Transmission: 9G-TRONIC
- Grab handle for entry to the cargo area sliding door on the partition wall
- Instrument panel and instrument cluster with various storage options (and optimized operating and display elements)
- Paint finish: Solid color paint
- Headlight range control
- Without weight increase/decrease: 3,500 kg
- Upholstery: Cloth
- Radio: Radio pre-installation (2 speakers)
- Radio: Pre-installation for digital radio DAB
- Radio accessories: Communication module (LTE) for digital services
- Tires: Tires without specified make
- Tires: Premium protection tires (3 years)
- Tires: Summer tires
- Sliding door on the right, cargo/passenger compartment
- Power steering
- Seats: Driver's seat armrest
- Seats: Driver's seat
- Speedometer km/h
- First aid kit
- Pre-installation for Remote Services Plus
- Warning triangle
- Heat-insulating glass
- Approval N1
- Storage compartment under cockpit
- Axle ratio i = 3.923
- Driver's side airbag
- Electrically adjustable and heated exterior mirrors, left and right
- Outdoor temperature display
- Battery: fleece battery 12 V / 92 Ah
- Hill start assist
- third brake light
- Brake lights, adaptive
- Diesel particulate filter and SCR
- Entry handle on rear right corner pillar
- Electric window regulator for driver and passenger door
- Noise measures
- Seatbelt warning device for driver's seat
- Main tank 71 liters
- HOLD function
- KEYLESS start
- Child safety locks on doors in the passenger compartment
- Headrests (2), front
- Steering wheel adjustable for tilt and height
- Mercedes-Benz emergency call system
- Breakdown Management (By pressing the breakdown button or via the phone book entry in the vehicle's address book, the disabled vehicle automatically establishes a voice connection with the Customer Assistance Center (CAC). It transmits the current location and all relevant vehicle information. The CAC staff immediately inform the nearest Mercedes-Benz Service24h, which dispatches a repair service.)
- Wheels: Steel rims 6.5 J x 16 (with tires 235/65 R16 C low rolling resistance tires)
- Seats: Passenger seat armrest
- Seats: Adjustable passenger seat
- Start-stop function
- continuous partition wall
- Lashing eyes (according to DIN 7510-3 in the floor and in the B-pillars)
- Immobiliser
- Central locking with radio remote control

Extra equipment

- Passenger side airbag
- Tachograph controls at the front under the headliner
- Ceiling light in the cargo/passenger compartment (with door contact)
- Seatbelt warning device for front passenger seat
- Interior lining of the cargo area up to roof height (wood)
- Clothes hooks in the driver's cab
- Load securing: tensioning straps
- Load securing: Lashing rails on the side wall to the side railing.
- Cable duct at rear portal
- Steering wheel: Multifunction steering wheel
- MBUX multimedia system with 7-inch touchscreen (High-resolution 7-inch touchscreen (960 x 540 pixels), AM/FM radio with dual tuner, Bluetooth connectivity with audio streaming and hands-free function, smartphone integration via Android Auto or Apple CarPlay, multimedia connection unit for connecting portable devices via a USB-C interface, 4 x 25 W output power, sound adjustment, separate volume control for audio and telephone, 2-way front speakers)
- Radio: Digital Radio DAB
- Tires: M+S tires
- Spare wheel carrier with jack (under frame end)
- Double-leaf rear door, opening to side wall
- Seats: Passenger seat, two-seater
- Seats: Suspension seat comfort version, driver's seat
- Cruise control
- Front axle with increased load capacity
- Heat-insulating glass with band filter on the windshield
- Entrance rear door
- Reference mass of at least 2611 kg is necessary
- Digital operating instructions
- Chassis stabilization stage 1
- Wooden floor (cargo area)
- Intelligent tachograph EU
- Thermotronic automatic climate control
- Load securing: Tension straps for lashing rails
- Load securing: Lashing rails on side wall to roof frame
- Load anchoring rail system
- Cable duct on side wall
- Marker lights, side
- Navigation (linguatronic voice control, Wi-Fi hotspot, multimedia connection unit for connecting portable devices via an additional USB-C interface, center fill speaker for improved sound and voice output, improved hands-free function, dual-phone operation, digital operating instructions)
- Navigation: 3 years of free map data updates
- Fog lights with cornering function
- Package: Acoustics in conjunction with MBUX
- Rain sensor
- Spare wheel
- Rear view camera
- vibration damper
- Seats: Driver's seat box, low
- Seat heating on driver's side
- Rear panel
- Heated windshield

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Bonnet	Insulation lining - Damage caused by marten / rodent - Replace
2	Side panel - rear right side	Wheel arch (Delle) - dent(s) - Repair and paint
3	Cab	Insulation lining - Damage caused by marten / rodent - Replace
4	Body	B-pillar - right side (inkl. Verkleidung) - dent(s) - Repair and paint
5	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Inspection / maintenance (Letzter Service nict eingetragen.) - Scratch(es) - No deduction
2	Body	Body - Dent / paintcoat damage - No deduction
3	Wheel / tyres	Tyres - complete set - Differs from the original configuration - No deduction
4	Documents	Service book (Wartungen unregelmäßig durchgeführt) - Incomplete - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Marder Spuren sind im Motorraum, weitere Schäden sind möglich.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Damage 1: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 1: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 2: Side panel - rear right side: Wheel arch (Delle) - dent(s) - Repair and paint




Damage 2: Side panel - rear right side: Wheel arch (Delle) - dent(s) - Repair and paint



Damage 3: Cab: Insulation lining - Damage caused by marten / rodent - Replace



Damage 3: Cab: Insulation lining - Damage caused by marten / rodent - Replace



Damage 4: Body: B-pillar - right side (inkl. Verkleidung) - dent(s) - Repair and paint



Damage 4: Body: B-pillar - right side (inkl. Verkleidung) - dent(s) - Repair and paint



Damage 4: Body: B-pillar - right side (inkl. Verkleidung) - dent(s) - Repair and paint



Damage 4: Body: B-pillar - right side (inkl. Verkleidung) - dent(s) - Repair and paint



Damage 5: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 5: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 5: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint