Audi

VIN: WAUZZZF36P1042449

Estimated repair cost

2,321.48 EUR
TOTAL



Description

Registration number -	**First registration date** -	**Odometer** 59862 km
Color -	**Model year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction	net cost
001	Rim / Front Right Rim/Tyre diameter : 19 " / Surface : Painted	Scratched	Smart repair	165.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**165.00 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

002	Rim / Front Left Rim/Tyre diameter : 19 " / Surface : Painted	Scratched	Smart repair	165.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	165.00 EUR
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

003	Rim / Back Right Rim/Tyre diameter : 19 " / Surface : Painted	Scratched	Smart repair	165.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	165.00 EUR
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

004	Bumper / Front Painted : Yes	Broken	Replace	554.44 EUR



Bodywork time	Paint time	Part Price	Lumpsum
2.10 h	0.50 h	354.44 EUR	-
Bodywork cost	**Paint cost**	**MaterialCost**	
157.50 EUR	42.50 EUR	-	

005	Bumper moulding / Front Right Painted : Yes / Chromed : No	Scratched	Painting	25.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	0.30 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	25.50 EUR	-	

006	Bumper grille / Front Right Painted : No / Chromed : No	Broken	Replace	57.77 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	57.77 EUR	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

007	Bumper moulding / Front Right Painted : Yes / Chromed : No	Scratched	Painting	25.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	0.30 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	25.50 EUR	-	

008	Bumper moulding / Front Left Painted : Yes / Chromed : No	Scratched	Painting	25.50 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
-	0.30 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	25.50 EUR	-	

009	Bumper grille / Front Left Painted : No / Chromed : No	Scratched	Replace	57.77 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	57.77 EUR	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

010	Front face / -	Chip	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

011	Door / Front Left	Chip	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

012	Door / Back Left	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

013	Roof / - Sunroof : Yes	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

014	Bumper moulding / Back Painted : Yes / Chromed : No	Improper Repair	Painting	161.00 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
0.90 h	1.10 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
67.50 EUR	93.50 EUR	-	

015	Bumper / Back Painted : Yes	Scratched	Polishing	37.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.50 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
37.50 EUR	-	-	

016	Door / Back Right	Improper Repair	Repair	211.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
1.00 h	1.60 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
75.00 EUR	136.00 EUR	-	

017	Door moulding / Back Right Painted : Yes	Scratched	Painting	49.00 EUR




Bodywork time	Paint time	Part Price	Lumpsum
0.20 h	0.40 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
15.00 EUR	34.00 EUR	-	

018	Door moulding / Back Right Painted : Yes	Scratched	Painting	49.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.20 h	0.40 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
15.00 EUR	34.00 EUR	-	

019	Door / Front Right [1]	Improper Repair	Repair	257.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
1.50 h	1.70 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
112.50 EUR	144.50 EUR	-	

020	Door moulding / Front Right Painted : Yes	Scratched	Painting	49.00 EUR

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bodywork time	Paint time	Part Price	Lumpsum
0.20 h	0.40 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
15.00 EUR	34.00 EUR	-	

021	Door moulding / Front Right Painted : Yes	Scuff	Painting	49.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.20 h	0.40 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
15.00 EUR	34.00 EUR	-	

022	Wing / Front Right	Dent	Repair	177.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
1.00 h	1.20 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
75.00 EUR	102.00 EUR	-	

023	Exterior door mirror shell / Right	Scratched	Painting	40.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.20 h	0.30 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
15.00 EUR	25.50 EUR	-	

[1] + oneffenheden

Loose Items

- ☑ Quick charging cable (Type 2, Mode 3)
- ☑ Charging cable bag
- ☑ Tyre repair kit complete
- ☑ Spare Key
- ☑ Rear parcel shelf

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	MICHELIN	235/50/19 103 H All-season	3 mm
Front Right	MICHELIN	235/50/19 103 H All-season	3 mm
Back Left	MICHELIN	235/50/19 103 H All-season	4 mm
Back Right	MICHELIN	235/50/19 103 H All-season	4 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right



Odometer


Spare Tyre



Vin


Other


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Back Right / Scratched



Rim / Back Right / Scratched



Bumper / Front / Broken



Bumper / Front / Broken



Bumper / Front / Broken



Bumper moulding / Front Right / Scratched



Bumper moulding / Front Right / Scratched



Bumper grille / Front Right / Broken



Bumper grille / Front Right / Broken




Bumper moulding / Front Right / Scratched



Bumper moulding / Front Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper moulding / Front Left / Scratched



Bumper moulding / Front Left / Scratched



Bumper moulding / Front Left / Scratched



Bumper grille / Front Left / Scratched



Bumper grille / Front Left / Scratched



Front face / - / Chip



Door / Front Left / Chip



Door / Front Left / Chip



Door / Back Left / Dent



Door / Back Left / Dent



Door / Back Left / Dent



Roof / - / Dent



Roof / - / Dent



Bumper moulding / Back / Improper Repair




Bumper moulding / Back / Improper Repair

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper moulding / Back / Improper Repair



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Door / Back Right / Improper Repair



Door / Back Right / Improper Repair



Door / Back Right / Improper Repair



Door / Back Right / Improper Repair



Door moulding / Back Right / Scratched



Door moulding / Back Right / Scratched



Door moulding / Back Right / Scratched



Door moulding / Back Right / Scratched



Door moulding / Back Right / Scratched



Door / Front Right / Improper Repair

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Door / Front Right / Improper Repair



Door / Front Right / Improper Repair



Door / Front Right / Improper Repair



Door moulding / Front Right / Scratched



Door moulding / Front Right / Scratched



Door moulding / Front Right / Scuff



Door moulding / Front Right / Scuff



Wing / Front Right / Dent



Wing / Front Right / Dent



Wing / Front Right / Dent



Exterior door mirror shell / Right / Scratched



Exterior door mirror shell / Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.