TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48136520
Order No. / Reference: 27042117
Inspection date: 13 Oct 2026

Manufacturer: Opel	Model: Vivaro 1.5 D Cargo M Edition
VIN: VXEVBYHVMN7031996	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Vivaro 1.5 D Cargo M Edition	
Vehicle Identification number	VXEVBYHVMN7031996
Mileage (Read)	154,173 km
First registration	6 Sept 2022
Number of holders	1
Next periodical technical inspection	09/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Eis Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Grey-Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	27,760 km
Last service on / at	03/2026 at 141,942 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ689591
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	Conditional: Light/moisture/dirt	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	3003 / BAL 00404		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,695 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 104H	Winter tyres on Steel	Continental	5mm / 5mm
2)	215/60 R17 104H	Winter tyres on Steel	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E				

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Driver and passenger side airbags
- Exterior mirrors, electrically adjustable, heated and manually folding
- Battery discharge protection
- Floor covering: Cargo area floor, painted
- third brake light
- Tachometer
- Electronic Stability Program (ESP Plus)
- Speed controller and limiter
- Grab handle in the first row of seats, passenger side
- Steering wheel: Comfort steering wheel (PU), flattened at the bottom
- Parkpilot, rear parking aid
- Side protection strips
- Visibility equipment
- Sun visors, driver and passenger
- 12V power outlet in the cargo area and in the lower glove compartment
- Partition wall: closed, without windows
- Doors: Rear wing doors, sheet metal with a 180° opening angle
- Electronic immobilizer
- Central locking with remote control
- ABS including brake assist and adaptive brake light
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirror housings in black
- Hill Start Assist
- On-board computer
- Diesel particulate filter, maintenance-free
- Three-point seat belts in all seats
- Electric front windows
- Transmission: 6-speed transmission
- Glove compartment closed at the top
- Steering column, adjustable for reach and height
- Fatigue detection level 1 coffee break
- Side impact protection
- Speed-sensitive power steering
- Seats: Comfort driver and comfort passenger seats
- 12-volt power outlet in the center console
- Daytime running light
- Traction control with engine and brake intervention (TC Plus)
- Doors: Sliding door, passenger side
- Lashing eyes (6) in the cargo area
- Heat-insulating glazing, tinted
- Ignition key (2), foldable

Extra equipment

- GPS
- Park pilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards - blind spot warning - electrically folding exterior mirrors - fog lights)
- Radio: Multimedia radio with 7" color touchscreen display (Automatic music recognition for audio devices with USB connection, Bluetooth audio streaming, DAB+ digital radio reception, hands-free calling via Bluetooth interface, phonebook and call list display, up to 10 mobile phones can be paired, display of pictures/films/videos via USB interface, smartphone integration, voice control, 1 USB interface, dual tuner, graphic equalizer, 4 speakers (8 in double cab Edition or Elegance))
- Keyless locking and starting system "Keyless Open & Start"
- Würth: Heating/Sanitary according to invoice 6035266464 dated 28.0
- Würth: Overnight
- Würth: RG 6035284098 dated October 6, 2022
- Automatic climate control: Dual-zone automatic climate control, front (with particle and odor filter - recirculation mode, manual - automatic air distribution - sun position sensor - activated carbon filter)
- Tires: Winter tires, usable all year round (tire size 215/60 R 17 C 104 H 3PMSF)
- Wheels: Spare wheel, steel
- Wheels: Steel wheels 7 J x 17 with wheel cover, full surface (tires 215/60 R 17 C 104H)
- 180° panoramic reversing camera (displays the area behind the vehicle up to 180 degrees, including steering guidelines, when reverse gear is engaged, on the color display of the infotainment system.)
- Safety package including whisk
- Seats: Comfort driver's seat and double passenger seat (comfort driver's seat adjustable in 6 ways, with armrest and lumbar support - double passenger seat with storage under the seat - height-adjustable headrests, front)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Missing - Replace
2	Sliding door, right	Sliding door - Scratch(es) - Smart repair
3	Boot lid / rear door	Rear door - right side - dent(s) - Smart repair
4	Door - rear right side	Door (innen) - Dent / paintcoat damage - Loss in value
5	Body	Body - Glued / labelled - Remove

Wear and tear

No.	Component group	Description
1	Steering system	Steering wheel - Worn - No deduction
2	Interior	Interior - Soiled - No deduction
3	Door - rear left side	Door - Dent / paintcoat damage - No deduction
4	Side panel - rear left side	Side panel - Scratch(es) - No deduction
5	Side panel - rear right side	Sill - Dent / paintcoat damage - No deduction
6	Roof	Roof - dent(s) - No deduction
7	Door - front right side	Door - Scratch(es) - No deduction
8	Wheel / tyres	Wheel cover - front left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Provided by user / customer, from 14 May 2024	10.439,90 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents




Figure 19: Documents




Figure 20: Documents



Figure 21: Documents



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Wheel / tyres: Wheel cover - front right side - Missing - Replace



Damage 2: Sliding door, right: Sliding door - Scratch(es) - Smart repair



Damage 2: Sliding door, right: Sliding door - Scratch(es) - Smart repair



Damage 3: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 3: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair




Damage 4: Door - rear right side: Door (innen) - Dent / paintcoat damage - Loss in value



Damage 4: Door - rear right side: Door (innen) - Dent / paintcoat damage - Loss in value



Damage 5: Body: Body - Glued / labelled - Remove



Damage 5: Body: Body - Glued / labelled - Remove

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Damage 5: Body: Body - Glued / labelled - Remove