ARVAL
BNP PARIBAS GROUP


2EQZ260

INSPECTION REPORT

End of contract


GENERAL INFO

File	321178
License plate	2EQZ260
Vehicle identification number	VSSZZZKL1RR047599
Dossier	2023347038
Make	Cupra Leon ST 1.4eHyb.150kW DS
Mileage	112194
First registration	02/01/2024
client availability date	02/09/2026
inspectionDate	04/09/2026







CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	


14:59
21.5°C
Wagen rijklaar.
Voor het verlaten
van de wagen
contact uitschakelen.
220 km
33 km
READY
R
N
D
P
11210 km


B
2-EQZ-260
BELCAR

DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
40	Windshield // Repair	Y
111	Wing Rear Left // Smart Repair Medium	N
117	Wing Rear Left / Trim / Replace	Y
133	Bumper Rear // Painting	N
150	Rear Bonnet // Smart Repair Small	N
181	Wing Rear Right // Smart Repair Medium	N
201	Rocker Panel Right // Smart Repair Medium	N
340	Wheel Two Tone Front Right // Repair	N
432	Seat Rear Left / Bottom Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
648	Rear Right Door Interior Coating / Door Handle / Replace	N
774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures




Interior / Side Cover rear Seat / Replace-scratch




Wheel Two Tone Front Right // Repair-scratch



Bumper Rear // Painting-scratch



Bumper Front // Smart Repair Large-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Wing Rear Left // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Medium-dent





Rear Bonnet // Smart Repair Small-dent






Rocker Panel Right // Smart Repair Medium-scratch + dent






Interior Cleaning // Small-dirty





Rear Right Door Interior Coating / Door Handle / Replace-tear

Seat Rear Left / Bottom Coating / Replace-worn




Windshield // Repair-stone chipping




Wing Rear Left / Trim / Replace-Chipped paint