Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Lagermax - AT - Straßwalchen
Lagermax Str. 1
5204 Straßwalchen

Inspection date: 11 Sept 2026
Protocol number: **47534878**

WBAYN910305X73147

Vehicle details

Operator		**Inspection condition**	sufficient
License number		**Mileage (Read)**	48,877 km
Manufacturer	BMW	**Next maintenance in**	6,000 km
Type / Model	X2 xDrive25e PHEV	**Main inspection**	11/2026
Vehicle Identification number	WBAYN910305X73147	**Power**	162 kW
Engine displacement	1,499 ccm	**Cylinder**	—
First registration	16 Nov 2023	**Upholstery/Colour**	Cloth / Black
Last maintenance	09/2025, 21,699 km	**Paintwork**	Blue
Fuel type	Hybrid Petrol / E	**Gearbox**	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Seat - front	Seat base trim - left side - Scratched - Smart repair
2	Door - rear right side	Door (2 M) - dent(s) - Smooth repair work
3	Braking system	Brake fluid - Due - Replace
4	Rear bumper	Bumper with Parktronic (Ladekante) - Scratched - Smart repair

Wear and tear

No.	Component group	Description
1	Wing mirror - right side	Mirror housing - Abrasion - No deduction
2	Roof	Roof (Hartzflecken Folgekosten möglich) - Soiled - No deduction
3	Door - rear left side	Door - dent(s) - No deduction
4	Door - front left side	Door - dent(s) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17	Pirelli	Summer tyres	5mm - 5mm	o.k.	
2	225/55 R17	Pirelli	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Standard equipment

Code	Description
-	12V power outlet
-	2-year warranty
-	Advantage
-	Advertisement-
-	Aerodynamic Features
-	Air Curtain
-	Airbag for driver and front passenger
-	Anti-lock braking system (ABS)
-	Armrest - front
-	Attention assistant eDRIVE button
-	Automatic start-stop function
-	BMW xDrive
-	Braking system
-	Central locking system
-	Cloth bag for boarding documents
-	DAB tuner
-	Driving experience switch including ECO PRO mode
-	Dynamic Stability Control (DSC)
-	Electric motor
-	electric window regulator
-	Exterior mirror housings in body color with integrated additional indicator light using LED/light guide technology
-	fin
-	Floor mats in anthracite
-	Front door sill trims in matte black with "BMW" lettering
-	Fund seats
-	Green heat/sun protection glazing all around
-	Head airbags for the 1st and 2nd rows of seats
-	Headlight washer system
-	Heated and electrically adjustable exterior mirrors
-	High-voltage battery including battery certificate
-	Interior lighting
-	Interior trim strips, oxide silver, dark matte
-	ISOFIX child seat attachments for the outer rear seats
-	LED headlights with extended features
-	LED taillights for rear light and brake light
-	Loading edge with stainless steel inlays
-	Loading flap
-	Manual passenger seat height adjustment
-	Media
-	Multi-collision brake

Code	Description
-	Oil level and quality sensor
-	On-board computer
-	Operating concept
-	Otto particulate filter (OPF)
-	Passenger airbag deactivation
-	Performance Control
-	Rain sensor
-	Reflex silver
-	Servotronic
-	Shift point indicator, 5 seats
-	Sport leather steering wheel
-	Standard charging cable
-	Standard charging cable (Mode 2) for household sockets
-	Standard seat for driver and passenger
-	Standard steering wheel in 3-spoke design
-	Standard suspension
-	Stationary air conditioning
-	Steering column adjustment
-	Stereo speaker system
-	Storage options
-	Tire pressure monitoring
-	Tire repair kit for 17" alloy wheels, double spoke design 564
-	USB port
-	Vehicle dynamics control systems
-	visible exhaust tailpipe, simply round
-	Warning triangle with first aid kit

Extra equipment

Code	Description
04U9	Acoustic pedestrian protection
05AV	Active Guard
08TF	Active pedestrian protection
01DZ	Additional scope earth
A060	AGM battery 60 Ah
0302	Alarm system
0534	Automatic air conditioning
0316	Automatic tailgate operation
0205	automatic transmission
04NE	Blow-by heater
023E	BMW LM wheel V-spoke 560
04T1	CHARGING CABLE (MODE 2)
01CB	CO2 scope
06AK	Connected Drive Services
07S9	ConnectedDrive Services Package
0544	Cruise control with braking function
0654	DAB tuner (DAB+ capable)
06AG	eDrive services
0230	EU-specific additional scopes
01DF	EU6 rde II emissions standard
0313	Exterior mirror folding function
POLS	Fabric upholstery
0473	Front armrest
0851	German language version
0610	Head-Up Display
0502	Headlights washer / wiper system
0494	Heated seats for driver and passenger
06AC	Intelligent emergency call
0431	Interior mirror automatically dimming
0430	Interior/exterior mirrors with automatic dimming
05A4	LED headlights with extended features
0488	Lumbar support for driver and front passenger
0710	M leather steering wheel
07LC	Model Advantage
0249	Multifunction for steering wheel
06UP	Navigation Plus
0548	odometer
08KA	Oil change interval: 24 months/30,000 km
0879	Onboard literature in German
04FS	oxide silver matt, accent black high gloss.
0508	Park Distance Control (PDC)
05DP	Parking assistant

Code	Description
05DA	Passenger airbag deactivation
0450	Passenger seat height adjustment
06NW	Phone calls with wireless charging
06AM	Real-time traffic information
03AG	Rear view camera
08R9	Refrigerant R1234yf
0481	Sports seat
0493	Storage package
06AE	Teleservices
02VB	Tire pressure gauge
02VC	Tyre repair kit
0423	Velour floor mats
0428	Warning triangle and first aid kit
02PA	Wheel bolt lock

Comments

Dieses Gutachten wurden in Verantwortung von Ing. Martin Lennes, allgemein beeideter und gerichtlich zertifizierter Sachverständiger, erstellt.

Die o.a. Serienausstattung des Fahrzeuges basiert auf Angaben der Firma Eurotax und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Die o.a. Sonderausstattung des Fahrzeuges stammt aus dem BMW System Myair und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Lagermax - AT - Straßwalchen
Lagermax Str. 1
5204 Straßwalchen

Inspection date: 11 Sept 2026
Protocol number: **47534878**

Vehicle details

Manufacturer	BMW	**Inspection condition**	sufficient
Type / Model	X2 xDrive25e PHEV	**Mileage (Read)**	48,877 km
Vehicle Identification number	WBAYN910305X73147	**First registration**	16 Nov 2023

Details of the order:
In accordance with the contract, the evaluation of vehicle's condition was performed without the vehicle being disassembled.

This product is based on the Austrian standard ÖNORM V5080. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on their own expertise.

Vehicle identification:
The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.

Inspection conditions:
The inspection conditions were sufficient for the assessment of the vehicle.

General condition:
The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior




Figure 6: Interior



Figure 7: Interior




Figure 8: Interior



Figure 9: Interior



Figure 10: Interior




Figure 11: Interior




Figure 12: Interior




Figure 13: Interior




Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.

Pictures of damage



Damage Seat - front: Seat - front: Seat base trim - left side - Scratched - Smart repair



Damage Seat - front: Seat - front: Seat base trim - left side - Scratched - Smart repair



Damage Door - rear right side: Door - rear right side: Door (2 M) - dent(s) - Smooth repair work




Damage Door - rear right side: Door - rear right side: Door (2 M) - dent(s) - Smooth repair work



Damage Door - rear right side: Door - rear right side: Door (2 M) - dent(s) - Smooth repair work



Damage Door - rear right side: Door - rear right side: Door (2 M) - dent(s) - Smooth repair work



Damage Braking system: Braking system: Brake fluid - Due - Replace



Damage Rear bumper: Rear bumper: Bumper with Parktronic (Ladekante) - Scratched - Smart repair



Damage Rear bumper: Rear bumper: Bumper with Parktronic (Ladekante) - Scratched - Smart repair