MACADAM

Polestar Polestar 2 '19 BEV

Vehicle information

Make:	**Polestar**	License:	**N220HS**
Gearbox:	**Automatic**	Body color:	
Model:	**Polestar 2 '19 BEV**	VIN:	**LPSVSECEKNL052095**
Fuel type:	**Electric**	Power:	**165 kW**
Version:	**Polestar 2 63kWh Sing.M.St.Ra.**	First registration	**11/11/2021**
Mileage:	**150958 km**	N° of doors:	

Damage summary

Front	2
Left	2

Commercial pictures







































Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Hook	**Yes**	Radio multimedia	**Yes**	Rear view camera	**Yes**
Telephone equipment	**Yes**				

Damages

Bumper F
Bad repair
Repair and paint (complete)
Front




Bumper trim F
Scratch(es)
Replace
Front




Door FL
Bad repair
Repair and paint (complete)
Left




Door RL
Scratch(es)
Repair and paint (complete)
Left





Tyres

Front Left
Summer
245/45/19/102/Y
Michelin
3.5 mm
Front Right
Summer
245/45/19/102/Y
Michelin
3.2 mm
Rear Left
Summer
245/45/19/102/Y
Michelin
6.4 mm
Rear Right
Summer
245/45/19/102/Y
Michelin
3.9 mm

Checks

CO2 Emission	**0**	Digital maintenance	**Yes**
GPS storage	**Yes**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**Yes**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.