TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48087986
Order No. / Reference: 27150367
Inspection date: 13 Oct 2026

Manufacturer: Seat	Model: Ateca 2.0 TDI Xperience
VIN: VSSZZZ5F1P6564664	





Vehicle details

Manufacturer / Type / Model / Equipment	
Seat Ateca 2.0 TDI Xperience	
Vehicle Identification number	VSSZZZ5F1P6564664
Mileage (Read)	103,520 km
First registration	1 Aug 2023
Number of holders	1
Next periodical technical inspection	09/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Magic Schwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	9,400 km
Last service on / at	04/2026 at 90,491 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ529167
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	7593 / AMQ 00472		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,990 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R18 92V	Summer tyres on Light alloy	Goodyear	5mm / 5mm
2)	215/50 R18 92V	Summer tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18 99M	Summer tyres on Steel	Sonstige	4 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12V socket at the front
- Storage compartment in the middle area of the lower dashboard
- Storage pocket on the back of the front seats
- Electrically adjustable, folding and heated exterior mirrors
- Hill Start Assist (HHC)
- Chrome applications in the interior
- Electronic differential lock (XDS)
- Three-point automatic seat belts, front and rear, with belt tensioners
- Electronic parking brake including auto-hold function
- Electric windows front and rear
- luggage compartment cover
- Transmission: 6-speed transmission
- Rear window wiper and rear window heater
- Climatronic air conditioning system with electronic temperature control (separate temperature control for driver and front passenger)
- Center console with integrated storage compartment, center armrest, cup holders and rear air vents
- Package: Design Exterior Package "Silver" (chrome trim on the side windows - roof rails in silver - body covers on the wheel arches)
- Package: Light and Sight (Automatic Coming Home and Leaving Home function - Automatically dimming interior mirror - Light sensor with automatic headlight control - Rain sensor)
- Radio: Media System Plus Style, Xperience, FR (Audio system with 8.25" color touchscreen - USB and Aux-in interface - 2 USB charging ports for the 2nd row of seats - Bluetooth interface with integrated hands-free system and audio streaming - 8 speakers - Multifunction display with multi-color screen in the instrument panel - Emergency call service)
- SEAT Drive Profile with "Driving Experience" button and progressive steering
- Electromechanical power steering
- Seats: Lumbar support for driver and front passenger with height adjustment for front passenger seat
- Front door sill trims in aluminum look, illuminated
- Lashing eyes in the luggage compartment
- Full LED headlights
- thermal insulation glazing
- Storage compartment for sunglasses on the driver's side
- Storage compartment in the front doors
- Storage compartment under the driver's seat
- Airbags
- Exterior mirror housings in body color
- On-board computer
- Diesel particulate filter and SCR catalyst
- Tachometer
- Third brake light, integrated into the tailgate
- Rear parking sensors
- Electronic Stability Control (ESC)
- Gear recommendation display
- Cruise control system (CCS)
- LED taillights
- ISOFIX child seat restraint system
- Headrests, 2 front, 3 rear
- Steering wheel: Multifunction steering wheel in leather
- Armrest - centre, rear
- Fatigue detection
- Fog lights with cornering light function in LED technology
- Package: LED interior lighting (consisting of LED technology for: - Ambient lighting (multicolor) in the door trim - Ambient light front - Glove compartment - Reading lights, 2 front / 2 rear - Footwell lighting - Luggage compartment lighting)
- Upholstery: Cloth
- Radio: Digital radio reception DAB+
- Tire Pressure Monitoring System (TPMS)
- Wheels: 4 light alloy wheels "Performance I" (7J x 18 with tires 215/50 R 18)
- Rear view camera
- Rear seat backrest asymmetrically split and foldable
- Keyless locking and starting system "Kessy"
- SEAT CONNECT
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Seats: Driver's seat with height adjustment
- Start-stop technology
- LED daytime running lights
- Front Assist area monitoring system with City Emergency Braking function
- Electronic immobilizer
- Central locking, including tailgate, with remote control

Extra equipment

- Storage box under the front seats
- Luggage partition net
- Package: Business Package NAVIGATION (Navigation system with 9.2" color touchscreen, voice control - Full Link: Android Auto, Apple CarPlay - Wireless charger in the storage compartment of the center console - Spare wheel as emergency wheel)
- Seats: Remote release for folding down the rear seat backrest into the boot
- Deletion of the lettering on the tailgate
- Paint finish: Metallic
- Package: Winter (multifunction leather steering wheel, heated - heated front seats)
- Panoramic glass sliding roof, electric, including sunshade blind.
- Park Assist with front and rear parking aid
- Virtual Cockpit (Fully digital instrument cluster with 10.25" TFT display)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Front bumper	Spoiler - Scratch(es) - Smart repair
2	Rear bumper	Rear bumper - Scratch(es) - Paint
3	Vehicle glazing	Windscreen (Steinschlag im Sichtfeld) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Interior	Interior - Scratch(es) - No deduction
2	Door - rear left side	Door - Scratch(es) - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Front bumper	Front bumper - Stone chips - No deduction
5	Sill - left side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area





Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Deutsche Bank AG
Taunusanlage 12
60325 Frankfurt

Hauptuntersuchung nach §29 StVZO

(3) Ort und Datum der Prüfung: H

(D)F-FJ1238	(1)	Fz.-Ident.-Nr.: VSSZZZ5F1P6564664
Z.-Art: PKW	(5)	Fz.-Klasse: M1 / AC
Hersteller: SEAT (E)		HSN: 7593
Variant: 5FP		TSN / VSN: AMQ / 00472
Masse: 2000 kg	(4)	Kilometerstand: 102024 km
Prüfung: 01.08.2023		letzte HU: 00.00

Kunde,
Auftrag nach oben genannter Untersuchungsart geprüft und abschließend folgendes Ergebnis festgestellt:

Prüfplakette	(8) Nächste HU:	Wiedervorfüh
zugeteilt	09.28	----

rechts (daN)	Brems-Druck/Kennw. (bar/-)	Berechn. Druck (bar)	Summe der Bremskräfte ∑FB Ist (daN)	Erforderliche Bremskräfte ∑FB Min (daN)	Bremskraft-anteil Ist (%)	Bremskr anteil M (%)
311	40,63	-	612	477	71.5	55.3
225	80,43	-	483	251	28.5	14.7
174	-	-	271	-	-	-

rechts nahe Verschleißgrenze (HW)
rechts nahe Verschleißgrenze (HW)
rechts nahe Verschleißgrenze (HW)

Figure 14: Documents



Figure 15: Documents




Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.




Damage 1: Front bumper: Spoiler - Scratch(es) - Smart repair




Damage 1: Front bumper: Spoiler - Scratch(es) - Smart repair




Damage 1: Front bumper: Spoiler - Scratch(es) - Smart repair




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 3: Vehicle glazing: Windscreen (Steinschlag im Sichtfeld) - Stone chips - Replace



Damage 3: Vehicle glazing: Windscreen (Steinschlag im Sichtfeld) - Stone chips - Replace



Damage 3: Vehicle glazing: Windscreen (Steinschlag im Sichtfeld) - Stone chips - Replace