TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48356596
Order No. / Reference: 27114406
Inspection date: 28 Oct 2026

Manufacturer: Opel	Model: Vivaro 1.5 D Cargo M
VIN: VXEVBYHVMP7819282	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Vivaro 1.5 D Cargo M	
Vehicle Identification number	VXEVBYHVMP7819282
Mileage (Read)	161,117 km
First registration	11 Jul 2023
Number of holders	1
Next periodical technical inspection	08/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Kaolin Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	24,400 km
Last service on / at	05/2026 at 145,529 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS846541
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	3003 / BAL 00471		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,695 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 107T	All-season tyres on Steel rim with wheel cover	Sonstige	8mm / 8mm
2)	215/65 R16 107T	All-season tyres on Steel rim with wheel cover	Nexen	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Driver and front passenger airbag (front airbag, passenger, deactivatable; automatic activation of hazard warning lights and unlocking of doors after deployment of airbag and seatbelt tensioner)
- Tachometer
- Electronic Stability Program (ESP Plus)
- Transmission: 6-speed transmission
- Paint finish: Solid color paint
- Radio: Basic Radio
- Tire pressure monitoring system
- Power steering
- Seats: Driver's seat height-adjustable, with armrest and lumbar support (double passenger seat with storage compartments under the bench seat)
- Doors: Sliding door on the right, manual
- Central locking with remote control
- Anti-lock braking system (ABS)
- On-board computer
- third brake light
- Diesel particulate filter, maintenance-free
- Rear parking aid (acoustic)
- Speed controller and speed limiter
- Air conditioning
- Upholstery: Cloth
- Tires: Tire repair kit
- Wheels: Steel wheels 7 J x 16 with wheel hub cover (with summer tires 215/65 R 16 C 106T)
- Start/Stop System
- Partition wall, sheet metal cladding
- Doors: Rear wing doors 50/50, opening 180°, sheet metal
- Immobiliser

Extra equipment

- Package: 180-degree panoramic reversing camera (reversing camera - RCC audio system - analog instrument with LCD text display)
- Package: Comfort and other equipment Multifunction leather steering wheel, electric handbrake (leather steering wheel -visibility package - rain and light sensor -interior design package: dashboard, door panels black, air vents chromed -automatic climate control, 2 zones -keyless system -steering wheel remote control -analog instrument with LCD text display -closed storage compartments: dashboard center, passenger side lower -windshield with increased protection against heat and sound)
- Package: Driver Assistance Package 1 (Lane Keeping Assist - Front Collision Warning and Emergency Brake Assist - Blind Spot Assist - Front and Rear Parking Aid with Acoustic Warning - Multimedia Radio - Steering Wheel Remote Control - Visibility Equipment - Analog Instrument Cluster with 3.5" Color Display - Windscreen with Increased Protection Against Heat and Sound)
- Security package

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Roof	Stub aerial - Damage caused by marten / rodent - Replace
2	Sill - right side	Sill - Paint defect - Smart repair
3	Sill - left side	Sill (Lackläufer) - Unprofessionally repaired - Conditioning
4	Side panel - rear left side	Side panel (teilweise) - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Service book

Accident damages

No.	Accident
1	Side right

Repainting

No.	Repainting
1	Door - front left side, Professionally carried out, Invoice of repair done Non-existent
2	Sill - left side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Sill - left side	221 µm	Door - front left side	212 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.

Seitenwand rechts im Unfall nur Teilweise berechnet.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Damage 1: Roof: Stub aerial - Damage caused by marten / rodent - Replace



Damage 1: Roof: Stub aerial - Damage caused by marten / rodent - Replace



Damage 2: Sill - right side: Sill - Paint defect - Smart repair



Damage 2: Sill - right side: Sill - Paint defect - Smart repair



Damage 3: Sill - left side: Sill (Lackläufer) - Unprofessionally repaired - Conditioning



Damage 3: Sill - left side: Sill (Lackläufer) - Unprofessionally repaired - Conditioning



Damage 3: Sill - left side: Sill (Lackläufer) - Unprofessionally repaired - Conditioning



Damage 4: Side panel - rear left side: Side panel (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 4: Side panel - rear left side: Side panel (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 4: Side panel - rear left side: Side panel (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 4: Side panel - rear left side: Side panel (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 4: Side panel - rear left side: Side panel (teilweise) - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Wing mirror - right side: Cap - Scratch(es) - No deduction



Wear and tear 1: Wing mirror - right side: Cap - Scratch(es) - No deduction



Accident 1: Side right



Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Repainting 1: Door - front left side



Repainting 1: Door - front left side



Repainting 2: Sill - left side



Repainting 2: Sill - left side