DEKRA Automotive Solutions

Condition Report

Vehicle details

VIN	JMZKBAC3X 0A364349	Mileage	65 238 km	Engine (Fuel) Type	Hybrid petrol
Licence Plate	2FUZ315	Registration date	02/09/2024	Engine size	1490
Brand	MAZDA	Fuel level	-	Transmission	Automatic
Model	2-Hybrid-Berlina-KBAC3-2021	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Rouge		

Inspection Details

Inspection date	13/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique















Other technical information

Refill emergency kit	✔
Rear parcel shelf	✔
Emergency compressor kit	✖

Tyres

Bridgestone 195/55/16 H Summer 3.0 mm

Bridgestone 195/55/16 H Summer 3.0 mm





Bridgestone 195/55/16 H Summer 4.0 mm

Bridgestone 195/55/16 H Summer 4.0 mm

Damages

1



Part	Emergency compressor kit
Position	-
Damages	Missing
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	74.58€

2

Part	Service
Position	-
Damages	Missing
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	100.00€

geen onderhoud bewijs aanwezig

3



Part	Fabric seat
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
Net cost (Excluding VAT)	17.77€

4



Part	Carpet
Position	Front left
Damages	Perforated
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	90.00€

5



Part	Door sill
Position	Front left
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	49.00€

6



Part	Door sill
Position	Back left
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	60.00€

7



Part	Engine soundproofing
Position	-
Damages	Perforated
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	353.65€

8



Part	Spoiler
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	191.19€

9



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	467.00€

10



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	60.00€

11



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

12



Part	Wing
Position	Back right
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	120.00€
	x2

Summary Inspection

Net Price (Exclusing VAT)	1,583.19€