TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48583772
Order No. / Reference: 27242465
Inspection date: 9 Nov 2026

Manufacturer: Opel	Model: Mokka-e Elegance
VIN: VXKUKZKXZPW047777	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Mokka-e Elegance	
Vehicle Identification number	VXKUKZKXZPW047777
Mileage (Read)	34,633 km
First registration	29 Aug 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	08/2027
Fuel type	Electric
Power	57 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Kontrast Grau (Metallic)
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Light grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	10,800 km
Last service on / at	07/2025 at 20,254 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS842676
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ADD 00041		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,015 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 96H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/60 R17 96H	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 96H	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	215/60 R17 96H	Summer tyres on Light alloy	Continental	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys, with remote control
- Storage compartments
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Active Pedestrian Warning System (AVAS)
- Exterior mirrors in black
- Exterior mirrors, electrically adjustable and heated, manually foldable
- Hill Start Assist
- Roof design line in chrome
- Roof spoiler, black
- Third brake light
- Electronic Stability Program Plus (ESP Plus)
- Chassis: Driving modes
- Front collision warning with automatic city emergency braking and pedestrian detection
- Transmission: Automatic electric drive with fixed gear ratio
- rear window wiper
- Child safety lock in the rear doors, manual
- Front headrests and 3 rear headrests, height adjustable
- Charging options
- Steering wheel: Leather steering wheel, flattened at the bottom
- Steering column, height and tilt adjustable
- Reading lights, front
- Center armrest, front
- Multi-collision brake
- myOpel App
- Onboard charger (vehicle-integrated charging unit), 3-phase (11 kW)
- Upholstery: Fabric/Premium leather look
- Tire pressure warning
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- "Mokka" lettering on the rear in chrome
- Speed-sensitive power steering
- Visibility equipment
- Seats: Driver's seat 6-way manually adjustable
- Seats: Rear seat backrest foldable in a 60:40 ratio
- Lane Keeping Assist
- Start/Stop System
- Traction control with engine and brake intervention TC Plus
- Underride protection look, front and rear, in silver
- Immobiliser
- Tinted heat-insulating glazing
- Storage: Pockets on the back of the front seats
- Adaptive brake light
- Airbag: Front and side airbags
- Actively controlled air intakes (Active Aero Shutter)
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Battery charging kit: Mode 2 charging cable (1.8 kW) for household socket and battery charging status indicator
- Braking system: Regenerative
- Headliner, Grey
- Decorative strips, silver
- Electronic brake force distribution (EBD)
- Emblem "e" on tailgate
- Electric windows front and rear
- Pedestrian protection
- Cruise control with intelligent speed limiter
- Heated rear window
- Rear shelf
- automatic climate control
- Paint finish: Metallic
- LED headlights (LED ambient lighting in door storage compartments, front - LED turn signals, front and rear - LED taillights - LED daytime running lights - LED headlights - High beam assist)
- Makeup mirror in sun visor, driver and front passenger
- Mode 2 charging cable (Type 2, up to 1.8 kW), 6 m length, for household sockets)
- Fatigue detection
- Opel Connect with telematics services
- Parkpilot, rear parking aid, with acoustic warning signal when reversing.
- Wheels: Light alloy (4) 5 double spokes 6.5 J x 17 in BiColor Black (with tires 215/60 R 17)
- Keyless Start system
- Side impact protection
- Seat belts
- Seats: Passenger seat 6-way manually adjustable
- Seats: Comfort seats, front
- Seats: Pre-installation for ISOFIX child seat mounting system, front passenger seat and rear outer seats
- 12-volt power outlet
- Ambient lighting
- Traffic sign recognition
- heat pump
- Central locking with remote control

Extra equipment

- Double loading floor including mounting bracket for loading floor
- Package: Winter (Seat heating, driver and front passenger, multi-stage switchable - Leather steering wheel, heated)
- Park & Go (Park Pilot, front and rear parking aid with audiovisual warning - 180-degree panoramic reversing camera - blind spot warning and side protection - electrically folding exterior mirrors - ambient lighting - LED fog lights)
- Radio: Multimedia Navi (Mokka-e) (with 7" color touchscreen display and fully digital 7" driver information display - navigation system with integrated memory - road map of Europe (including Russia and Turkey) - 3D map display - dynamic route guidance via map and/or arrow display - display of points of interest - trip planning - GPS module - display of charging stations. OpelConnect, including LIVE navigation services: - map updates (via USB) - voice control for audio, telephone and navigation - radio, Bluetooth, DAB+, USB, hands-free calling.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	A-pillar - trim - interior, left side - Loose - Repair
2	Trim / covers	Boot lid - interior trim - Scratch(es) - Loss in value
3	Side panel - rear left side	Wheel arch - Scratched - Replace
4	Airbag systems	Airbag system - on - Perform diagnosis
5	Boot lid / rear door	Rear spoiler - dent(s) - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Interior - Rear shelf

Repainting

No.	Repainting
1	Bonnet, Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Bonnet	160 µm	Side panel - rear left side	180 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der montierte Winterradsatz ist nicht Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Damage 1: Trim / covers: A-pillar - trim - interior, left side - Loose - Repair



Damage 1: Trim / covers: A-pillar - trim - interior, left side - Loose - Repair



Damage 2: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value




Damage 2: Trim / covers: Boot lid - interior trim - Scratch(es) - Loss in value



Damage 3: Side panel - rear left side: Wheel arch - Scratched - Replace



Damage 3: Side panel - rear left side: Wheel arch - Scratched - Replace




Damage 4: Airbag systems: Airbag system - on - Perform diagnosis




Damage 4: Airbag systems: Airbag system - on - Perform diagnosis



Damage 5: Boot lid / rear door: Rear spoiler - dent(s) - Repair and paint



Damage 5: Boot lid / rear door: Rear spoiler - dent(s) - Repair and paint



Damage 5: Boot lid / rear door: Rear spoiler - dent(s) - Repair and paint



Repainting 1: Bonnet, Side panel - rear left side



Repainting 1: Bonnet, Side panel - rear left side



Repainting 1: Bonnet, Side panel - rear left side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Repainting 1: Bonnet, Side panel - rear left side