TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48286192
Order No. / Reference: 27146330
Inspection date: 23 Oct 2026

Manufacturer: Ford	Model: Transit 350 L3H2 Lkw HA Trend
VIN: WF0EXXTTREPD20222	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit 350 L3H2 Lkw HA Trend	
Vehicle Identification number	WF0EXXTTREPD20222
Mileage (Read)	92,955 km
First registration	9 Aug 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	25,000 km
Last service on / at	12/2025 at 76,720 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT902387
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BNG 10779		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115S	All-season tyres on Steel rim with wheel cover	Goodyear	7mm / 7mm
2)	235/65 R16 115S	All-season tyres on Steel rim with wheel cover	Goodyear	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel	Pirelli	6mm / 6mm
2)	235/65 R16 115R	Winter tyres on Steel	unterschiedliche Hersteller	6mm / 3mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- Rubberized floor, entire vehicle length
- On-board computer
- Double-leaf rear door with 180° opening angle (without window)
- Electronic Stability Program (ESP) with Traction Control (TSC)
- Front electric windows
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Lockable glove compartment with lid
- Front air conditioning
- Cargo area lighting
- MyKey key system
- Package: Technology Package 9
- Wheels: Wheel trims
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Sliding door: Sliding door, right
- Rear mud flaps
- Low side paneling
- Seat belts
- Seats: Seat package 13
- Rear bumper with integrated step
- Partition wall (plastic) with window
- Immobiliser
- Central locking with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- Battery: Battery life, programming of battery life to 10 minutes
- roof, middle
- Tachometer
- Third brake light
- Windows: Sliding windows, right and left (at the height of the 2nd row of seats)
- Ford Easy Fuel
- Generator, high-performance version
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Paint finish: Solid color paint
- Steering column, adjustable in height and reach
- Emergency call assistant
- Particulate filter: diesel particulate filter
- Wheels: Tire repair kit
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Seats: Rear seat package 2
- Start-stop system
- Daytime running light
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Front overhead storage compartment

Extra equipment

- Airbag (passenger side)
- Double-wing rear doors with a 256° opening angle, (without windows) (without rear windows, with holding magnets)
- LED lights in the cargo area
- Package: Technology Package 13 (Heated windscreen, wipers with rain sensor - Front and rear parking sensors, plus side sensors, active radar-based emergency braking assist) - Lane Keeping Assist with Driver Alert and High Beam Assist; plus Lane Keeping Assist and Lane Change Assist - Headlight Assist with day/night sensor - Blind Spot Assist, adaptive cruise control, reversing camera - LED downlights, fog lights - Electrically adjustable, folding, and heated exterior mirrors - Automatic climate control - Ford audio system with 12" multifunction display and Ford SYNC 4
- Partition wall (plastic) with window A6ABE
- Bott installations
- Heated rear windows including rear window protection grille
- Rear step retrofitted
- Navigation system (dynamic and cloud-based navigation with road map for Western Europe - including automatic climate control - Ford audio system with 12" multifunction display and Ford SYNC 4 - Bluetooth, hands-free system with voice control - music playback with voice control - integration of storage media (USB, MP3 player) - FordPass Connect including Wi-Fi hotspot, control of selected functions with the FordPass app - Emergency call assistant - Ford Power-Up - AppLink, Android Auto, Apple CarPlay - touchscreen)
- Wheels: Alloy wheels 6.5 J x 16 (6.5 J x 16 with 235/65 R16 tires)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Mirror glass - Broken / torn - Replace
2	Indicator - front	Mirror - left side - Broken / torn - Replace
3	Indicator - front	Mirror - right side - Broken / torn - Replace
4	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Body	Body - Dent / paintcoat damage - No deduction
3	Misc.	Main inspection - No evidence - No deduction
4	Wing mirror - left side	Cap - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Tirefit complete

Repainting

No.	Repainting
1	Side panel - rear left side, Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear left side	189 µm	Side panel - rear right side	205 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Keine Besichtigung des Unterbodens, Begutachtung Fahrwerk/Achsen/Aggregate nur bedingt möglich, Zusatzkosten können entstehen.

Winter - Radsatz ist kein Bestandteil des Lieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Damage 1: Wing mirror - right side: Mirror glass - Broken / torn - Replace




Damage 1: Wing mirror - right side: Mirror glass - Broken / torn - Replace



Damage 2: Indicator - front: Mirror - left side - Broken / torn - Replace



Damage 2: Indicator - front: Mirror - left side - Broken / torn - Replace



Damage 2: Indicator - front: Mirror - left side - Broken / torn - Replace




Damage 3: Indicator - front: Mirror - right side - Broken / torn - Replace



Damage 3: Indicator - front: Mirror - right side - Broken / torn - Replace



Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Wear and tear 4: Wing mirror - left side: Cap - Scratch(es) - No deduction



Wear and tear 4: Wing mirror - left side: Cap - Scratch(es) - No deduction



Repainting 1: Side panel - rear left side, Side panel - rear right side



Repainting 1: Side panel - rear left side, Side panel - rear right side



Repainting 1: Side panel - rear left side, Side panel - rear right side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Repainting 1: Side panel - rear left side, Side panel - rear right side