MACADAM









CITRO?N BERLINGO: FS-988-SK

Vinnumber:	**VR7EFYHWCLN537886**	Versionname:	**CITRO?N BERLINGO Taille M 1000kg BlueHDi 75 S&S BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)**
First Registrationdate:	**16/09/2020**	Fiscalpower:	
Expertise Mileage:	**150945**	Power Kw:	**55**
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 5 VIT**	Paint type	**Opaque**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Steel**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**No**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**3**		
Number head rests	**3**		
Type of rims (mounted)	**Steel**		
Category	**Light Commercial Vehicle**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**1**	Luggage cover	
Cruise Control		Rear parking sensors	
Type of climate control	**Manual climate control**	Sliding door right-side	
		Seat cover lining	**Lining Other**

Tyres

Summer tyres:	**215/65/16/102 V**			
	Fr.L.	**Other: 0%**	Fr.R.	**Other: 0%**
	Re.L.	**Other: 10%**	Re.R.	**Other: 0%**

Tyre profile depth FL	**8.2**
Tyre profile depth FR	**8.6**
Tyre profile depth RL	**7.6**
Tyre profile depth RR	**8.8**
Tyre size FL	**215/65 R 16 102 V**
Tyre size FR	**215/65 R 16 102 V**
Tyre size RL	**215/65 R 16 102 V**
Tyre size RR	**215/65 R 16 102 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**263**
Tyre make FR	**263**
Tyre make RL	**263**
Tyre make RR	**263**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Steering wheel, Scratch(es), Replace




Door FL, Dent(s), Repair and paint (complete)





Outer sill L, Dent(s) and scratch(es), Replace and paint




Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)





Bumper moulding FR, Scratch(es), Replace




Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)










Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)





Outside rear-view mirror housing R, Scratch(es), Replace

Boot door panel RL, Dent(s) and scratch(es), Replace and paint






Bodywork, Not original part, Acceptable



ALPHABET

Historique Maintenance

Immatriculation: **FS-988-SK** Date de 1ère immatriculation: **16/09/2020**

Modèle: **Citroen BERLINGO Taille M 1000kg BlueHDi 75 S&S BVM Club VU [4P] bvm 5-75CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
03/03/2026	140.471	TREBON AUTO SA	REVISION
	0		DIVERS ECHAPPEMENT
	0		COURROIE ACCESSOIRES RPLT
	0		DIVERS CLIM
	0		REVISION
	0		FILTRE A AIR RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
01/12/2025	120.020	TREBON AUTO SA	PLAQUETTES AR RPLT
	0		BALAIS ESSUIE GLACE AV
	0		DISQUES PLAQUETTES AV RPLT
12/03/2025	99.985	TREBON AUTO SA	REVISION
	0		FILTRE CLIM RPLT
	0		FILTRE A AIR RPLT
	0		REVISION
	0		BALAIS ESSUIE GLACE AV
23/09/2024	84.001	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
14/12/2023	59.131	TREBON AUTO SA	DISQUES PLAQUETTES AV RPLT
	0		FILTRE CLIM RPLT
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
	0		REVISION
	0		ADBLUE
22/09/2022	32.610	TREBON AUTO SA	REVISION
	0		REVISION
	0		FILTRE A AIR RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
	0		RECYCLAGE
	0		BALAIS ESSUIE GLACE AV AR
	0		ADBLUE