TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48509375
Order No. / Reference: 27248297
Inspection date: 2 Nov 2026

Manufacturer: Mercedes-Benz	Model: EQE SUV 350 4MATIC AMG Line Premium
VIN: W1NGM1CB9PA006818	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz EQE SUV 350 4MATIC AMG Line Premium	
Vehicle Identification number	W1NGM1CB9PA006818
Mileage (Read)	124,786 km
First registration	25 Jul 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	07/2028
Fuel type	Electric
Power	135 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	OBSIDIANSCHWARZ - METALLICLACK
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	22,705 km
Last service on / at	05/2025 at 60,886 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV724136
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / BMI 00099		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	3,095 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R20 105Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	255/45 R20 105Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R19 104V	Winter tyres on Light alloy	Dunlop	6mm / 6mm
2)	255/45 R19 104V	Winter tyres on Light alloy	Dunlop	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment under center console
- Airbag: Kneebag for driver
- Airbag: Windowbags all around
- Active Brake Assist
- Ambient lighting
- Trailer maneuvering assistant
- Anti-lock braking system (ABS)
- ATTENTION ASSIST
- Digital Light
- DYNAMIC SELECT
- EASY-Pack: Cargo area cover (removable)
- Electronic Stability Program (ESP)
- Flex Bottle Holder
- GUARD 360° Vehicle Protection Plus
- Rear window wiper/washer system
- Climate: THERMOTRONIC automatic climate control
- Communication module (LTE Advanced) for the use of Mercedes me connect services
- Charging cable for household socket, 8m, smooth
- Charging system: Direct current charging system (DC charging) up to 200 kW
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Center console fine texture look black
- Package: AMG Line Exterior
- Package: Display Package
- Package: Customization Package
- Package: Night
- Upholstery: ARTICO leatherette/MICROCUT microfiber
- Radio accessories: Burmester 3D surround sound system
- Tire pressure monitoring system
- Remote and Charging Services Premium
- Three-point seat belts on all seats
- Seats: 4-way lumbar support for driver
- Seats: Rear seat backrests foldable
- Heated seats for driver and front passenger
- Phone accessories: Smartphone integration
- TIREFIT with tire inflation compressor
- Traffic Sign Assistant
- Pre-installation for MBUX Entertainment Plus
- Immobiliser
- heat pump
- Airbag for driver and front passenger
- Airbag: Center airbag
- AIRMATIC
- Acoustic environmental protection
- AMG floor mats
- Towbar with ESP trailer stabilization
- Traction control (ASR)
- Basic services
- Third brake light in LED technology
- EASY-PACK tailgate
- Illuminated door sills with "Mercedes-Benz" lettering
- Electric windows, front and rear
- Transmission: Direct drive
- Head-up display
- Black fabric headliner
- Climate: Pre-conditioning
- Rear headrests (3)
- Paint finish: Metallic
- Charging cable for wallbox and public charging station, 8m, smooth
- Steering wheel: Steering wheel heating
- Steering: Parameter steering
- Mercedes-Benz emergency call system
- Navigation: MBUX Navigation Premium
- Package: AMG Line Premium
- Package: Driver Assistance Package Plus
- Package: Memory
- Package: Mirror Package
- PRE-SAFE system
- Radio accessories: Digital radio
- Remote Services Premium
- Wheels: 53.3 cm (20") AMG light-alloy wheels in a 5-twin-spoke design
- Seats: Heated rear seats
- Seats: Sports seats
- Phone accessories: Wireless charging system for mobile devices
- Separation net
- Pre-installation for digital key handover
- High-visibility vest for drivers
- Heat-insulating dark tinted glass
- Decorative elements laser-cut and backlit with Mercedes-Benz pattern

Extra equipment

- Pirelli W SottoZero complete winter wheel

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Braking system	Brake fluid - No evidence - No deduction
3	Documents	Service book - Incomplete - No deduction
4	Bonnet	Bonnet bowden cable (Hebel innenraum) - Missing - Replace
5	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
6	Door - front left side	Door edge - Scratch(es) - Smart repair
7	Side panel - rear left side	Sill - Scratch(es) - Smart repair
8	Mudguard - right side	Mudguard - right side - Scratch(es) - Smart repair
9	Bonnet	Support - Missing - Replace
10	Indicator - front	Mirror - right side - Broken / torn - Replace
11	Front bumper	Front bumper (Sandstrahlefekt) - Stone chips - Paint
12	Door - rear right side	Door - Scratch(es) - Paint
13	Door - rear left side	Door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Body	Body (Waschstraßenkratzer) - Scratch(es) - No deduction
2	Rear bumper	Rear bumper - Abrasion - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 18 May 2026	1.324,20 €
2	Front, Provided by user / customer, from 28 Mar 2025	2.526,00 €

Repainting

No.	Repainting
1	Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	185 µm

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Der beiliegende Radsatz gehört nicht zur Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.




Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.




Figure 42: Misc.



Figure 43: Misc.




Figure 44: Misc.




Figure 45: Misc.



Figure 46: Misc.




Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 5: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 7: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 7: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 8: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



Damage 8: Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



Damage 9: Bonnet: Support - Missing - Replace



Damage 9: Bonnet: Support - Missing - Replace




Damage 10: Indicator - front: Mirror - right side - Broken / torn - Replace



Damage 10: Indicator - front: Mirror - right side - Broken / torn - Replace



Damage 11: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 11: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint




Damage 11: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint




Damage 11: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 11: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 11: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint




Damage 11: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 11: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 11: Front bumper: Front bumper (Sandstrahlefekt) - Stone chips - Paint



Damage 12: Door - rear right side: Door - Scratch(es) - Paint



Damage 12: Door - rear right side: Door - Scratch(es) - Paint




Damage 12: Door - rear right side: Door - Scratch(es) - Paint




Damage 12: Door - rear right side: Door - Scratch(es) - Paint



Damage 12: Door - rear right side: Door - Scratch(es) - Paint




Damage 12: Door - rear right side: Door - Scratch(es) - Paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint



Repainting 1: Boot lid / rear door



Repainting 1: Boot lid / rear door