MACADAM
BYD Atto 3 '22 BEV

Vehicle information

Make:	**BYD**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**Atto 3 '22 BEV**	VIN:	**LGXCE4CB4N2093896**
Fuel type:	**Electric**	Power:	**150 kW**
Version:	**ATTO 3 Comfort**	First registration	**04/10/2023**
Mileage:	**32284 km**	N° of doors:	

Damage summary

Interior	1
Left	1
Rear	2
Right	1

Commercial pictures


10:11
10°c
km/h
0
kW
288
km
66%
High OK NORMAL P
000 32284 km




BYD AUTO CO.,LTD.
e9*2018/858*11147*01
LGXCE4CB4N2093896
2 160 kg
- kg
1 - 1 070 kg
2 - 1 110 kg
Model:BYD ATTO3
















Zoeken naar...
Nijkerk, Gelderland


Batterijcertificaat
Datum van diagnose: 05/11/2026
92%
Status van de gezondheid (SOH)*
BYD ATTO 3
VIN : LGXCE4CB4N2093896
Kilometerstand : 32.285 km
*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA







Options according to the inspector


Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Panoramic roof	**Yes**	Radio multimedia	**Yes**	Rear view camera	**Yes**
Sun Roof electric	**Yes**	Telephone equipment	**Yes**		

Damages


Boot lid covering R
Scratch(es)
Smart repair
Rear





Bumper moulding R
Scratch(es)
Replace and paint
Rear


Door RR
Scratch(es)
Repair and paint (complete)
Right

Interior
Stain
Cleaning
Interior

Wing FL
Scratch(es)
Repair and paint (complete)
Left





Tyres

Front Left
Summer
235/50/15/101/V
Continental
4.0 mm
Front Right
Summer
235/50/15/101/V
Continental
4.0 mm
Rear Left
Summer
235/50/15/101/V
Continental
5.3 mm
Rear Right
Summer
235/50/15/101/V
Continental
5.2 mm

Checks

CO2 Emission	**0**	Digital maintenance	**Yes**
Luggage cover	**Yes**	Number head rests	**3**
Number of charging cables (rapid charge)	**1**	Number of keys total	**2**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Service book	**N/A**
User's manual	**Yes**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.