TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48488944
Order No. / Reference: 27188811
Inspection date: 29 Oct 2026

Manufacturer: Polestar	Model: 2 Dual Motor 78kWh
VIN: YSMVSEDE8PL165018	





Vehicle details

Manufacturer / Type / Model / Equipment	
Polestar 2 Dual Motor 78kWh	
Vehicle Identification number	YSMVSEDE8PL165018
Mileage (Read)	62,763 km
First registration	24 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2028
(Report on hand)	
Fuel type	Electric
Power	160 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	Saloon car
Colour / colour code	Magnesium Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	20,393 km
Last service on / at	06/2026 at 53,156 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV805628
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Not possible
Manufacturer key number/ type code number	2219 / AAA 00007		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,600 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R19 102V	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	245/45 R19 102V	Summer tyres on Light alloy	Michelin	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R19 102V	Winter tyres on Light alloy	Continental	7mm / 7mm
2)	245/45 R19 102V	Winter tyres on Light alloy	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- 12V socket in the trunk
- Acoustic Vehicle Alert System - AVAS
- Airbags: Head/shoulder airbags
- Airbags: SIPS side airbags (including inner side)
- Armrest with cup holder and storage compartment
- Automatic braking after a collision
- Back window, heater
- Charging cable (7 meters) for normal sockets (10A 2.3kW - Schuko plug, Type 2, Mode 2)
- Connected Safety (Connected Safety transmits information between your vehicle and other vehicles via the internet. This function can inform the driver if another vehicle on the current route has activated its hazard warning lights or has detected slippery road conditions. Connected Safety communication only works between vehicles equipped with this function and in which it is activated.)
- ECC 2-zone air conditioning
- Electric child safety lock
- Electronic Stability Control (ESC) and traction control
- Frameless, electrically adjustable exterior mirrors (automatically dimming exterior mirrors)
- Front and rear headrests
- Front storage compartment 41 liters
- Infotainment powered by Android (incl. Google Assistant, Google Maps, Google Play Store -Google service connectivity -Over-the-air (OTA) updates for life)
- Keyless opening and starting (remote control for central locking including charging flap - electrically operated trunk lid with extra-wide foot sensor)
- One pedal drive (regenerative braking)
- Paint finish: Magnesium Metallic
- Polestar Connect (Thanks to Polestar Connect, the driver can communicate with the Polestar 2. For example, the Polestar Connect app allows the driver to switch on the climate control without entering the passenger compartment. The vehicle has buttons for making breakdown or emergency calls. In the event of an accident, the Polestar 2 even automatically makes an emergency call and a call if it is stolen.)
- Rear lights, Full-LED (Full LED rear light with persistent light signature - automatically dimming)
- Rear view camera
- Seats: Semi-electric seats, front (driver's seat memory - lumbar support, front - 4-way electrically adjustable)
- Seats: Split and foldable rear bench seat (40/60)
- Steering wheel: Multifunction steering wheel, height and reach adjustable
- Textile floor mats
- third brake light
- 2 USB ports on the back
- 2 USB ports on the front
- Airbags, driver and front passenger (passenger airbag, deactivatable)
- Alarm system (double locking - Alarm inclination sensor and motion sensor)
- Automatic headlight range control
- Automatically folding exterior mirrors
- Bluetooth
- Charging cable (6 meters) (16A 11kW - Type 2, Mode 3)
- CleanZone (cabin air filter)
- Collision avoidance and mitigation (with braking and steering support - vehicle, cyclist and pedestrian detection)
- Driver Alert Control
- Driver display 12.3" (Progressive - digital display)
- Electric parking brake (with auto-hold function)
- Electric tailgate with soft closing
- electric window regulators
- First aid kit
- Forward Collision Warning
- Front and rear parking assist
- Hexagonal gear selector with illuminated Polestar symbol
- High Performance audio (8 speakers/250 W)
- Hill start assist
- Immobiliser
- Indirect tire pressure monitoring
- Integrated eSIM (with constant internet connectivity)
- Interior rearview mirror with automatic dimming function
- ISOFIX attachment for front passenger seat and outer rear seats
- Lane Keeping Assist (LKA) (The lane keeping assist steers the vehicle back into the lane and/or warns the driver with steering wheel vibrations.)
- Large, vertical display with touchscreen (11, 15")
- LED headlights, adaptive (Thor's Hammer daytime running lights)
- Navigation system
- Polestar Digital Key
- Radio accessories: Digital radio DAB+
- Rain sensor
- Seat belts (warning for unfastened seat belts, belt tensioners in the front and on the outer rear seats)
- Seats: Front seats with seat heating
- Servotronic
- Speed limiter and cruise control
- Tire repair kit
- Upholstery: embossed fabric with 3D etched decor
- Vehicle Deceleration Control (ABS, Electronic Brake Distribution and Emergency Brake Assist)
- Wheels: 19" alloy wheels with 5 V-spokes, black, diamond cut (with 245/45 R19 tires on 8Jx19 ET50 front, 9Jx19 ET53 rear)

- Traffic Sign Information (RSI) (Using a camera or information from the Sensus navigation system, it provides information on speed limits, no-overtaking zones, one-way streets and various supplementary signs. The traffic sign is displayed on the speedometer or in the head-up display.)
- Transmission: Direct drive
- Whiplash protection system (In the event of a collision, the backrest and headrest of the front seat move as a unit with the occupant to support their neck.)

Extra equipment

- Package: Plus (Panoramic glass roof with projected Polestar logo, heat pump, WeaveTech seats - Black Ash decor, electrically adjustable front seats with 4-way power lumbar support (memory for driver's seat), leg rest and storage nets in the backrest, heated rear seats, steering wheel and windshield washer nozzles, high-level interior lighting, Harman Kardon premium sound system with 13 speakers, 15W wireless smartphone charging, bag holders, tinted rear window, air quality)
- Winter tires 245/45 R 19

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run could not be performed.

Value reducing factors

No.	Component group	Description
1	Interior	Rear shelf (+ Arretierungsklammer fehlt.) - Damaged - Replace
2	Door - front right side	Door - Scratched - Smart repair
3	Multimedia system	Navigation system - Non-operational - Perform diagnosis
4	Rear bumper	Rear bumper (Ladekante) - Scratched - Smart repair
5	Mudguard - left side	Wheel well extension - Scratched - Replace
6	2nd wheel set	1 alloy rim (Großflächig mit Materialabtrag) - Scratched - Replace
7	2nd wheel set	1 alloy rim - Scratched - Replace
8	2nd wheel set	1 alloy rim - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Mudguard - left side	Mudguard - left side - Abrasion - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Vehicle key with remote control

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres




Figure 19: Navigation




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Interior: Rear shelf (+ Arretierungsklammer fehlt.) - Damaged - Replace




Damage 1: Interior: Rear shelf (+ Arretierungsklammer fehlt.) - Damaged - Replace



Damage 2: Door - front right side: Door - Scratched - Smart repair



Damage 2: Door - front right side: Door - Scratched - Smart repair



Damage 3: Multimedia system: Navigation system - Non-operational - Perform diagnosis



Damage 4: Rear bumper: Rear bumper (Ladekante) - Scratched - Smart repair



Damage 4: Rear bumper: Rear bumper (Ladekante) - Scratched - Smart repair



Damage 4: Rear bumper: Rear bumper (Ladekante) - Scratched - Smart repair




Damage 5: Mudguard - left side: Wheel well extension - Scratched - Replace



Damage 5: Mudguard - left side: Wheel well extension - Scratched - Replace




Damage 6: 2nd wheel set: 1 alloy rim (Großflächig mit Materialabtrag) - Scratched - Replace



Damage 6: 2nd wheel set: 1 alloy rim (Großflächig mit Materialabtrag) - Scratched - Replace



Damage 6: 2nd wheel set: 1 alloy rim (Großflächig mit Materialabtrag) - Scratched - Replace



Damage 7: 2nd wheel set: 1 alloy rim - Scratched - Replace



Damage 7: 2nd wheel set: 1 alloy rim - Scratched - Replace



Damage 7: 2nd wheel set: 1 alloy rim - Scratched - Replace



Damage 8: 2nd wheel set: 1 alloy rim - Scratched - Replace