BMW X3

Vehicle information

Make:	**BMW**	License:	**2ADE416**
Gearbox:		Body color:	
Model:	**X3**	VIN:	**WBATS110309F33466**
Fuel type:		Power:	**120 kW**
Version:	**BMW X3 2.0 XDRIVE30E (120KW) AUTO**	First registration	**25/02/2021**
Mileage:	**75291 km**	N° of doors:	

Damage summary

- **Front** 1
- **Interior** 1
- **Rear** 2
- **Right** 1
- **Roof & others** 1

Commercial pictures
























Options according to the inspector

GPS	**Yes**

Damages

Bodywork
Damaged
Acceptable
Roof & others








Compressor
Missing
Check
Rear



Engine insulation
Tear
Replace
Front



Interior
Damaged
Acceptable
Interior




Tyre repair kit
Missing
Check
Rear



Wing RR
Dent(s)
Repair and paint (complete)
Right





Tyres

Front Left
Summer
Aluminium
225/60/18/104/W
Bridgestone
5.0 mm
Front Right
Summer
Aluminium
225/60/18/104/W
Bridgestone
4.0 mm
Rear Left
Summer
Aluminium
225/60/18/104/W
Bridgestone
4.0 mm
Rear Right
Summer
Aluminium
225/60/18/104/W
Bridgestone
5.0 mm

Checks

Battery level	**100**	Category	**Passenger Car**
Certificate of Conformity	**Yes**	Compressor	**N/A**
Number of charging cables (normal)	**2**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Registration Certificate Car (BE)	**Yes**
Registration Certificate Home (BE)	**No**	Repair kit	**N/A**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Statutory inspection	**OK**
Type of Maintenance book	**Digital maintenance**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.