

MACDAM

Kia Niro FL'19 BEV

Vehicle information


Make:	Kia	License:	
Gearbox:	Automatic	Body color:	
Model:	Niro FL'19 BEV	VIN:	KNACC81GFM5085168
Fuel type:	Electric	Power:	150 kW
Version:	Niro EV 64kWh 11 f.3 Dyn.+Line	First registration	24/09/2021
Mileage:	173621 km	N° of doors:	

Damage summary

Front	2
Left	5
Rear	7
Right	4

Commercial pictures





Options according to the inspector				
Central consol F	Yes	GPS	Yes	Headlights Xenon/LED/Laser
Hook	Yes	Panoramic roof	Yes	Radio multimedia
Rear view camera	Yes	Sun Roof electric	Yes	Telephone equipment

Damages				
Alloy rim FL Scratch(es) Repair and paint (complete) Left	 			
Alloy rim RL Rust Repair and paint (complete) Left	 			
Alloy rim RR Scratch(es) Repair and paint (complete) Right	 			
Bonnet Stone chip(s) Repair and paint (complete) Front	 			
Bumper F Scratch(es) Repair and paint (partial) Front	 			

Bumper R
Scratch(es)
Repair and paint (complete)
Rear



Door frame FL
Dent(s) and scratch(es)
Repair and paint (complete)
Left



Door frame RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right




Door RL
Scratch(es)
Repair and paint (partial)
Left




Door RR
Scratch(es)
Repair and paint (partial)
Right



Internal boot lining L
Scratch(es)
Smart repair
Rear



Internal boot lining R
Scratch(es)
Smart repair
Rear



Rear light L
Broken
Replace
Rear



Rear light L tailgate
Broken
Replace
Rear



Rear spoiler
Scratch(es)
Repair and paint (complete)
Rear



Tailgate / Boot
Scratch(es)
Repair and paint (complete)
Rear



Wing RL
Scratch(es)
Repair and paint (complete)
Left



Wing RR
Dent(s)
Repair and paint (complete)
Right



Tyres	
	Front Left
	Summer
	215/55/17/94/W
	Michelin
	6.1 mm
	Front Right
	Summer
	215/55/17/94/W
	Michelin
	6.1 mm
	Rear Left
	Summer
	215/55/17/94/W
	Michelin
	4.7 mm
	Rear Right
	Summer
	215/55/17/94/W
	Michelin
	5.3 mm

Checks			
Certificate of Conformity	No	CO2 Emission	0
Digital maintenance	N/A	GPS storage	Yes
GPS storage	HD	Luggage cover	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of keys total	2	Reset to factory settings	Yes, vehicle is reset to factory settings
Service book	Yes	User's manual	Yes

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.