TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48366412
Order No. / Reference: 27208586
Inspection date: 28 Oct 2026

Manufacturer: Mercedes-Benz	Model: GLC 300 e 4Matic 9G-TRONIC Avantgarde Advanced
VIN: W1NKM5GB6PF046868	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLC 300 e 4Matic 9G-TRONIC Avantgarde Advanced	
Vehicle Identification number	W1NKM5GB6PF046868
Mileage (Read)	77,440 km
First registration	29 Jun 2023
Number of holders	1
Next periodical technical inspection	06/2026
(Report not on hand)	
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,999 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Schwarz
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Beige-Black
Re-import	no
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	-52,440 km
Last service on / at	07/2024 at 26,938 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV696609
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	2222 / BLC 00009		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,890 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	255/55 R18 109H	Winter tyres on Light alloy	Continental	6 mm
	255/55 R18 109H	Summer tyres on Light alloy	Continental	6 mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103W	Summer tyres on Light alloy	Goodyear	5mm / 5mm
2)	255/55 R18 109W	Summer tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Adaptive Highbeam Assist
- Airbag: Kneebag for driver
- Airbag: Windowbag
- Active Lane Keeping Assist
- Ambient lighting
- Traction control (ASR)
- Automatic passenger airbag deactivation
- AVANTGARDE Interior
- Brake system with larger brake discs on the front axle
- Double cup holder
- Tachometer
- EASY-PACK tailgate
- Electronic Stability Program (ESP)
- Chassis: Comfort chassis
- Velour floor mats
- Transmission: 9G-TRONIC
- Rear window heated
- Rear window wiper/washer system
- Instrument panel in black with contrasting decorative stitching
- Communication module (LTE) for the use of Mercedes me connect services
- Radiator grille with integrated Mercedes star
- Paint finish: Solid
- Charging cable for household socket, 5m, smooth (This charging cable, also called Mode 2 cable, allows you to charge the vehicle battery at the household socket with up to 1.8 kW (230 V, 1-phase, 8 A) and fits sockets of type E/F CEE 7/7.)
- Charging system: Alternating current charging system (AC charging) up to 11 kW (3-phase)
- LED High Performance headlights (torch and trifunctional light guide for daytime running lights, position lights and turn signals - multi-chamber reflector system with 4 individual reflectors each) for low beam and high beam. The rear light elements in LED technology: - All light functions in full LED technology - tail light - brake light and parking light - rear fog light (left side only) - turn signals in the white light strip - reversing light in the white light strip - 3rd brake light
- Navigation accessories: Pre-installation for navigation services
- Navigation: Hard disk navigation
- Otto particulate filter
- Package: Storage
- Package: Avantgarde Advanced (for hybrid models) (P14 AVANTGARDE Interior - P15 AVANTGARDE Exterior - 38U Remote and Charging Services Plus - 70B Warning vest for driver - 9B2 Charging cable for wallbox and public charging station, 5m, smooth - PBG MBUX Navigation Premium - PDA Advanced package)
- Package: Boot Comfort Package (electrically foldable rear seat backrests via switches on the right and left in the control panel in the cargo area - 12V socket on the left in the control panel in the cargo area - tension strap on the right side wall - reversible mat with a rubberized, non-slip side and a soft velour side)
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- 4MATIC all-wheel drive
- Anti-lock braking system (ABS)
- ATTENTION ASSIST
- AVANTGARDE Exterior
- Basic services
- Roof rails made of glossy anodized aluminum
- Downhill Speed Regulation (DSR)
- Dynamic front bumper with visual underguard
- EASY-Pack: Cargo area cover
- Driver display
- Fingerprint scanner (color-illuminated fingerprint scanner in the control bar below the central display - two fingerprints can be stored per user - faster access replaces PIN entry - protects personal data such as profiles as well as office and payment functions)
- Climate: THERMATIC automatic climate control (2-zone automatic climate control - control of climate settings - depending on equipment - sensor system for detecting, for example, indoor/outdoor temperature, solar radiation, humidity and dew point - automatic recirculation - ventilation system: 3 center vents in the center area and 2 side vents (each swiveling and adjustable), 2 air vents each in the footwell for driver and front passenger - fine dust activated carbon filter for filtering dust, soot and pollen - dew point sensor)
- Charging cable for wallbox and public charging station, 5m, smooth (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 11 kW (Type 2, 3-phase, 16 A).)
- Steering wheel: Multifunction sports steering wheel in leather
- Mercedes-Benz emergency call system
- Center console in high-gloss black
- Navigation accessories: Extended MBUX functions
- Navigation accessories: Pre-installation for Live Traffic Information
- Navigation accessories: Pre-installation for remote and navigation services
- Navigation: MBUX Navigation Premium (Pre-installation for navigation services - Hard drive navigation - Pre-installation for Live Traffic Information - 3 years of free navigation updates for map data)
- Package: Chrome Interior Package
- Package: Interior lighting (More light, more atmosphere, better orientation: The interior lighting package provides more comprehensive direct and indirect lighting. The additional light elements create a pleasant atmosphere and make operation easier.)

- Package: Seating Comfort (various electric and manual adjustment options for the front seats to adapt to the specific body and comfort requirements of the driver and front passenger - electropneumatic 4-way lumbar support and lateral support adjustment with control element on the seat - electric seat cushion tilt adjustment - electric height adjustment - electric backrest adjustment - electric seat cushion depth adjustment by 6 cm with leg rest pad - mechanical longitudinal adjustment - mechanical headrest adjustment)
- Upholstery: ARTICO leatherette/fabric
- Radio accessories: Digital radio (DAB)
- Tire pressure loss warning
- Wheels: 45.7 cm (18") light alloy wheels in 5-spoke design (aerodynamically optimized, painted black and polished with front axle 235/60 R18 on 8.0 J x 18 ET 32.5 and rear axle 255/55 R18 on 9.0 J x 18 ET 30)
- Seats: 4-way lumbar support for driver and front passenger
- Phone accessories: Wireless charging system for mobile devices
- Pre-installation for digital key handover
- Immobiliser
- Central display
- Decorative elements in diamond pattern, silver-grey
- Package: Parking package with reversing camera (12 ultrasonic sensors: 6 each in the front and rear bumpers - reversing camera: integrated into the trunk lid, display in the media display, trailer mode - Active Parking Assist PARKTRONIC: detects parking spaces, assisted parking, assisted exiting, visual and acoustic warning of detected obstacles, display of camera and ultrasonic data in the central display, button for Active Parking Assist with PARKTRONIC - cross traffic warning - maneuvering brake - drive-away assist)
- Package: Mirror package (interior and exterior mirrors on the driver's side automatically dimming - exterior mirrors left and right electrically folding - ambient lighting in the exterior mirrors)
- Package: USB package (2 USB-C ports under the front center armrest, suitable for data transfer)
- Radio accessories: MBUX multimedia system
- Remote and Charging Services Plus
- Wheels: Summer tires
- Wheel accessories: TIREFIT with tire inflator compressor
- Windscreen wipers with rain sensor
- Power steering
- Heated seats for driver and front passenger
- Phone accessories: Smartphone integration
- Cruise control
- High-visibility vest for drivers
- Heat-insulating dark tinted glass
- Central locking with remote control

Extra equipment

- Black fabric headliner
- Upholstery: ARTICO man-made leather
- Wheels: Complete summer wheel sets fitted at the factory
- Wheels: Winter complete wheels M+S 4-way 45.7 cm (18") light alloy wheels in 5-spoke design (aerodynamically optimized, black painted and gloss-turned with front axle 235/60 R18 on 8.0 J x 18 ET 32.5 and rear axle 255/55 R18 on 9.0 J x 18 ET 30)
- Sunroof: Panoramic sunroof (large glass module made of heat-insulating safety glass - mesh wind deflector in the front area - electric sunshade with one-touch operation - comprehensive protection concept: anti-pinch protection, automatic rain closing, automatic closing when the recirculation function is activated, PRE-SAFE closing function (only in conjunction with PRE-SAFE system))
- Decorative elements: open-pored brown walnut wood
- Package: Driving Assistance Package Plus (Active Distance Assist DISTRONIC, Active Speed Limit Assist, Extended Automatic Restart, Route-Based Speed Adaptation with Traffic Jam Definition, Active Steering Assist, Active Lane Change Assist, Active Emergency Stop Assist with SOS Radio, Emergency Lane Radio, Active Brake Assist, Turn and Intersection Radio, Traffic Jam Emergency Brake Radio, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist, Exit Warning Radio, PRE-SAFE PLUS Pedestrian Warning Function, Traffic Sign Assist, Active Traffic Jam Assist, PRE-SAFE Impulse Side)
- Traffic Sign Assistant (Camera and navigation data always keep an eye on the current speed limit – so you stay oriented even in a maze of signs. Because the system constantly informs you, the risk of violations decreases. This is not only convenient, but also increases safety in everyday road traffic.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Door - rear left side	Door - Scratch(es) - Cover / polish
2	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
3	Door - front left side	Door edge - Scratch(es) - Smart repair
4	Misc.	Main inspection - Due - Perform
5	Wheel / tyres	Tyre - front right side (235 60 18 s) - Worn - Replace
6	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
7	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
8	Misc.	Inspection / maintenance - Due - Perform
9	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
10	Bonnet	Bonnet (Vogelkot) - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Body	Underbody panelling - Scratch(es) - No deduction
2	Boot lid / rear door	Boot lid - dent(s) - No deduction
3	Misc.	Inspection / maintenance (Nur erste Inspektion/Motorölservice nachgewiesen) - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Provided by user / customer, from 25 Jun 2025	3.486,34 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Damage 1: Door - rear left side: Door - Scratch(es) - Cover / polish




Damage 1: Door - rear left side: Door - Scratch(es) - Cover / polish



Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair




Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 5: Wheel / tyres: Tyre - front right side (235 60 18 s) - Worn - Replace



Damage 5: Wheel / tyres: Tyre - front right side (235 60 18 s) - Worn - Replace



Damage 5: Wheel / tyres: Tyre - front right side (235 60 18 s) - Worn - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 8: Misc.: Inspection / maintenance - Due - Perform




Damage 9: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 9: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 9: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 9: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 9: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 10: Bonnet: Bonnet (Vogelkot) - Scratch(es) - Paint



Damage 10: Bonnet: Bonnet (Vogelkot) - Scratch(es) - Paint



Damage 10: Bonnet: Bonnet (Vogelkot) - Scratch(es) - Paint



Wear and tear 1: Body: Underbody panelling - Scratch(es) - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Wear and tear 2: Boot lid / rear door: Boot lid - dent(s) - No deduction