VOLVO XC40

Vehicle information


Brand:	**VOLVO**	License plate:	**2CAK677**
Gearbox:		Body color:	
Model:	**XC40**	LEVEL:	**YV1XZBWVFN2787018**
Fuel type:		Power:	**95 kW**
Version:	**1.5 T4 PHEV REGISTRATION EXPR. DCT**	First registration	**10/05/2022**
Mileage:	**127568 km**	Number of doors:	


Summary of damages


Back	3
Before	1
LEFT	3
Interior	3
Roof & other	1

Commercial photos






























Options according to the inspector

GPS	**Yes**

Damages

Rear wiper arm
incomplete
E - Replace
Rear





Charging cable (normal)
Missing Rear
Control



Fast charging cable
missing
- Replace
rear



Bodywork
Damaged -
Acceptable.
Roof & other














Interior
Sale
Package
Interior




Damaged **Interior**
- Acceptable
Interior








Polished ARG alloy
rim with scratches
on the left - Repair and paint (complete
)





Polished front left alloy wheel
with scratches
on the left - Repair and paint (complete
)




Windshield
Repaired
Acceptable
Before




Left rear tire
tear
-
Replace





AVG Backrest Cover, Smart Repair
Scratch(es), Interior





Tires

Front Left
Summer
Aluminum
235/55/18/100/V
Michelin
5.0 mm
Front Right
Summer
Aluminum
235/55/18/100/V
Michelin
5.0 mm
Left Back
Summer
Aluminum
235/55/18/100/V
Michelin
5.0 mm
Rear Right
Summer
Aluminum
235/55/18/100/V
Michelin
5.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Vehicle inspection	**OK**
Vehicle inspection	**10/05/2028**	Interview	**OK**
Interview	**+ 12853 km**	Repair kit	**Yes**
Number of charging cables (220V)	**0**	Number of charging cables (fast charging)	**0**
Total number of keys	**2**	Charge level	**100**
Factory reset	**Yes, the vehicle has been reset to factory settings.**	Type of maintenance log	**Maintenance logbook present**

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable usage damage according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.