TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48417617
Order No. / Reference: 27182697
Inspection date: 29 Oct 2026

Manufacturer: Volkswagen	Model: Passat Variant 2.0 TDI SCR Business
VIN: WVWZZZ3CZPE043678	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Passat Variant 2.0 TDI SCR Business	
Vehicle Identification number	WVWZZZ3CZPE043678
Mileage (Read)	100,408 km
First registration	8 Aug 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Aquamarinblau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	12,700 km
Last service on / at	09/2026 at 97,906 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS446584
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / BQS 04003		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,170 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99V	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	215/60 R16 95V	Summer tyres on Light alloy	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99H	Winter tyres on Light alloy	Pirelli	7mm / 7mm
2)	215/60 R16 99H	Winter tyres on Light alloy	Pirelli	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Adaptive Cruise Control (ACC) including speed limiter
- Cup holders (2) front
- Hill start assist
- Chrome trim on the side windows
- black roof rails
- Tachometer
- Entry/warning lights in LED technology in the front doors
- Electronic parking brake including auto-hold function
- Automatic headlight control
- Remote release for luggage compartment lid
- Pedestrian detection
- Adjustable luggage compartment floor
- Rear window heated
- Interior lights with delayed shut-off and dimming function
- Rear headrests (3)
- LED fog lights and cornering lights
- LED headlights with daytime running lights
- Headlight range control
- "Premium" multifunction display with multicolor screen
- Fatigue detection
- Non-smoking version
- Emergency call service
- Package: Light and Sight Package "Plus"
- Proactive occupant protection system in conjunction with "Front Assist"
- Wheels: 4 light alloy wheels "Sepang" 6.5 J x 16
- Rear bench seat, undivided, backrest asymmetrically split and foldable, with center armrest
- Seat belts: Three-point automatic seat belt
- Seats: Lumbar support in the front
- Lane keeping assistant “Lane Assist”
- 12V power outlet on the rear of the center console
- Textile floor mats
- Warning tone and light for unfastened seat belts front and rear
- Airbag, head airbag system for front and rear passengers
- App-Connect
- Electrically adjustable and heated exterior mirrors, ambient lighting
- third brake light
- Headliner in Mistral Grey
- Diesel particulate filter
- Parking aid - warning signals for obstacles in the front and rear area
- Electronic stability program and electromechanical brake booster
- Windscreen made of laminated safety glass, heat and sound insulating
- Transmission: 6-speed manual transmission
- rear window wiper
- ISOFIX mounting points
- Front headrests
- LED taillights
- Steering wheel: Multifunction steering wheel in leather
- Front center armrest, height and length adjustable, with storage box
- Mesh partition
- Emergency braking assistant "Front Assist" (for automatic distance control ACC up to 210 km/h)
- Upholstery: "Business" fabric
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system (passive)
- Wheels: Tire Mobility Set
- Keyless start system without safe locking
- Power steering
- Seats: Comfort seats in the front
- Seats: Front seats are height-adjustable
- Start-stop system
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control

Extra equipment

- App-Connect Wireless (Volkswagen offers three interfaces for connecting smartphones with numerous possibilities: - Apple CarPlay - Android Auto from Google - MirrorLink)
- Navigation system "Discover Media" incl. "Streaming & Internet" (4x20 watts, user interface with proximity sensor, dual tuner with phase diversity, vehicle menu, speed, volume adjustment, map, 2D display, tone control, 3-way TFT display with touchscreen operation, navigation "Discover Media" incl. "Streaming & Internet", MP3 radio, telephone contact addresses for navigation, telephone interface, 2 USB ports also for iPod/iPhone, traffic sign recognition "VW Media Control", We Connect Plus, 3 years, incl. We Connect route guidance, dynamic RDS, TMC tuner)
- Package: Ambient lighting (ambient lighting, 1-color - entry/warning lights in LED technology in all doors)
- Sunshade roller blind on the rear door windows
- "Comfort" telephone interface with inductive charging function (hands-free system)
- Roof rails, silver anodized, with 2 silver anodized support bars (with anti-theft device and included in a storage bag)
- Digital Cockpit, multi-colored (various info profiles selectable)
- Package: "Business Premium" package incl. navigation (from Business trim level) (2 USB-C ports in the front, USB-C charging socket in the rear, 230V socket, App-Connect incl. wireless, Apple CarPlay, Android Auto, "Travel Assist" driver assistance system and "Lane Assist" lane keeping assist system, Air Care Climatronic with 3-zone temperature control, active combination filter and rear controls, lumbar support in the front, electric on the driver's side, massage function on the driver's side, "Rear View" reversing camera, heated windshield washer nozzles, Comfort telephone interface, inductive charging function, heated front seats)
- Voice control

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Trim / covers	Boot lining (Blende Links) - Missing - Replace
3	Door - front right side	Door handle - outside - Scratched - Smart repair
4	Door - rear right side	Door - Scratched - Smart repair
5	Door - front left side	Door edge - Scratched - Smart repair
6	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
7	Mudguard - left side	Mudguard - left side - Scratched - Smart repair
8	Side panel - rear right side	Side panel - Scratched - Smart repair
9	Front bumper	Front bumper - Scratched - Smart repair
10	Steering system	Steering wheel - Scratched - Smart repair
11	Side panel - rear left side	Side panel - Scratched - Smart repair
12	Rear bumper	Rear bumper - Scratched - Repair and paint
13	Vehicle glazing	Windscreen (Mit Rissbildung im Randbereich) - Stone chips - repair according to calculation

Wear and tear

No.	Component group	Description
1	2nd wheel set	1 tyre (Karkasse beschädigt, Nicht Bestandteil der Ausstattung) - Damaged - No deduction
2	2nd wheel set	1 alloy rim (Nicht Bestandteil der Ausstattung) - Deformed - No deduction
3	2nd wheel set	1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction
5	Door - front right side	Door - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Der angegebene Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

- Ein Nachweis über die Zulässigkeit des beiliegenden Radsatzes wurde nicht erbracht.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Damage 2: Trim / covers: Boot lining (Blende Links) - Missing - Replace



Damage 2: Trim / covers: Boot lining (Blende Links) - Missing - Replace



Damage 3: Door - front right side: Door handle - outside - Scratched - Smart repair




Damage 3: Door - front right side: Door handle - outside - Scratched - Smart repair




Damage 4: Door - rear right side: Door - Scratched - Smart repair




Damage 4: Door - rear right side: Door - Scratched - Smart repair




Damage 5: Door - front left side: Door edge - Scratched - Smart repair



Damage 5: Door - front left side: Door edge - Scratched - Smart repair



Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 6: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 7: Mudguard - left side: Mudguard - left side - Scratched - Smart repair




Damage 7: Mudguard - left side: Mudguard - left side - Scratched - Smart repair



Damage 8: Side panel - rear right side: Side panel - Scratched - Smart repair



Damage 8: Side panel - rear right side: Side panel - Scratched - Smart repair




Damage 9: Front bumper: Front bumper - Scratched - Smart repair




Damage 9: Front bumper: Front bumper - Scratched - Smart repair




Damage 10: Steering system: Steering wheel - Scratched - Smart repair




Damage 10: Steering system: Steering wheel - Scratched - Smart repair



Damage 10: Steering system: Steering wheel - Scratched - Smart repair



Damage 10: Steering system: Steering wheel - Scratched - Smart repair



Damage 11: Side panel - rear left side: Side panel - Scratched - Smart repair



Damage 11: Side panel - rear left side: Side panel - Scratched - Smart repair



Damage 12: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage 12: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 12: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 12: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 12: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 12: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 13: Vehicle glazing: Windscreen (Mit Rissbildung im Randbereich) - Stone chips - repair according to calculation



Damage 13: Vehicle glazing: Windscreen (Mit Rissbildung im Randbereich) - Stone chips - repair according to calculation



Wear and tear 1: 2nd wheel set: 1 tyre (Karkasse beschädigt, Nicht Bestandteil der Ausstattung) - Damaged - No deduction



Wear and tear 1: 2nd wheel set: 1 tyre (Karkasse beschädigt, Nicht Bestandteil der Ausstattung) - Damaged - No deduction



Wear and tear 1: 2nd wheel set: 1 tyre (Karkasse beschädigt, Nicht Bestandteil der Ausstattung) - Damaged - No deduction



Wear and tear 2: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Deformed - No deduction



Wear and tear 2: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Deformed - No deduction



Wear and tear 2: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Deformed - No deduction



Wear and tear 3: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction




Wear and tear 3: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction




Wear and tear 4: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 4: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 4: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 4: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 5: Door - front right side: Door - Scratched - No deduction



Wear and tear 5: Door - front right side: Door - Scratched - No deduction