TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48388046
Order No. / Reference: 27204110
Inspection date: 27 Oct 2026

Manufacturer: Ford	Model: Transit Custom 340 L1H1 LKW VA 1.0 EcoBoost PHEV Trend Kasten
VIN: WF0YXXTTGHLB75422	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Custom 340 L1H1 LKW VA 1.0 EcoBoost PHEV Trend Kasten	
Vehicle Identification number	WF0YXXTTGHLB75422
Mileage (Read)	51,131 km
First registration	20 May 2020
Number of holders	1
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	996 ccm / 3
Power	62 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Available / incomplete	**Next maintenance in**	
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FS974424
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BTU 00001		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,400 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	Summer tyres on Steel rim with wheel cover	Fulda	8mm / 8mm
2)	215/65 R16 109T	Summer tyres on Steel rim with wheel cover	Falken	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109R	Winter tyres on Steel	Semperit	7mm / 7mm
2)	215/65 R16 109R	Winter tyres on Steel	Pirelli	9mm / 9mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 109T C	Summer tyres on Light alloy	Goodyear	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Theft alarm system
- Tachometer
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- Geofencing
- Speed limiter 120 km/h
- Glove compartment with lid
- Front air conditioning
- Cargo area lighting with activatable switch-off delay
- Steering column, adjustable in height and reach
- Gasoline particulate filter (GPF)
- Radio: Audio system 17: Ford audio system with 4" multifunction display, additionally with DAB/DAB+
- Wheels: Steel wheels 6.5 J x 16 with 215/65 R 16 C 109 T tires
- Sliding door: Sliding door, right
- Side protection strips
- Seat belts
- Power outlet: 12-volt connection in the passenger compartment
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric
- Driver's side airbag
- Exterior mirrors with integrated turn signals
- On-board computer
- Headliner in driver's cab
- Double-leaf rear door with 180° opening angle (without window)
- Front electric windows
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 1-speed direct drive
- Interior lighting with delay circuit
- Paint finish: Solid color paint
- Cargo area floor: Vinyl floor covering omitted
- Emergency brake assist including emergency brake light
- Package: Visibility Package I
- Wheel hub covers
- Wheels/Tires: Spare wheel, steel wheel
- Headlight low beam: Halogen headlights with daytime running lights
- Mud flaps front and rear
- Power steering
- Seats: Seat package 11 - partition (with pass-through flap)
- Lashing eyes 8
- Immobiliser
- Central locking with remote control

Extra equipment

- Airbag (passenger side)
- Double-leaf rear door with 90° opening angle (with window)
- Paintwork: Special paintwork in standard color
- Package: Cargo Area Protection Package "Heavy Duty"
- Radio: Audio system 24: Ford audio system including Ford SYNC3 with AppLink, DAB/DAB+, navigation system.
- Headlights: Halogen projector headlights
- Sliding door: Sliding door, left
- Exterior mirrors, electrically adjustable, heated and foldable
- Rear swing door without window
- LED lights in the cargo area
- Front and rear parking pilot system including fog lights
- Tire Pressure Monitoring System (TPMS)
- Reversing camera with front and rear parking pilot system with fog lights

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Wear and tear

No.	Component group	Description
1	Body	Wheel well - rear left side - Dent / paintcoat damage - No deduction
2	Body	Wheel well - rear right side - Dent / paintcoat damage - No deduction
3	Roof	Roof - dent(s) - No deduction
4	Sliding door, right	Sliding door - dent(s) - No deduction
5	Door - front left side	Door edge - Scratch(es) - No deduction
6	Documents	Service book - Incomplete - No deduction
7	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Roof - Stub aerial

Repainting

No.	Repainting
1	Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent
2	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
3	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
4	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	1,670 µm	Mudguard - right side	193 µm
Side panel - rear left side	284 µm	Door - front right side	175 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Comments

- Service-Restlauf wird nicht angezeigt.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Repainting 1: Boot lid / rear door



Repainting 1: Boot lid / rear door



Repainting 2: Mudguard - right side



Repainting 2: Mudguard - right side



Repainting 3: Side panel - rear left side



Repainting 3: Side panel - rear left side



Repainting 4: Door - front right side



Repainting 4: Door - front right side