TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48361802
Order No. / Reference: 27080659
Inspection date: 28 Oct 2026

Manufacturer: Opel	Model: Vivaro 2.0 D Cargo L EHZ Autm. Edition Kasten
VIN: VXEVFEHS7N7033541	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Vivaro 2.0 D Cargo L EHZ Autm. Edition Kasten	
Vehicle Identification number	VXEVFEHS7N7033541
Mileage (Read)	191,349 km
First registration	1 Sept 2022
Number of holders	2
Next periodical technical inspection	09/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	106 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Casablanca Weiß
Doors / Seats	4 / 2
Upholstery type	Leather
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	36,160 km
Last service on / at	06/2026 at 177,516 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ695374
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	3003 / BCD 00517		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,100 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	Summer tyres on Steel	Pirelli	6mm / 6mm
2)	215/65 R16 109T	Summer tyres on Steel	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 106T	Winter tyres on Steel	Continental	5mm / 5mm
2)	215/65 R16 106T	Winter tyres on Steel	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 106T	Summer tyres on Steel	Michelin	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Driver and passenger side airbags
- Exterior mirrors, electrically adjustable, heated and manually folding
- Hill Start Assist
- Floor covering: Cargo area floor, painted
- third brake light
- Tachometer
- Electronic Stability Program (ESP Plus)
- Front and rear aprons in black
- Transmission: 8-speed automatic
- Grab handle in the first row of seats, passenger side
- Air conditioning, front with particle and odor filter
- Steering column, adjustable for reach and height
- Rear fog lights with integrated reversing lights
- Wheels: Steel wheels 7 J x 16 with wheel hub cover
- Side impact protection
- Visibility equipment
- Sun visors, driver and passenger
- 12-volt power outlet in the center console
- Traction control with engine and brake intervention (TC Plus)
- Doors: Rear wing doors, sheet metal with a 180° opening angle
- Electronic immobilizer
- Central locking with remote control
- Ignition keys (2), both foldable
- ABS including brake assist and adaptive brake light
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Exterior mirror housings in black
- Sheet metal insert, driver's side in the 2nd row of seats
- On-board computer
- Diesel particulate filter, maintenance-free
- Three-point seat belts in all seats
- Electric front windows
- Speed controller and limiter
- Halogen headlights with daytime running lights
- Glove compartment closed at the top
- Paint finish: Solid color paint
- Fatigue detection level 1 coffee break
- Upholstery: Fabric / faux leather with grey dashboard underside
- Speed-sensitive power steering
- Seats: Comfort driver and comfort passenger seats
- Start/Stop System
- 12V power outlet in the cargo area and in the lower glove compartment
- Partition wall: closed, without windows
- Doors: Sliding door, passenger side
- Lashing eyes (8) in the cargo area
- Heat-insulating glazing, tinted
- Payload increased by +400 kg

Extra equipment

- 180° panoramic reversing camera (displays the area behind the vehicle up to 180 degrees, including steering guidelines, when reverse gear is engaged, on the color display of the infotainment system.)
- Front seat heating
- Package: Driver Assistance Package 1 (High Beam Assist - Driver Alert System with Camera Monitoring - Lane Keeping Assist - Traffic Sign Recognition with Intelligent Speed Control - Solar Reflect Windscreen)
- Steering wheel: Multifunction leather steering wheel
- Trailer hitch
- Wheels: Spare wheel, steel
- Park pilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards - blind spot warning - electrically folding exterior mirrors - fog lights)
- Radio: Multimedia Navi Pro with 7" color touchscreen display and voice control for audio, telephone and navigation (automatic music recognition (title, album, artist, cover) for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth interface, up to 10 mobile phones can be paired, image display via USB interface, navigation system with integrated memory, OpelConnect with telematics services, map of Europe, 3D map display, TMC GPS module, smartphone integration via Apple CarPlay and Android Auto, 1 USB interface, dual tuner, graphic equalizer)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim (Rechts) - Scratched - Loss in value
2	Trim / covers	Boot lid - interior trim (Links) - Scratched - Loss in value
3	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Loss in value
4	Boot lid / rear door	Rear door - left side (Innen) - Dent / paintcoat damage - Loss in value
5	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
6	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Loss in value
7	Front bumper	Front bumper (unpainted) - Scratch(es) - Loss in value
8	Interior	Cargo area floor - Scratch(es) - Loss in value
9	Front bumper	Front bumper (Lackabplatzer) - Paint defect - Paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - dent(s) - No deduction
2	Documents	Service book - Incomplete - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Roof, Front, Provided by user / customer, from 8 Feb 2023	3.438,47 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Wartungshistorie gemäß Auftraggeber Informationen.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Trim / covers: Boot lid - interior trim (Rechts) - Scratched - Loss in value



Damage 1: Trim / covers: Boot lid - interior trim (Rechts) - Scratched - Loss in value



Damage 2: Trim / covers: Boot lid - interior trim (Links) - Scratched - Loss in value



Damage 2: Trim / covers: Boot lid - interior trim (Links) - Scratched - Loss in value



Damage 3: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Loss in value



Damage 3: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Loss in value



Damage 3: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Loss in value



Damage 3: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Loss in value



Damage 4: Boot lid / rear door: Rear door - left side (Innen) - Dent / paintcoat damage - Loss in value



Damage 4: Boot lid / rear door: Rear door - left side (Innen) - Dent / paintcoat damage - Loss in value



Damage 4: Boot lid / rear door: Rear door - left side (Innen) - Dent / paintcoat damage - Loss in value



Damage 5: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value




Damage 6: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 7: Front bumper: Front bumper (unpainted) - Scratch(es) - Loss in value



Damage 7: Front bumper: Front bumper (unpainted) - Scratch(es) - Loss in value



Damage 7: Front bumper: Front bumper (unpainted) - Scratch(es) - Loss in value



Damage 8: Interior: Cargo area floor - Scratch(es) - Loss in value



Damage 8: Interior: Cargo area floor - Scratch(es) - Loss in value




Damage 9: Front bumper: Front bumper (Lackabplatzer) - Paint defect - Paint



Damage 9: Front bumper: Front bumper (Lackabplatzer) - Paint defect - Paint



Damage 9: Front bumper: Front bumper (Lackabplatzer) - Paint defect - Paint



Wear and tear 2: Documents: Service book - Incomplete - No deduction



Wear and tear 2: Documents: Service book - Incomplete - No deduction