# Tesla

VIN: LRW3E7EB2NC606680

Estimated repair cost

1,175.00 EUR
TOTAL



## Description

| | | |
|---|---|---|
| **Registration number**<br>2GNC747 | **First registration date**<br>- | **Odometer**<br>48637 km |
| **Color**<br>- | **Model year**<br>- | **Upholstery**<br>- |
| **Number of doors**<br>- | **Number of seats**<br>- | **Generation**<br>- |

## Statement details

**Inspection loc**
PARC LIZY

## Control

**Detected issues**

| | | | |
|---|---|---|---|
| Engine / Sound | ✓ Ok | Vehicle leak proofness | ✓ Ok |
| Exhaust / Clarity | ✓ Ok | | |

## Defects & corrections

| # | Element | Defect | Correction | net cost |
|---|---|---|---|---|
| 001 | Interior tailgate lining / -<br>Trim material : Plastic | Scratched | Smart repair | 68.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | **68.00 EUR** |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

| | | | | |
|---|---|---|---|---|
| 002 | Rim / Front Left<br>Material : Aluminium alloy / Rim/Tyre diameter : 19 " / Surface : Painted | Scratched | Smart repair | 165.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | **165.00 EUR** |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 003 | Rear-view mirror / Left | Scratched | Smart repair | 30.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | **30.00 EUR** |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 004 | Door sill / Front Left | Scratched | Acceptable | - |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | - |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 005 | Door / Front Left<br>Material : Metal / Windowed : Yes | Scratched | Acceptable | - |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | - |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 006 | Door / Back Left<br>Material : Metal / Windowed : Yes | Scratched | Acceptable | - |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | - |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 007 | Seat back plastic trim / Front Left<br>Trim material : Plastic | Scuff | Smart repair | 68.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | **68.00 EUR** |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 008 | Rim / Back Left<br>Material : Aluminium alloy / Rim/Tyre diameter : 19 " / Surface : Painted | Scratched | Smart repair | 165.00 EUR |

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | 165.00 EUR |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 009 | Rim / Back Right<br>Material : Aluminium alloy / Rim/Tyre diameter : 19 " / Surface : Painted | Scratched | Smart repair | 165.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | 165.00 EUR |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 010 | Wing / Back Right<br>Material : Metal / Windowed : Yes | Dent | Smart repair | 49.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | 49.00 EUR |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 011 | Rim / Front Right<br>Material : Aluminium alloy / Rim/Tyre diameter : 19 " / Surface : Painted | Scratched | Smart repair | 165.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| - | - | - | 165.00 EUR |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| - | - | - | |

| | | | | |
|---|---|---|---|---|
| 012 | Tyre / Front Right<br>Speed symbol : Y / Load index : 96 / Tyre Brand : PIRELLI / Width : 235 mm / Anti-puncture technology : None / Aspect ratio : 40 / Rim/Tyre diameter : 19 " / Season : All-season | Tear | Replace | 300.00 EUR |



| Bodywork time | Paint time | Part Price | Lumpsum |
|---|---|---|---|
| 0.50 h | - | 262.50 EUR | - |
| **Bodywork cost** | **Paint cost** | **MaterialCost** | |
| 37.50 EUR | - | - | |

## Loose Items

- [x] Quick charging cable (Type 2, Mode 3)
- [x] Registration certificate owner
- [x] Registration certificate
- [x] Triangle
- [x] User manual
- [x] Spare Key
- [x] First aid kit
- [x] Charging cable bag

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

## Main set of tyres

| | | | |
|---|---|---|---|
| **Front Left** | PIRELLI | 235/40/19 96 Y<br>All-season | 5 mm |
| **Front Right** | PIRELLI | 235/40/19 96 Y<br>All-season | 5 mm |
| **Back Left** | PIRELLI | 235/40/19 96 Y<br>All-season | 4 mm |
| **Back Right** | PIRELLI | 235/40/19 96 Y<br>All-season | 4 mm |

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

## Pictures



Front left




Rear left



Boot opened



Rear right



Rear passenger compartment




Dashboard from rear seat



Front passenger compartment



Front right




Odometer



Cable




Vin




Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Other



Interior tailgate lining / - / Scratched



Interior tailgate lining / - / Scratched



Interior tailgate lining / - / Scratched




Rim / Front Left / Scratched




Rim / Front Left / Scratched




Rim / Front Left / Scratched




Rear-view mirror / Left / Scratched




Rear-view mirror / Left / Scratched




Door sill / Front Left / Scratched



Door sill / Front Left / Scratched



Door / Front Left / Scratched




Door / Front Left / Scratched



Door / Back Left / Scratched




Door / Back Left / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Door / Back Left / Scratched




Seat back plastic trim / Front Left / Scuff



Seat back plastic trim / Front Left / Scuff



Seat back plastic trim / Front Left / Scuff



Rim / Back Left / Scratched




Rim / Back Left / Scratched




Rim / Back Left / Scratched




Rim / Back Left / Scratched



Rim / Back Right / Scratched




Rim / Back Right / Scratched




Rim / Back Right / Scratched




Rim / Back Right / Scratched



Wing / Back Right / Dent



Wing / Back Right / Dent




Wing / Back Right / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Rim / Front Right / Scratched




Rim / Front Right / Scratched




Rim / Front Right / Scratched




Rim / Front Right / Scratched




Rim / Front Right / Scratched



Tyre / Front Right / Tear



Tyre / Front Right / Tear

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.