TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48447868
Order No. / Reference: 27249255
Inspection date: 27 Oct 2026

Manufacturer: Opel	Model: Corsa 1.5 Diesel Start/Stop Elegance
VIN: VXKUBYHTKP4123511	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Corsa 1.5 Diesel Start/Stop Elegance	
Vehicle Identification number	VXKUBYHTKP4123511
Mileage (Read)	137,574 km
First registration	25 Sept 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	75 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Car hatchback
Colour / colour code	Voltaik Blau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Blue-Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	9 Monat(e)
Last service on / at	07/2026 at 126,005 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS852799
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ABW 00230		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,660 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/55 R16 91V	All-season tyres on Light alloy	Nokian	6mm / 6mm
2)	195/55 R16 91V	All-season tyres on Light alloy	Nokian	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Front airbags, driver and front passenger
- Airbag: Side airbag for driver and front passenger side
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- On-board computer
- Diesel particulate filter (DPF) maintenance-free
- Electronic brake force distribution (EBD)
- Driver information display 7", color
- Front collision warning system with automatic emergency braking and pedestrian detection
- Transmission: 6-speed manual transmission
- rear window wiper
- Air conditioning (manual recirculation - rear footwell heating)
- LED headlights (LED daytime running lights - high beam assist - LED turn signals in exterior mirrors)
- Steering column, height and reach adjustable
- Center armrest with storage compartment in front
- Opel Connect
- Upholstery: Imagination fabric, dark blue
- Wheels: Tire repair kit (tire sealant - 12 Volt compressor (without jack))
- Visibility equipment
- Seats: Comfort driver's seat
- Lane Keeping Assist
- 12V power outlet in the center console, front
- Ambient lighting
- Pre-installation for ISOFIX child seat mounting system
- Heat-insulating glazing, tinted
- Central locking: 2 ignition keys, one of which is foldable
- Adaptive brake light
- Airbag: Front and rear head airbags
- Anti-lock braking system (ABS)
- Exterior mirror housings in black
- Hill Start Assist
- third brake light
- Tachometer
- Electronic Stability Program Plus (ESP Plus)
- Electric windows front and rear
- Pedestrian protection
- Intelligent speed control and limiter
- Back window, heater
- Child safety lock in the rear doors, manual
- Headrests (5)
- LED daytime running lights
- Steering wheel made of vegan synthetic leather, flattened at the bottom
- Makeup mirror
- Fatigue detection
- Pollen filter
- Quickheat rapid heating system
- Power steering
- Seat belts: Three-point seat belts in all seats
- Seats: Comfort passenger seat
- Seats: Rear seat backrest split 60:40, foldable
- Start/Stop System
- Traction Control (TC) Plus
- Traffic sign recognition
- Pre-wiring for child seat mounting system "ISOFIX"
- Central locking with remote control

Extra equipment

- Paint finish: Metallic
- Park & Go Plus (180-degree panoramic reversing camera - Park Pilot, front and rear parking aid with audiovisual warning - blind spot warning and side protection - electrically folding exterior mirrors)
- Wheels: Alloy wheels 6.5 J x 16 in 4-twin-spoke design in silver (all-weather tires 195/55 R16)
- Heated seats for driver and front passenger (multi-stage adjustable)
- Navigation system: Multimedia navigation system with 7" color touchscreen display (multimedia radio, automatic music recognition, Bluetooth hands-free system, Apple CarPlay, Android Auto, voice control, 1 USB port, DAB+, steering wheel remote control, navigation system with integrated memory, road map of Europe (including Russia and Turkey), 3D map display, dynamic route guidance, display of points of interest, tour planning, GPS module)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Empty - Replace
2	Side panel - rear right side	Side panel - dent(s) - Smart repair

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side right, Provided by user / customer, from 28 Jun 2024	4.454,16 €

Repainting

No.	Repainting
1	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - front right side	170 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig


Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Damage 1: Equipment: Tirefit filler - Empty - Replace



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smart repair



Repainting 1: Door - front right side



Repainting 1: Door - front right side