TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48006518
Order No. / Reference: 26879481
Inspection date: 8 Oct 2026

Manufacturer: Seat	Model: Alhambra 1.4 TSI S&S OPF STYLE
VIN: VSSZZZ7NZNV500938	





Vehicle details

Manufacturer / Type / Model / Equipment	
Seat Alhambra 1.4 TSI S&S OPF STYLE	
Vehicle Identification number	VSSZZZ7NZNV500938
Mileage (Read)	62,019 km
First registration	2 Nov 2021
Number of holders	1
Next periodical technical inspection	11/2026
(Report not on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	1,395 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Atlantic Blau Metallic
Doors / Seats	5 / 7
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Re-import	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	20,400 km
Last service on / at	11/2025 at 52,421 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG143672
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	7593 / AFJ 00226		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,450 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 95V	Summer tires (with run-flat tires) on Light alloy	Continental	4mm / 4mm
2)	215/60 R16 95V	Summer tires (with run-flat tires) on Light alloy	Continental	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 95H	Winter tires (with run-flat tires) on Light alloy	Pirelli	3mm / 3mm
2)	215/60 R16 95H	Winter tires (with run-flat tires) on Light alloy	Pirelli	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- Storage compartments
- Airbag: Driver's side knee airbag system
- Airbag: Side airbag for driver and front passenger
- Exterior mirror housings in body color
- Outdoor temperature display
- LED turn signals integrated into the side of the exterior mirrors
- Roof rails, black
- Electronic Stability Program (ESP) with counter-steering support
- luggage compartment cover
- Cruise control system
- LED taillights
- rear window wiper
- Interior mirror automatically dimming
- Use of instruments
- Electric child safety lock for the rear doors
- "Climatronic" air conditioning system with 3 climate zones
- Front headrests (2) are height adjustable
- Steering wheel: Three-spoke leather steering wheel with multifunction controls
- Front center armrest with storage box
- Fatigue detection
- Fog lights with cornering light function
- Package: Smoker's Package
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- Rear view camera
- Sliding doors at the rear left and right
- Seat belts: 3 three-point automatic in the rear
- Seats: 3 individual seats in the 2nd row
- Seats: Front passenger seat backrest can be folded down completely
- Sunshade roller blind on the rear door windows
- Lane departure warning system
- 12V socket
- Bag hooks in the luggage compartment
- Ultrasonic parking aid, front and rear
- Traffic sign recognition
- Lashing eyes in the luggage compartment
- Warning light for unclosed doors and luggage compartment
- Driver and passenger side airbags
- Airbag: Head airbag system for front and rear passengers
- Electrically adjustable, heated and folding exterior mirrors with ambient lighting,
- Lighting
- third brake light
- Chrome interior applications
- Electronic parking brake
- Automatic headlight control
- Electric windows front and rear
- luggage compartment floor
- Transmission: 6-speed manual
- Heated rear window
- Interior lights front and rear with delayed shut-off
- Instrument lighting
- ISOFIX child seat restraint system, triple in the 2nd row of seats
- Comfort turn signals
- Rear headrests (3)
- Steering column with height and reach adjustment
- Illuminated makeup mirrors in the sun visors
- Multifunction display with color screen
- Navigation system
- Otto particulate filter
- Upholstery: Cloth
- Rain sensor
- Wheels: Alloy wheels (4) 6.5 J x 16" "Design"
- Side and rear windows with heat-insulating glazing
- Power steering
- Seat belts: Three-point automatic front belts, height-adjustable
- Seats: Driver's seat with electric backrest adjustment
- Seats: Front seats with height adjustment and lumbar support
- Start-stop system with brake energy recuperation
- Daytime running light
- Blind spot assist
- Front Assist area monitoring system with City Emergency Braking function
- Automatic hazard warning lights during emergency braking
- Electronic immobilizer
- Central locking including tailgate with remote control

Extra equipment

- Airbag: Rear side airbags
- Paint finish: Metallic paint
- Package: Luggage compartment package (luggage net - net partition - rails on side walls with tension strap (fixable))
- Package: Technology Package (Exterior mirrors with passenger-side mirror lowering function - 230V socket, on the rear center console)
- Parking assist (including ultrasonic parking aid front and rear)
- Side windows from the 2nd row of seats and rear window are dark tinted.
- Xenon lights: Bi-Xenon with cornering lights (with dynamic headlight range control - headlight cleaning system)
- Swiveling towbar with electric release
- Package: Business COMFORT (Automatic distance control - High beam assist - External antenna connection in the storage compartment of the center armrest - DAB+ - Full Link - Android Auto - Apple CarPlay - Anti-theft alarm system with interior monitoring including backup horn and tow-away protection)
- Package: Winter Package (Headlight cleaning system - Heated front windshield washer nozzles - Heated front seats)
- Seats: 7 seats (3 individual seats in the 2nd row - 2 individual seats in the 3rd row - Easy-Entry access aid - warning tone for unfastened seat belts)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
2	Door - front right side	Door - Dent / paintcoat damage - Smart repair
3	Front bumper	Front bumper - Scratched - Repair and paint
4	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
5	Rear bumper	Rear bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Door - front left side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 20 Oct 2025	1.834,94 €

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der beiliegende Radsatz ist nicht Bestandteil der vorliegenden Fahrzeugausstattung.

- Wartungshistorie gemäß Auftraggeber Informationen.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 2: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 2: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 3: Front bumper: Front bumper - Scratched - Repair and paint




Damage 3: Front bumper: Front bumper - Scratched - Repair and paint




Damage 3: Front bumper: Front bumper - Scratched - Repair and paint



Damage 3: Front bumper: Front bumper - Scratched - Repair and paint



Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint