MACADAM










SKODA OCTAVIA COMBI: GM-571-YP

Vinnumber:	**TMBJG8NXXPY052705**	Versionname:	**SKODA OCTAVIA COMBI 2.0 TDI 116 DSG7 Ambition VF [5P] 7-116CH-6cv (break)**
First Registrationdate:	**27/03/2023**	Fiscalpower:	
Expertise Mileage:	**158839**	Power Kw:	**85**
Bodytype:	**Break**	Body colour	**Light Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Dark Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Steering wheel leather			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/60/16/92 V**			
	Fr.L.	**Goodyear: 30%**	Fr.R.	**Goodyear: 35%**
	Re.L.	**Goodyear: 45%**	Re.R.	**Goodyear: 50%**

Tyre profile depth FL	**6.2**
Tyre profile depth FR	**6.0**
Tyre profile depth RL	**5.2**
Tyre profile depth RR	**5.0**
Tyre size FL	**205/60 R 16 92 V**
Tyre size FR	**205/60 R 16 92 V**
Tyre size RL	**205/60 R 16 92 V**
Tyre size RR	**205/60 R 16 92 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Seat cover FL, Stain, Cleaning




Outside rear-view mirror housing R, Scratch(es), Acceptable




Bumper R, Scratch(es), Paint











ALPHABET

Historique Maintenance

Immatriculation: **GM-571-YP** Date de 1ère immatriculation: **27/03/2023**

Modèle: **Skoda OCTAVIA COMBI 2.0 TDI 116 DSG7 Ambition VF [5P] 7-116CH-6cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
09/06/2026	145.357	GAMBETTA SPORT AUTO	LIQUIDE DE FREIN
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			REVISION
31/03/2026	132.900	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS ETE
			REMPLACEMENT PNEUS ETE
31/10/2025	116.817	ESPACE 3000	DISQUES PLAQUETTES AR RPLT
			REVISION ET CLIM
			DISQUES PLAQUETTES AV RPLT
			SELECTEUR DE BV RPLT
28/10/2025	116.738	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS HIVER
			PERMUTATIONS PNEUS
11/04/2025	86.238	ESPACE 3000	REVISION
			BALAIS ESSUIE GLACE AV
			LIQUIDE DE FREIN
26/08/2024	56.193	ESPACE 3000	PLAQUETTES AR RPLT
			REVISION
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			PLAQUETTES AV RPLT
12/03/2024	25.889	ESPACE 3000	REVISION
06/11/2023	8.964	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS HIVER