MACADAM











Mercedes Sprinter (Segm. B3): 2DWP545

Vinnumber:	**W1VGFBFZ8RP601345**	Versionname:	**Sprinter 311 Functional L2 2.0CDi 114pk/cv FWD**
First Registrationdate:	**17/07/2023**	Fiscalpower:	
Expertise Mileage:	**40146**	Power Kw:	**84**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Diesel**		
Maintenance	**OK**		
Maintenance	**ass B plus 297 d**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/65/16/110 R**			
	Fr.L.	**Vredestein: 8 mm**	Fr.R.	**Vredestein: 5 mm**
	Re.L.	**Continental: 4 mm**	Re.R.	**Continental: 5 mm**

Tyre profile depth FL	**8.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**225/65 R 16 110 R**
Tyre size FR	**225/65 R 16 110 R**
Tyre size RL	**225/65 R 16 110 R**
Tyre size RR	**225/65 R 16 110 R**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**2480**
Tyre make FR	**2480**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Seat cover FL, Stain, Cleaning





Bumper F, Scratch(es), Acceptable





Central pillar L, Dent(s), Acceptable




Wheel aperture RL, Scratch(es), Acceptable




Wheel aperture RR, Scratch(es), Acceptable




Boot door lining L, Scratch(es), Replace




Boot door lining R, Scratch(es), Replace




Rear light L, Broken, Replace




Bumper R, Scratch(es), Acceptable






Boot door panel RR, Dent(s), Paintless dent repair





Wing RR, Dent(s) and scratch(es), Repair and paint (complete)







Bodywork, Not original part, Check





Onderhoudshistorie van: W1VGFBFZ8RP601345

ALPHABET

Kenteken	2DWP545
Merk Model	Mercedes Sprinter 311 Functional L2 2.0CDi 114pk/cv FWD
Brandstofsoort	Diesel
Datum deel1	7/17/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/17/25	21,464	ad blue bijvullen	Bijvullen/-laden
7/17/25	21,464	klein materiaal	
7/17/25	21,464	mercedes assyst a	Uitvoeren
7/17/25	21,464	remvloeistof	Vervangen
7/17/25	21,464	ruitenwisserrubber vooraan	Vervangen
7/17/25	21,464	stoffilter (motor compartiment)	Vervangen
7/17/25	21,464	tech. keuring: nazicht/tijdens onderhou	Uitvoeren