TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

# Expertise

Protocol number: 48582333
Order No. / Reference: 27157075
Inspection date: 3 Nov 2026

| | |
|---|---|
| Manufacturer: Mercedes-Benz | Model: C 200 4Matic 9G-TRONIC |
| VIN: W1KAF4DB1PR154492 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Mercedes-Benz C 200 4Matic 9G-TRONIC | |
| **Vehicle Identification number** | W1KAF4DB1PR154492 |
| **Mileage** (Read) | 132,913 km |
| **First registration** | 5 Sept 2023 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** | 09/2028 |
| (Report on hand) | |
| **Fuel type** | Hybrid Petrol / E |
| **Engine displacement / Cylinder** | 1,496 ccm / 4 |
| **Power** | 150 kW |
| **Gearbox / Number of gears** | Automatic / 9 |
| **Type of drive** | All-wheel drive |
| **Type of vehicle** | Saloon car |
| **Colour / colour code** | Schwarz |
| **Doors / Seats** | 4 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 255 Tag(e) |
| **Last service on / at** | 07/2026 at 123,310 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GV752911 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | No |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 2222 / AYE 00153 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,320 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/50 R17 98Y | Summer tyres on Light alloy | Bridgestone | 3mm / 3mm |
| 2) | 225/50 R17 98Y | Summer tyres on Light alloy | Bridgestone | 3mm / 3mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/50 R17 98H | Winter tyres on Light alloy | Pirelli | 5mm / 5mm |
| 2) | 225/50 R17 98H | Winter tyres on Light alloy | Pirelli | 5mm / 5mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Airbag for driver and front passenger
- Airbag: Center airbag
- Airbag: Windowbag for driver and front passenger
- Left and right exterior mirrors are heated and electrically adjustable
- Double cup holder at the front
- ECO start/stop function
- Chassis: AGILITY CONTROL chassis with selective damping system and lowered suspension
- Velour floor mats
- Transmission: 9-speed automatic, 9G-TRONIC
- Interior headliner fabric crystal grey
- KEYLESS-GO start function
- THERMATIC automatic climate control with 1 climate zone (controlled via the central display or the climate control unit in the center console) - Sensor system for detecting, for example, interior/ exterior temperature, solar radiation, humidity and dew point - Ventilation system consisting of: 3 center vents in the center area and 2 side vents, 2 ventilation openings each in the footwell for driver and front passenger - Fine dust filter for filtering dust, soot and pollen - Dew point sensor, continuous defroster vent under the windshield and 2 fixed defroster vents)
- Steering wheel: Multifunction sports steering wheel in leather
- Mercedes-Benz emergency call system
- Otto particulate filter
- Package: Interior lighting package
- Radio: Extended MBUX functions
- Radio accessories: Digital radio (DAB)
- Radio accessories: Central display
- Tire pressure monitoring system (TPMS)
- Windscreen wipers with rain sensor
- Lane Keeping Assist, active
- High-visibility vest for drivers
- Central locking with remote control
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- 4MATIC all-wheel drive
- Basic services
- Brake assist, active
- DYNAMIC SELECT
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Front bumper painted in body color
- Speed Limit Assistant
- Rear bumper with diffuser-look insert, black grained
- ISOFIX child seat attachment with top tether in the rear
- Mechanical child safety lock for the rear doors
- Rear headrests (3)
- Front headrests
- Paint finish: Solid
- LED High Performance headlights (The elements of the LED High Performance headlights: - Torch and trifunctional light guide for daytime running lights, position lights and turn signals - Multi-chamber reflector system with 4 individual reflectors each) for low beam and high beam. The elements of the rear lights in LED technology: - All light functions in full LED technology - Tail light - Brake light and parking light - Rear fog light (only on the left side) - Turn signals - Reversing light - 3rd brake light)
- Center console in high-gloss black
- Package: Storage
- Upholstery: Fabric Tandel
- Radio: MBUX
- Radio accessories: Communication module (LTE) for using Mercedes me connect services
- Remote Services Plus
- Seats: Rear seat backrests foldable
- Cruise control
- Electronic immobilizer
- Decorative elements, base foil, instrument panel

### Extra equipment

- Airbag: Side airbags in the rear
- Package: Advanced Light Package (DIGITAL LIGHT: -HD system with projection module (more than 1.3 million pixels per headlight) and MULTIBEAM LED background module -Adaptive Highbeam Assist Plus -ULTRA RANGE high beam with a range of more than 600 m -Topography compensation -Cornering light with roundabout and intersection function -Active curve light with predictive control -Extended fog light, city light, country road light, motorway light, motorway high beam and bad weather light)
- Package: Infotainment package (MBUX Navigation Premium (hard drive navigation, pre-installation for Live Traffic Information), traffic sign assistant, smartphone integration (connects the mobile phone wirelessly to the multimedia system via Apple CarPlay and Android Auto))
- Package: Comfort Package (heated seats for driver and front passenger - 4-way lumbar support)
- Package: Mirror package (both exterior mirrors electrically folding (button in the driver's door control panel) - interior mirror and exterior mirror on the driver's side automatically dimming continuously - ambient lighting of the exterior mirror to illuminate the entry area with projection of the Mercedes-Benz logo)
- Wheels: 43.2 cm (17") light alloy wheels in 5-spoke design (black painted and polished with 225/50 R 17 on 7 J x 17 ET 44.5)
- Wheels: Complete winter wheel sets fitted at the factory
- Sunroof: Electric panoramic sunroof
- Heat-insulating dark tinted glass
- Fuel tank with larger capacity
- Package: Assistance (Blind Spot Assist: The system can warn you of side collisions with other road users in your blind spot, especially as soon as you activate the turn signal. Even after driving, the system remains vigilant and warns you if you open the door at the wrong moment. An important safety feature – especially for cyclists.)
- Package: AVANTGARDE Exterior (radiator grille with integrated Mercedes star and a chrome-plated louvre, radiator grille frame in chrome - 43.2 cm (17") 5-spoke alloy wheels, high-gloss black paint and gloss coating, 225/50 R 17 on 7 J x 17 ET 44.5 - Dynamic front bumper with centrally positioned trim strip in high-gloss chrome and diamond-pattern air intakes in black. - AGILITY CONTROL suspension with 15 mm lowering and selective damping system. - Strip on the rear side windows in high-gloss black.)
- Package: Parking (12 ultrasonic sensors - reversing camera - Active Parking Assist with PARKTRONIC: detects free parking spaces, assisted parking, visual and acoustic warning, display of camera and ultrasonic data in the media display - Cross traffic warning: can provide visual and acoustic warnings when reversing out of a parking space and, if necessary, automatically initiate emergency braking - Reverse maneuvering brake: can trigger a braking process - Drive-away assist)
- Wheels: Winter complete set of M+S wheels, 4-way 43.2 cm (17") light alloy wheels with 10-twin-spoke design (vanadium silver painted with 225/50 R 17 on 7 J x 17 ET 44, 5.)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Seat - rear | Back seat - Soiled - Clean |
| 2 | Door - rear left side | Door - dent(s) - Smooth repair work |
| 3 | Door - front right side | Door - dent(s) - Smooth repair work |
| 4 | Wheel / tyres | Tyre - front left side (Ausriss aus der Lauffläche) - Damaged - Replace |
| 5 | Boot lid / rear door | Boot lid - Scratch(es) - Paint |
| 6 | Rear bumper | Rear bumper - Scratched - Paint |
| 7 | Door - front left side | Door edge - Scratch(es) - Paint |
| 8 | Front bumper | Front bumper (& Lackschaden) - Deformed - Paint |
| 9 | Side panel - rear left side | Side panel - Dent / paintcoat damage - Repair and paint |
| 10 | Side panel - rear right side | Side panel (Kniestück) - Dent / paintcoat damage - Repair and paint |
| 11 | Vehicle glazing | Windscreen (Mit Rissbildung im Fahrersichtfeld) - Stone chips - Replace |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Bonnet | Bonnet - Stone chips - No deduction |
| 2 | Mudguard - right side | Mudguard - right side - Scratch(es) - No deduction |
| 3 | Door - rear right side | Door edge - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

| Description |
|---|
| Documents - Log book |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)




**Figure 5:** Interior - front



**Figure 6:** Interior - rear



**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel



**Figure 9:** Cargo area




**Figure 10:** VIN



**Figure 11:** Mounted tyres




**Figure 12:** Documents




**Figure 13:** Documents




**Figure 14:** Documents



**Figure 15:** Additional tyres





**Figure 16:** Navigation




**Figure 17:** Misc.




**Figure 18:** Misc.



**Figure 19:** Misc.



**Figure 20:** Misc.



**Figure 21:** Misc.



**Figure 22:** Misc.



**Figure 23:** Misc.



**Figure 24:** Misc.



**Figure 25:** Misc.



**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.




**Figure 29:** Misc.



**Figure 30:** Misc.



**Figure 31:** Misc.



**Figure 32:** Misc.




**Figure 33:** Misc.



**Figure 34:** Misc.



**Damage 1:** Seat - rear: Back seat - Soiled - Clean



**Damage 1:** Seat - rear: Back seat - Soiled - Clean



**Damage 2:** Door - rear left side: Door - dent(s) - Smooth repair work



**Damage 2:** Door - rear left side: Door - dent(s) - Smooth repair work



**Damage 3:** Door - front right side: Door - dent(s) - Smooth repair work



**Damage 3:** Door - front right side: Door - dent(s) - Smooth repair work




**Damage 4:** Wheel / tyres: Tyre - front left side (Ausriss aus der Lauffläche) - Damaged - Replace



**Damage 4:** Wheel / tyres: Tyre - front left side (Ausriss aus der Lauffläche) - Damaged - Replace



**Damage 4:** Wheel / tyres: Tyre - front left side (Ausriss aus der Lauffläche) - Damaged - Replace



**Damage 5:** Boot lid / rear door: Boot lid - Scratch(es) - Paint



**Damage 5:** Boot lid / rear door: Boot lid - Scratch(es) - Paint




**Damage 5:** Boot lid / rear door: Boot lid - Scratch(es) - Paint




**Damage 6:** Rear bumper: Rear bumper - Scratched - Paint



**Damage 6:** Rear bumper: Rear bumper - Scratched - Paint



**Damage 6:** Rear bumper: Rear bumper - Scratched - Paint




**Damage 6:** Rear bumper: Rear bumper - Scratched - Paint




**Damage 6:** Rear bumper: Rear bumper - Scratched - Paint



**Damage 7:** Door - front left side: Door edge - Scratch(es) - Paint



**Damage 7:** Door - front left side: Door edge - Scratch(es) - Paint



**Damage 7:** Door - front left side: Door edge - Scratch(es) - Paint




**Damage 8:** Front bumper: Front bumper (& Lackschaden) - Deformed - Paint



**Damage 8:** Front bumper: Front bumper (& Lackschaden) - Deformed - Paint




**Damage 8:** Front bumper: Front bumper (& Lackschaden) - Deformed - Paint




**Damage 9:** Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




**Damage 9:** Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




**Damage 9:** Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



**Damage 10:** Side panel - rear right side: Side panel (Kniestück) - Dent / paintcoat damage - Repair and paint




**Damage 10:** Side panel - rear right side: Side panel (Kniestück) - Dent / paintcoat damage - Repair and paint



**Damage 10:** Side panel - rear right side: Side panel (Kniestück) - Dent / paintcoat damage - Repair and paint



**Damage 11:** Vehicle glazing: Windscreen (Mit Rissbildung im Fahrersichtfeld) - Stone chips - Replace



**Damage 11:** Vehicle glazing: Windscreen (Mit Rissbildung im Fahrersichtfeld) - Stone chips - Replace



**Damage 11:** Vehicle glazing: Windscreen (Mit Rissbildung im Fahrersichtfeld) - Stone chips - Replace




**Wear and tear 1:** Bonnet: Bonnet - Stone chips - No deduction




**Wear and tear 1:** Bonnet: Bonnet - Stone chips - No deduction




**Wear and tear 1:** Bonnet: Bonnet - Stone chips - No deduction



**Wear and tear 2:** Mudguard - right side: Mudguard - right side - Scratch(es) - No deduction



**Wear and tear 2:** Mudguard - right side: Mudguard - right side - Scratch(es) - No deduction



**Wear and tear 3:** Door - rear right side: Door edge - Scratch(es) - No deduction