TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48562438
Order No. / Reference: 27204510
Inspection date: 6 Nov 2026

Manufacturer: Skoda	Model: Enyaq iV 50
VIN: TMBJA9NY1NF027913	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Enyaq iV 50	
Vehicle Identification number	TMBJA9NY1NF027913
Mileage (Read)	15,168 km
First registration	10 Dec 2021
Number of holders	1
Next periodical technical inspection	12/2027
(Report on hand)	
Fuel type	Electric
Power	109 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	SUV
Colour / colour code	Energyblau
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	400 Tag(e)
Last service on / at	12/2025 at 12,677 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG203859
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AWQ 00003		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,470 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103T	Summer tyres on Steel rim with wheel cover	Bridgestone	5mm / 5mm
2)	235/60 R18 103T	Summer tyres on Steel rim with wheel cover	Bridgestone	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 107H	Winter tyres on Light alloy	Continental	7mm / 7mm
2)	235/60 R18 107H	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag, driver and passenger
- Airbag, front side airbags
- Traction control (ASR)
- Electrically adjustable and heated exterior mirrors
- Hill start assist
- Design Selection Studio (seat covers in black fabric - decorative strips "Grained")
- E-Sound (external speaker for generating a driving sound)
- ESC Electronic Stability Control
- Front radar assistant with pedestrian and cyclist detection and city emergency braking function
- Tinted windows
- rear window wiper
- Isofix anchorage on the outer rear seats including top tether
- Removable boot cover
- Paint finish: Solid
- LED headlights with daytime running lights
- LED taillights
- Steering wheel adjustable for height and reach
- Manual headlight range adjustment
- Radio accessories: SmartLink
- Tire Mobility Kit
- Wheels: 18" steel rims Andromeda AERO silver (8Jx18 tires 235/60 R18 103T)
- Seat belts
- Skoda Care Connect
- Lane keeping assistant (Lane Assist)
- Traffic sign recognition
- Central locking including remote control integrated into the key
- Airbag, center airbag front
- Airbag, front and rear head airbags
- Anti-lock braking system (ABS)
- Evasive steering assist including turn assist
- Outdoor temperature display
- Grey headliner
- Digital instrument cluster (Virtual Cockpit)
- Third brake light
- Electronic parking brake including auto-hold function
- Electric windows front and rear
- Cruise control
- Transmission: 1-speed (EV)
- Heated rear window
- Isofix anchorage on the front passenger seat
- Child safety locks on the rear doors
- Climatronic air conditioning (2-zone)
- Front and rear headrests are height-adjustable.
- Charging cable for AC charging stations (Mode 3 charging cable, Type 2, 16A) (Fast charging connector (CCS / Combo 2))
- Steering wheel: Leather steering wheel with multifunction buttons
- Radio accessories: Wireless SmartLink
- Tire pressure monitoring
- Rear seat backrest split 60:40, foldable
- Power steering
- Seats: Driver's seat height adjustable
- Speed limiter
- 12V socket - in the trunk
- Immobiliser

Extra equipment

- Package: Infotainment BASIC (Navigation system - Infotainment Online 3 years (Online map updates for navigation; display of weather data, news, headlines; charging station and parking space search))
- Reversible boot mat
- Airbag, rear side airbags
- Luggage net partition
- Mobile charging station "iV Universal Charger" with interchangeable connection adapters

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Equipment	Vehicle key (Abdeckung) - Loose - Repair
3	Rear bumper	Reflector - right side - Broken / torn - Replace
4	Equipment	Tirefit filler - Expired - Replace
5	Instrument panel	Indicator light (SOS Notruf, Zusatzkosten können entstehen) - Non-operational - Perform diagnosis
6	Trim / covers	D-pillar trim - interior, left side - Scratch(es) - Replace
7	Door - front right side	Door - Scratch(es) - Smart repair
8	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair
9	Door - front left side	Door - Dent / paintcoat damage - Smart repair
10	Trim / covers	Boot lid - interior trim - Scratched - Replace
11	Vehicle glazing	Rear window - Scratch(es) - Loss in value
12	Front bumper	Front bumper - Scratch(es) - Paint
13	Door - rear left side	Door - Scratch(es) - Paint
14	Bonnet	Bonnet (Lackeinätzung) - Paint defect - Paint
15	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Mudguard - left side	Mudguard - left side - Scratch(es) - No deduction
2	Door - rear right side	Door - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Interior - Separation net

Accident damages

No.	Accident
1	Rear, Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des
Auslieferungsumfangs.

- Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Damage 2: Equipment: Vehicle key (Abdeckung) - Loose - Repair



Damage 3: Rear bumper: Reflector - right side - Broken / torn - Replace



Damage 3: Rear bumper: Reflector - right side - Broken / torn - Replace



Damage 4: Equipment: Tirefit filler - Expired - Replace



Damage 5: Instrument panel: Indicator light (SOS Notruf, Zusatzkosten können entstehen) - Non-operational - Perform diagnosis



Damage 5: Instrument panel: Indicator light (SOS Notruf, Zusatzkosten können entstehen) - Non-operational - Perform diagnosis



Damage 6: Trim / covers: D-pillar trim - interior, left side - Scratch(es) - Replace



Damage 6: Trim / covers: D-pillar trim - interior, left side - Scratch(es) - Replace



Damage 7: Door - front right side: Door - Scratch(es) - Smart repair




Damage 7: Door - front right side: Door - Scratch(es) - Smart repair



Damage 7: Door - front right side: Door - Scratch(es) - Smart repair



Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair




Damage 8: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 9: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 9: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 9: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 10: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage 10: Trim / covers: Boot lid - interior trim - Scratched - Replace



Damage 10: Trim / covers: Boot lid - interior trim - Scratched - Replace




Damage 11: Vehicle glazing: Rear window - Scratch(es) - Loss in value




Damage 11: Vehicle glazing: Rear window - Scratch(es) - Loss in value




Damage 11: Vehicle glazing: Rear window - Scratch(es) - Loss in value



Damage 11: Vehicle glazing: Rear window - Scratch(es) - Loss in value



Damage 12: Front bumper: Front bumper - Scratch(es) - Paint




Damage 12: Front bumper: Front bumper - Scratch(es) - Paint




Damage 12: Front bumper: Front bumper - Scratch(es) - Paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint




Damage 14: Bonnet: Bonnet (Lackeinätzung) - Paint defect - Paint



Damage 14: Bonnet: Bonnet (Lackeinätzung) - Paint defect - Paint



Damage 15: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Replace



Damage 15: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Replace



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right



Accident 1: Rear, Side right