TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48008797
Order No. / Reference: 27031196-1
Inspection date: 6 Oct 2026

Manufacturer: Opel	Model: Zafira Life 2.0 D M Aut. Edition
VIN: VXEVEEHZ7NZ015735	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Zafira Life 2.0 D M Aut. Edition	
Vehicle Identification number	VXEVEEHZ7NZ015735
Mileage (Read)	143,850 km
First registration	26 Apr 2022
Number of holders	1
Next periodical technical inspection	04/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	130 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Diamant Schwarz Metallic
Doors / Seats	5 / 8
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	37,260 km
Last service on / at	07/2025 at 101,015 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ640297
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	3003 / BBA 00317		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Summer tyres on Light alloy	Michelin	3mm / 3mm
2)	225/55 R17 101V	Summer tyres on Light alloy	Michelin	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Winter tyres on Light alloy	Dunlop	7mm / 7mm
2)	225/55 R17 101V	Winter tyres on Light alloy	Dunlop	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Low beam automatically
- Airbag for driver and passenger side
- Airbag: Curtain airbags, in the 2nd and 3rd rows of seats
- Automatic activation of the hazard warning lights
- Exterior mirror housings in black
- On-board computer
- Diesel particulate filter
- Electronic Stability Program (ESP Plus)
- Electric front windows
- luggage compartment cover
- Glazed tailgate, with rear window wiper and heater
- Air conditioning
- LED daytime running lights
- Fog light
- Package: Driver Assistance Package 1
- Rear parking pilot
- Radio: Multimedia radio with 7" touchscreen color display
- Tire repair kit
- Wheels: Alloy wheels in bicolor, 7J x 17
- Side impact protection
- Power steering
- Safety steering column, height and length adjustable
- Heated seats for driver and front passenger
- Sun visors driver and passenger side
- Traction Control (TC) Plus
- Exterior door handles, in car color
- Central locking with remote control
- Storage compartments
- Airbag: Head airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Exterior mirrors, electrically adjustable, heated and folding
- Hill Start Assist
- third brake light
- Tachometer
- Window: Window, driver's side in the 2nd row of seats, fixed
- Transmission: 8-speed automatic transmission
- Child safety lock, mechanical
- Air conditioning: Auxiliary air conditioning, rear
- Headlight range adjustment, manual
- Rear fog lights with reversing lights
- Package: Driver Assistance Package 2
- Radio: Digital radio reception DAB+
- Rain sensor
- Tire pressure warning
- Sliding door trim with cover, in vehicle color
- Side protection strips in vehicle color
- Seat belts: Three-point seat belts in all seats
- Seats: 8 seats in fabric, Harlequin Black
- Solar Protect thermal insulation glazing
- 12V socket
- Door: Sliding door, driver and passenger side
- Immobiliser
- Ignition keys (2), both foldable

Extra equipment

- Detachable trailer hitch
- GK-HP
- Glazed tailgate with rear window wiper and heater (and separately opening window)
- IntelliGrip (Adaptive traction system with 5 selectable modes: - ESP off - ESP standard - Snow mode - Mud mode - Sand mode)
- Package: Innovation Package (Head-Up Display - Park Pilot, front and rear - 180° panoramic reversing camera - Blind Spot Warning - Multimedia Navi Pro with 7" touchscreen, voice control, Bluetooth, hands-free system, USB, Apple CarPlay, Android Auto, OpelConnect)
- Power outlet: 220/230V, in the second row of seats under the passenger seat
- Xenon headlights with LED daytime running lights
- Floor mats in the 2nd and 3rd rows of seats
- Electric handbrake
- Interior mirror, automatically dimming
- Interior mirror, additional, for interior monitoring
- Paint finish: Metallic
- Steering wheel: Multifunction leather steering wheel, flattened at the bottom
- Keyless locking and starting system Keyless Open & Start
- safety net
- Solar Protect heat-insulating glazing (extra dark tinted in the rear)
- Sunshades in the 2nd row of seats
- Socket: Conversion socket
- winter tires

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Engine	Engine - Leaking - Perform diagnosis
2	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
3	Side panel - rear right side	Side panel - Dent / paintcoat damage - Smart repair
4	Instrument panel	Indicator light (Motorkontrolle-nicht fahrbereit) - on - Perform diagnosis
5	Rear bumper	Rear bumper - Scratch(es) - Paint
6	Mudguard - left side	Mudguard - left side - Scratch(es) - Paint
7	Mudguard - right side	Mudguard - right side - Scratch(es) - Paint
8	Bonnet	Bonnet (Streusandeffekt) - Stone chips - Paint
9	Front bumper	Front bumper (Streusandeffekt) - Scratched - Paint
10	Sliding door - left side	Sliding door with glass panel - Scratch(es) - Paint
11	Sliding door, right	Sliding door with glass panel - Scratch(es) - Paint
12	Door - front left side	Door - Scratch(es) - Paint
13	Sill - left side	Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint
14	Side panel - rear left side	Side panel - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Log book (Inkl.aller Unterlagen)

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.




Damage 1: Engine: Engine - Leaking - Perform diagnosis



Damage 1: Engine: Engine - Leaking - Perform diagnosis



Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair




Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair




Damage 3: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair



Damage 4: Instrument panel: Indicator light (Motorkontrolle-nicht fahrbereit) - on - Perform diagnosis



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 6: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint




Damage 6: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint




Damage 6: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint




Damage 6: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 6: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint




Damage 7: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




Damage 7: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 7: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




Damage 7: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 7: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




Damage 7: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 8: Bonnet: Bonnet (Streusandeffekt) - Stone chips - Paint




Damage 8: Bonnet: Bonnet (Streusandeffekt) - Stone chips - Paint



Damage 8: Bonnet: Bonnet (Streusandeffekt) - Stone chips - Paint



Damage 8: Bonnet: Bonnet (Streusandeffekt) - Stone chips - Paint



Damage 8: Bonnet: Bonnet (Streusandeffekt) - Stone chips - Paint



Damage 8: Bonnet: Bonnet (Streusandeffekt) - Stone chips - Paint




Damage 9: Front bumper: Front bumper (Streusandeffekt) - Scratched - Paint




Damage 9: Front bumper: Front bumper (Streusandeffekt) - Scratched - Paint



Damage 9: Front bumper: Front bumper (Streusandeffekt) - Scratched - Paint




Damage 9: Front bumper: Front bumper (Streusandeffekt) - Scratched - Paint




Damage 9: Front bumper: Front bumper (Streusandeffekt) - Scratched - Paint




Damage 9: Front bumper: Front bumper (Streusandeffekt) - Scratched - Paint




Damage 10: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint




Damage 10: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint



Damage 10: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint




Damage 10: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint




Damage 10: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint




Damage 10: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint




Damage 10: Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint




Damage 11: Sliding door, right: Sliding door with glass panel - Scratch(es) - Paint




Damage 11: Sliding door, right: Sliding door with glass panel - Scratch(es) - Paint




Damage 11: Sliding door, right: Sliding door with glass panel - Scratch(es) - Paint




Damage 11: Sliding door, right: Sliding door with glass panel - Scratch(es) - Paint




Damage 11: Sliding door, right: Sliding door with glass panel - Scratch(es) - Paint




Damage 12: Door - front left side: Door - Scratch(es) - Paint




Damage 12: Door - front left side: Door - Scratch(es) - Paint




Damage 12: Door - front left side: Door - Scratch(es) - Paint




Damage 12: Door - front left side: Door - Scratch(es) - Paint



Damage 12: Door - front left side: Door - Scratch(es) - Paint



Damage 12: Door - front left side: Door - Scratch(es) - Paint



Damage 12: Door - front left side: Door - Scratch(es) - Paint



Damage 12: Door - front left side: Door - Scratch(es) - Paint




Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint




Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint



Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint



Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint



Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint



Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint



Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint



Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint



Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint




Damage 13: Sill - left side: Sill (vorne und hinten) - Dent / paintcoat damage - Repair and paint



Damage 14: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 14: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 14: Side panel - rear left side: Side panel - Scratch(es) - Paint



Wear and tear 1: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Wear and tear 1: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction