MACADAM










Volkswagen Crafter: VRK79P

Vinnumber:	**WV1ZZZSY7P9001419**	Versionname:	**Crafter 35 2.0 TDI 103kW FWD GB L3H3 automaat**
First Registrationdate:	**15/09/2022**	Fiscalpower:	
Expertise Mileage:	**254848**	Power Kw:	**103**
Bodytype:		Body colour	**Candywit**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Diesel**	Parking lot	**1189**
Number of seats	**2**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**Yes**		

Options

Number of keys total	**1**	Rear parking sensors	
Manual climate control		Sliding door right-side	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 75 / 16 / 110 / R / Steel	1,4 mm	Continental	All season
	Right	205 / 75 / 16 / 110 / R / Steel	2,0 mm	Continental	All season
Rear	Left	205 / 75 / 16 / 110 / R / Steel	5,4 mm	Continental	All season
	Right	205 / 75 / 16 / 110 / R / Steel	4,4 mm	Continental	All season

Assistance equipment

Service, Maintenance, Execute



Ignition key, Missing, Replace

No pictures to display

Armrest F M, Worn, Replace




Outside rear-view mirror housing L, Scratch(es), Replace





Door FL, Dent(s) and scratch(es), Repair and paint (complete)








Side wall FL (LCV), Dent(s), Repair and paint (complete)





Side bar L, Scratch(es), Replace






Side wall RL, Dent(s), Repair and paint (complete)





Bumper F, Broken, Replace




Bumper FM, Deformed / Strained, Replace and paint




Grille, Broken, Replace




Door FR, Dent(s) and scratch(es), Repair and paint (complete)








Outside rear-view mirror housing R, Scratch(es), Replace





Wing FR, Dent(s), Repair and paint (complete)





Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)





Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)







Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)





Wing trim RR, Scratch(es), Replace





Side wall panel RR, Broken, Replace




Bumper corner RL, Scratch(es), Replace





Bumper corner RR, Scratch(es), Replace







Rear light R, Crack, Replace




Onderhoudshistorie van: WV1ZZZSY7P9001419

ALPHABET

Kenteken	VRK79P
Merk Model	Volkswagen Crafter 35 2.0 TDI 103kW FWD GB L3H3 automaat
Brandstofsoort	Diesel
Datum deel1	9/15/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
8/17/26	247,489	Remschijf + blokken achter
6/8/26	235,794	Onderhoudsbeurt
6/8/26	235,794	Waterpomp elektrisch
1/22/26	212,376	Aandrijfashoes
1/22/26	212,376	Brandstoffilter
1/22/26	212,376	Distributie riem
1/22/26	212,376	Luchtfilter
1/22/26	212,376	Onderhoudsbeurt
1/22/26	212,376	Remklauw(en) voorzijde
1/22/26	212,376	Remschijf + blokken voor
1/22/26	212,376	Ruitenwisserblad(en) voorzijde
1/22/26	212,376	Vervanging band
9/15/25	188,025	APK
9/15/25	188,025	Multiriem inclusief spanner
9/15/25	188,025	Onderhoudsbeurt
9/15/25	188,025	Remblokken achterzijde
9/15/25	188,025	Vervanging band
8/6/25	181,255	Vervanging band
5/21/25	166,876	Onderhoudsbeurt
5/21/25	166,876	Voorgloeirelais
3/14/25	155,294	Remblokken voorzijde
3/5/25	152,808	Reparatie band(en)
1/16/25	144,906	Slang koelsysteem
11/25/24	135,414	Distributieriem + spanrol + geleiderol
11/25/24	135,414	Onderhoudsbeurt
11/25/24	135,414	Remblokken achterzijde
11/25/24	135,414	Remvloeistof
11/25/24	135,414	Vervanging band
11/25/24	135,414	Waterpomp
7/9/24	116,055	Brandstoffilter
7/9/24	116,055	Distributie riem
7/9/24	116,055	Luchtfilter
7/9/24	116,055	Onderhoudsbeurt
7/9/24	116,055	Remblokken voorzijde
7/9/24	116,055	Ruitenwisserblad(en) voorzijde
3/27/24	99,501	Aandrijfas
3/26/24	99,501	Aandrijfashoes
3/26/24	99,501	Onderhoudsbeurt
12/14/23	79,890	Vervanging band
9/26/23	61,857	Onderhoudsbeurt

Datum reparatie	Kilometerstand	Reparatie omschrijving
9/26/23	61,857	Remblokken achterzijde
9/26/23	61,857	Remblokken voorzijde
3/8/23	29,043	Vervanging band
2/23/23	27,199	Onderhoudsbeurt
2/23/23	27,199	Ruitenwisserblad(en) voorzijde