MACADAM









PEUGEOT 308: HD-166-HY

Vinnumber:	**VR3FPHPY7SY534910**	Versionname:	**PEUGEOT 308 Hybrid 136 e-DCS6 STYLE VP [5P] bva 6-136CH-7cv (bi-corps)**
First Registrationdate:	**30/04/2025**	Fiscalpower:	
Expertise Mileage:	**68621**	Power Kw:	**100**
Bodytype:	**Break**	Body colour	**Blue**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Hybrid**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Seat cover lining	**Lining Other**
Steering wheel leather			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/55/16/94 V**			
	Fr.L.	**Goodyear: 80%**	Fr.R.	**Goodyear: 75%**
	Re.L.	**Goodyear: 60%**	Re.R.	**Goodyear: 65%**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.2**
Tyre profile depth RL	**4.3**
Tyre profile depth RR	**3.9**
Tyre size FL	**205/55 R 16 94 V**
Tyre size FR	**205/55 R 16 94 V**
Tyre size RL	**205/55 R 16 94 V**
Tyre size RR	**205/55 R 16 94 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**No**	Jack	**No**

Remote ignition key (no insert), Missing, Repair/replace (lump sum)




Interior, Dirty, Chemical cleaning








Tyre FL, Out of tolerance, Replace





Tyre RR, Out of tolerance, Replace





Tyre FR, Out of tolerance, Replace





Wing RL, Scratch(es), Paint




Bumper FR, Scratch(es), Paint







Bumper FL, Scratch(es), Paint




Windscreen, Stone chip(s), Windscreen repair

Jack, Missing, Repair/replace (lump sum)




Spare tyre, Missing, Replace




Spare rim, Missing, Replace




Rear bulkhead lining, Scratch(es), Replace










Bumper R, Scratch(es), Paint









ALPHABET

Historique Maintenance

Immatriculation: **HD-166-HY** Date de 1ère immatriculation: **30/04/2025**

Modèle: **Peugeot 308 Hybrid 136 e-DCS6 STYLE VP [5P] bva 6-136CH-7cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
04/03/2026	34.402	RYCKWAERT GIGNAC	FILTRE CLIM RPLT
	0		RECYCLAGE
	0		REVISION