DEKRA Automotive Solutions


Condition Report

Vehicle details

VIN	WAUZZZGY3 TA043949	Mileage	21 012 km	Engine (Fuel) Type	Hybrid petrol
Licence Plate	2HTX314	Registration date	06/11/2025	Engine size	1498
Brand	AUDI	Fuel level	-	Transmission	Automatic
Model	A3Lim-8YS-2020	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Noir		

Inspection Details


Inspection date	29/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique



Other technical information

Emergency compressor kit	✔
Refill emergency kit	✔

Tyres



Falken 225/45/17 Y Summer 4.0 mm

Falken 225/45/17 Y Summer 4.0 mm



Falken 225/45/17 Y Summer 5.0 mm

Falken 225/45/17 Y Summer 5.0 mm

Damages

1




Part	Interior cleaning
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
Net cost (Excluding VAT)	29.62€

2



Part	A-pillar trim
Position	Front left
Damages	Cut
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	28.40€

3



Part	Exterior complete
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Polishing
Net cost (Excluding VAT)	355.50€

brouillard de vernis sur tout le vehicule ! !!!! tout est touché vitres ,carrosserie , baguettes, sous reserve

4



Part	Bumper
Position	Front
Damages	Improper repair
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	339.25€

mauvaise reparation, defaut sous peinture

DEKRA

DEKRA Automotive Solutions

Condition Report

5



Part	Wing
Position	Front right
Damages	Improper repair
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	368.88€

mauvaise reparation, defaut sous peinture

6



Part	Wing
Position	Back right
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	49.00€

7



Part	12v Socket Cover
Position	-
Damages	Missing
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	12.90€

Summary Inspection

Net Price (Exclusing VAT)	1,183.55€