MACADAM

Ford Mustang '19 BEV

Vehicle information


Make:	**Ford**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**Mustang '19 BEV**	VIN:	**WF0TK1EM8MMA22304**
Fuel type:	**Electric**	Power:	**190 kW**
Version:	**Mustang EV 75kWh RWD St.Ran.**	First registration	**21/07/2021**
Mileage:	**159414 km**	N° of doors:	

Damage summary

Front	1
Interior	2
Left	3
Rear	1
Right	3

Commercial pictures


Rijbereik
206 km
57 %
Veiligheids-
gordels
km/h
0
P R N D L
READY
15944 km




WF0TK1EM8MMA22304


HANKOOK



Hankook


HANKOOK






mach-e


14:56


14:55
Vaarheen?
Apple CarPlay
Verbind
Geen apparaat verbonden
Verbind


Batterijcertificaat
Datum van diagnose: 26/10/2026
94%
Status van de gezondheid (SOH)*
Ford Mustang MACH e
Standard Range
VIN : WF0TK1EM8MMA22304
Kilometerstand : 159.414 km
*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA



Options according to the inspector


Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Radio multimedia	**Yes**	Rear view camera	**Yes**	Telephone equipment	**Yes**

Damages

Bumper F
Scratch(es)
Repair and paint (complete)
Front





Door FL
Dent(s) and scratch(es)
Repair and paint (complete)
Left

Door FR
Dent(s) and scratch(es)
Repair and paint (complete)
Right




Door RL
Dent(s) and scratch(es)
Repair and paint (complete)
Left





Door RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right





Ignition key
Missing
Replace
Interior

Interior
Smell
Ozone treatment (Smoke)
Interior





Tailgate / Boot
Scratch(es)
Repair and paint (complete)
Rear





Wheel arch cover moulding RL
Scratch(es)
Replace
Left





Wing RR
Deformed / Strained
Repair and paint (complete)
Right





Tyres

Front Left
Winter
225/60/18/104/H
Hankook
6.4 mm
Front Right
Winter
225/60/18/104/H
Hankook
5.6 mm
Rear Left
Winter
225/60/18/104/H
Hankook
3.8 mm
Rear Right
Winter
225/60/18/104/H
Hankook
3.4 mm

Checks

CO2 Emission	**0**	Digital maintenance	**Yes**
GPS storage	**Yes**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**1**
Number of keys total	**1**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**N/A**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.