TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48518540
Order No. / Reference: 27223231
Inspection date: 28 Oct 2026

Manufacturer: MAN	Model: TGE 3.140 4X2F SB
VIN: WMA03VUY7P9023174	





Vehicle details

Manufacturer / Type / Model / Equipment	
MAN TGE 3.140 4X2F SB	
Vehicle Identification number	WMA03VUY7P9023174
Mileage (Read)	75,656 km
First registration	17 Jul 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	103 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy Weiß Uni
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	6,800 km
Last service on / at	07/2025 at 32,389 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GW443185
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1516 / AYN 61613		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/75 R16 113R	All-season tyres on Steel rim with wheel cover	Continental	3mm / 3mm
2)	205/75 R16 113R	All-season tyres on Steel rim with wheel cover	Continental	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/75 R16 113R	All-season tyres on Steel	Continental	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- "Multifunction display ""Plus"" "
- "Rear View" reversing camera
- "Seat ""Comfort"" left "
- Single-layer solid color - Candy white
- 2 remote folding keys
- 3-button module
- 4 speakers: 2 tweeters, 2 woofers
- 4-cyl. turbo diesel engine 2.0 l/103 KW (4V) common rail
- 4th cylinder diesel engine 2.0L unit 04L.Y
- 6-speed
- from 09.2018
- Filing package
- Right-hand side mirror, convex, with integrated LED indicator light and wide-angle range
- Left-hand exterior mirror, convex, with integrated LED indicator light and wide-angle range
- Battery with increased capacity
- Hill start assist
- Operating permit supplement C38
- Floor in the cargo area
- On-board tools and jack
- CO2-optimized variant
- Digital radio reception (DAB+)
- Three-phase generator 140 A
- One towing eye at the front
- Entry handle on the partition wall in the cargo area
- Electronic Stability Program (ESP) and ABS with electronic differential lock
- Cab doors, additionally with reinforced door hinges on the driver's side
- Front Assist with City Emergency Braking function
- Radio frequency 433 MHz
- Generator 140 A
- Weight class front axle, weight range 2
- Rubber flooring in the driver's cab
- Halogen dual headlights
- Handbrake lever, standard
- Glove compartment with lockable, illuminated flap
- Rear wing doors with increased opening angle
- Heating in the driver's cab, electronically controlled
- High roof, painted in the car's color on the outside
- Wooden floor
- Instrument cluster, display in km/h
- panel van
- No category
- Fuel tank 75l
- LED interior lighting
- Unladen weight range 3
- Left-hand drive
- MAN Media Van
- "Region code "" ECE "" for radio "
- "Front disc brakes, 16"" "
- "Seat ""Standard"" right "
- 1968ccm (2.0 Ltr) 103kW
- 205/75 R 16 C
- 4 speakers
- 4 steel wheels 6 1/2 J x 16, with a load capacity of 1,050 kg, in silver
- 4490mm with extended frame (L5)
- 6.5 J x 16
- Exhaust concept, EU6 AR
- Airbag for driver and front passenger with passenger airbag deactivation
- Electrically adjustable exterior mirrors
- Exterior mirrors, electrically adjustable and heated
- 520A (92Ah) battery
- Component set without country-specific building regulations
- Operating voltage 12 V
- Onboard literature in German
- C-rails on the side walls in the loading area
- Roof gallery with storage compartments, two 1-DIN slots and reading light
- Three-point automatic seat belts with belt height adjustment and electric belt tensioners at the front
- Grab handles on the rear pillars
- Factory
- Driver/passenger airbag
- Vehicle class differentiation-7C0-
- Suspension/damping and stabilization package 1
- Front drive
- All-season tyres
- Weight range front axle class 2
- Gray Mesh-Man Black/Titanium Black-Palladium/Pearl Gray
- Seatbelt monitoring, electrical contact in the seatbelt buckle
- Lockable glove compartment
- Rear wing doors 270° opening
- Rear wing doors without window cutouts
- High roof (H2)
- Wooden floor in the cargo area with wheel arch cladding
- Interior noise reduction measures Plus
- Instrument panel
- Not a special vehicle, standard version
- Diesel fuel system
- Radiator guard grille, black with chrome trim
- LED interior lighting concept in the passenger/cargo area
- Steering wheel
- MAN brand/class specific features
- MAN Media Van package with 4 speakers
- Side marker lights
- Mobile phone interface
- National registration documentation Germany

- MAN SmartLink
- With first-aid supplies and a warning triangle
- Standard engine start
- Not hot country
- Center wheel cover
- Digital radio reception
- Long wheelbase 4,490 mm with long overhang
- Smoker's package
- Legal transactions
- Tires without specifying the tire brand
- Spare wheel (steel rim) with driving tires
- Rear view camera
- 6-speed manual transmission
- Sliding door, right
- Crosswind assist
- Side marker lights
- "Comfort" seat on the left, in the 1st row
- Fabric seat covers
- Standard climate zones
- Daytime running light
- Rear step
- USB dual function module 45W
- Lashing rails (airline) in the cargo area: side walls
- Electronic immobilizer
- Central locking with remote control and interior operation
- Two 12V sockets in the driver's cab (in the instrument panel)
- Emergency brake assist
- Center wheel cover with chrome emblem
- Wheel bolts without wheel locking mechanism
- Smoker's version: 12V socket with cigarette lighter, ashtray, 4 cup holders in dashboard
- Tires 205/75 R 16 C 113/111, optimized for rolling resistance
- Spare wheel in driving tire size, steel, as well as on-board tools and jack
- Windscreen wiper intermittent control
- Sliding door, right, in the cargo/passenger compartment
- Side interior paneling in the cargo area (plastic)
- Service indicator: 50,000 km or 2 years (variable)
- Seat covers in "Toronto Grid" fabric
- Sun visors, foldable and swiveling to the side
- Start-stop system
- Partition wall
- Rear step, across the entire width
- Laminated glass windshield in heat-insulating glazing
- Lashing eyes for securing cargo
- Central locking with remote control
- Approval as 3.5t

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratch(es) - No deduction
2	Trim / covers	Trim / covers - Loose - Repair
3	Trim / covers	Door trim - front left side - Loose - Repair
4	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Loss in value
5	Sill - right side	Sill - Dent / paintcoat damage - Smart repair
6	Seat - front	Seat cover - left side - Burn hole (cigarettes) - Smart repair
7	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - Smart repair
8	Roof	Roof rail - right side - Scratch(es) - Smart repair
9	Roof	Roof - dent(s) - Smart repair
10	Boot lid / rear door	Reflectors (Links und rechts) - Broken / torn - Replace
11	Body	Body - Glued / labelled - De-glue / neutralise
12	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint
13	Side panel - rear right side	Side panel (Wellig) - Unprofessionally repaired - Repair and paint
14	Wheel / tyres	Tyres - complete set - does not meet manufacturer specifications - Replace
15	Sliding door, right	Sliding door (Orangenhaut) - Unprofessionally repaired - Repair and paint
16	Mudguard - right side	Mudguard - right side (Wellig und eingefallen) - Unprofessionally repaired - Repair and paint
17	Door - front right side	Door (Orangenhaut und wellig) - Unprofessionally repaired - Repair and paint
18	Side panel - rear left side	Side panel (Wellig) - Unprofessionally repaired - Repair and paint

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper (unpainted) - Scratch(es) - No deduction
2	Wing mirror - right side	Cap - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Door - front left side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Mudguard - right side, Unprofessionally carried out, Invoice of repair done Non-existent
2	Side panel - rear left side, Unprofessionally carried out, Invoice of repair done Non-existent
3	Side panel - rear right side, Unprofessionally carried out, Invoice of repair done Non-existent
4	Door - rear right side, Unprofessionally carried out, Invoice of repair done Non-existent
5	Door - front right side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	927 µm	Side panel - rear left side	181 µm
Side panel - rear right side	181 µm	Door - rear right side	208 µm
Door - front right side	163 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.





Figure 27: Misc.



Figure 28: Misc.



Damage 1: Wing mirror - left side: Cap - Scratch(es) - No deduction



Damage 2: Trim / covers: Trim / covers - Loose - Repair



Damage 3: Trim / covers: Door trim - front left side - Loose - Repair



Damage 3: Trim / covers: Door trim - front left side - Loose - Repair



Damage 4: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 4: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 4: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 5: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 5: Sill - right side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Smart repair




Damage 6: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Smart repair



Damage 7: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 7: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 7: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 7: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair




Damage 8: Roof: Roof rail - right side - Scratch(es) - Smart repair




Damage 8: Roof: Roof rail - right side - Scratch(es) - Smart repair



Damage 9: Roof: Roof - dent(s) - Smart repair



Damage 9: Roof: Roof - dent(s) - Smart repair



Damage 9: Roof: Roof - dent(s) - Smart repair



Damage 10: Boot lid / rear door: Reflectors (Links und rechts) - Broken / torn - Replace



Damage 10: Boot lid / rear door: Reflectors (Links und rechts) - Broken / torn - Replace



Damage 10: Boot lid / rear door: Reflectors (Links und rechts) - Broken / torn - Replace



Damage 11: Body: Body - Glued / labelled - De-glue / neutralise




Damage 11: Body: Body - Glued / labelled - De-glue / neutralise




Damage 11: Body: Body - Glued / labelled - De-glue / neutralise




Damage 12: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint




Damage 12: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint




Damage 12: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint




Damage 13: Side panel - rear right side: Side panel (Wellig) - Unprofessionally repaired - Repair and paint




Damage 13: Side panel - rear right side: Side panel (Wellig) - Unprofessionally repaired - Repair and paint




Damage 13: Side panel - rear right side: Side panel (Wellig) - Unprofessionally repaired - Repair and paint




Damage 14: Wheel / tyres: Tyres - complete set - does not meet manufacturer specifications - Replace



Damage 14: Wheel / tyres: Tyres - complete set - does not meet manufacturer specifications - Replace




Damage 14: Wheel / tyres: Tyres - complete set - does not meet manufacturer specifications - Replace



Damage 14: Wheel / tyres: Tyres - complete set - does not meet manufacturer specifications - Replace




Damage 15: Sliding door, right: Sliding door (Orangenhaut) - Unprofessionally repaired - Repair and paint



Damage 15: Sliding door, right: Sliding door (Orangenhaut) - Unprofessionally repaired - Repair and paint



Damage 15: Sliding door, right: Sliding door (Orangenhaut) - Unprofessionally repaired - Repair and paint




Damage 15: Sliding door, right: Sliding door (Orangenhaut) - Unprofessionally repaired - Repair and paint




Damage 16: Mudguard - right side: Mudguard - right side (Wellig und eingefallen) - Unprofessionally repaired - Repair and paint



Damage 16: Mudguard - right side: Mudguard - right side (Wellig und eingefallen) - Unprofessionally repaired - Repair and paint




Damage 16: Mudguard - right side: Mudguard - right side (Wellig und eingefallen) - Unprofessionally repaired - Repair and paint




Damage 16: Mudguard - right side: Mudguard - right side (Wellig und eingefallen) - Unprofessionally repaired - Repair and paint



Damage 17: Door - front right side: Door (Orangenhaut und wellig) - Unprofessionally repaired - Repair and paint



Damage 17: Door - front right side: Door (Orangenhaut und wellig) - Unprofessionally repaired - Repair and paint



Damage 17: Door - front right side: Door (Orangenhaut und wellig) - Unprofessionally repaired - Repair and paint



Damage 17: Door - front right side: Door (Orangenhaut und wellig) - Unprofessionally repaired - Repair and paint




Damage 17: Door - front right side: Door (Orangenhaut und wellig) - Unprofessionally repaired - Repair and paint



Damage 17: Door - front right side: Door (Orangenhaut und wellig) - Unprofessionally repaired - Repair and paint



Damage 18: Side panel - rear left side: Side panel (Wellig) - Unprofessionally repaired - Repair and paint



Damage 18: Side panel - rear left side: Side panel (Wellig) - Unprofessionally repaired - Repair and paint




Damage 18: Side panel - rear left side: Side panel (Wellig) - Unprofessionally repaired - Repair and paint



Damage 18: Side panel - rear left side: Side panel (Wellig) - Unprofessionally repaired - Repair and paint




Damage 18: Side panel - rear left side: Side panel (Wellig) - Unprofessionally repaired - Repair and paint



Wear and tear 4: Door - front left side: Door - dent(s) - No deduction



Wear and tear 4: Door - front left side: Door - dent(s) - No deduction



Wear and tear 4: Door - front left side: Door - dent(s) - No deduction



Repainting 1: Mudguard - right side



Repainting 1: Mudguard - right side



Repainting 2: Side panel - rear left side



Repainting 2: Side panel - rear left side



Repainting 3: Side panel - rear right side



Repainting 3: Side panel - rear right side



Repainting 4: Door - rear right side



Repainting 4: Door - rear right side



Repainting 5: Door - front right side



Repainting 5: Door - front right side