TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48577736
Order No. / Reference: 27144529
Inspection date: 3 Nov 2026

Manufacturer: Skoda	Model: Kodiaq 2.0 TDI DSG Sportline
VIN: TMBJJ7NS6R8505060	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Kodiaq 2.0 TDI DSG Sportline	
Vehicle Identification number	TMBJJ7NS6R8505060
Mileage (Read)	91,266 km
First registration	13 Oct 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Black Magic Perleffekt
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	11,100 km
Last service on / at	09/2026 at 87,526 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV919316
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / ART 04443		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,360 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R19 99V	Summer tyres on Light alloy	Hankook	5mm / 5mm
2)	235/50 R19 99V	Summer tyres on Light alloy	Hankook	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 103H	Winter tyres on Light alloy	Bridgestone	2mm / 2mm
2)	215/65 R17 103H	Winter tyres on Light alloy	Bridgestone	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12V socket in the center console and in the trunk
- Storage compartments behind the wheel arches in the trunk
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Dashboard in black / black, door trim in black with microfiber inlay
- Electrically adjustable and heated exterior mirrors with integrated side indicators
- Care Connect: Proactive services (10-year term)
- Roof rails, black
- Diesel particulate filter
- Tachometer
- Easy Start (start-stop button)
- Electronic parking brake including auto-hold function
- ESC Electronic Stability Control
- Driving profile selection
- Electric windows front and rear
- High Beam Assist (Light Assist)
- front and rear floor mats
- Front and rear footwell lighting
- Cruise control
- Tinted windows
- Isofix anchorage on the outer rear seats including top tether
- LED ambient lighting
- LED matrix headlights and dynamic high beam assist (Light Assist)
- Steering wheel: Sport leather steering wheel with multifunction buttons including paddle shifters.
- Front center armrest, including storage compartment
- Multi-collision brake
- Rear parking sensors
- Upholstery: Microfiber Sport-Black
- Radio accessories: 8 speakers
- Radio accessories: Wireless SmartLink
- Wheels: 19" alloy wheels Triglav anthracite polished (7Jx19 tires 235/50 R19 99V ET43)
- Heated windshield washer nozzles, front
- Electromechanical power steering
- Seats: Heated front and outer rear seats
- Seats: Electrically adjustable front seats with memory function
- Skoda Care Connect
- Sun visor on driver and passenger side with illuminated vanity mirror
- Sunset
- Front door sill trims
- Variable fastening concept in the trunk
- Immobiliser
- Storage compartment on the left wheel arch
- front aero windshield wipers
- Airbag, driver and passenger
- Airbag, head airbags
- Allergen filter
- Traction control (ASR)
- Electrically folding exterior mirrors including interior and driver's side mirrors with automatic dimming
- Hill start assist
- Hydraulic brake assist (HBA)
- Black headliner
- Dark carbon decorative inlay
- Digital Cockpit (8")
- Third brake light
- eCall
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor
- Chassis: Adaptive chassis DCC including driving profile selection
- Front radar assistant including city emergency braking function with pedestrian detection
- Closed storage compartment on the driver's side
- Transmission: 7-speed dual-clutch transmission (DSG)
- Illuminated glove compartment
- Boot cover, roll-up and removable
- Front headrests are fixed, rear headrests are height-adjustable.
- LED taillights in crystal glass look with animated turn signals
- Reading lights at the front of the headliner
- Rear center armrest with cup holders
- Engine drag torque control (MSR)
- Fog lights with integrated LED daytime running lights
- Stainless steel pedal design
- Progressive steering
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring
- Rear seat backrest split 60:40, foldable, longitudinally adjustable, backrest angle adjustable
- Headlights washer / wiper system
- Kodiaq seat belts
- Seats: Adjustable lumbar support in the front seats
- Seats: Height-adjustable front seats
- Seats: Remote release of the rear seat backrests (2nd row) in the boot
- Speed limiter
- Bumpers painted in body color
- Telephone: Convenient hands-free telephone system including phone box
- Lashing eyes in the trunk
- Central locking with remote control

Extra equipment

- Swiveling trailer hitch (with electric release, including trailer stabilization)
- Climatronic air conditioning (3-zone) (fully automatic, separately adjustable for driver, front passenger and rear seats, including humidity sensor and odor and allergen filter)
- Package: Business Columbus (Sportline) (Dynamic radio navigation system Columbus - 9.2" capacitive color display - Digital Cockpit Plus (10") - Driver fatigue detection - 230V socket and a USB charging port (Type-C) on the back of the front center armrest - KESSY keyless entry - Electric tailgate operation including comfort opening - Luggage net partition - Infotainment Online (3-year subscription))
- Anti-theft alarm system with SAFE system incl. Kessy & Easy Start (interior monitoring and tilt sensor incl. Kessy & Easy Start)
- Paint finish: Metallic / Pearl effect
- Steering wheel: Heated sports steering wheel including paddle shifters (height and reach adjustable leather steering wheel with multifunction buttons)
- Front and rear parking sensors
- Rear view camera
- Windscreen, wirelessly heated

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear left side	Door edge - Scratch(es) - Smart repair
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Roof	Roof rail - left side - Scratch(es) - Loss in value
4	Rear bumper	Spoiler - Scratched - Smart repair
5	Mudguard - right side	Wheel well extension - Scratch(es) - Replace
6	Wheel / tyres	Alloy rim - rear right side - Scratched - Loss in value
7	Roof	Roof rail - right side - Scratch(es) - Replace
8	Door - front right side	Brightware - lower - Scratched - Replace
9	Mudguard - right side	Mudguard - right side - Scratch(es) - Paint
10	Door - rear right side	Door - Scratched - Paint
11	Side panel - rear right side	Side panel - Scratch(es) - Paint
12	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint
13	Side panel - rear left side	Side panel (Lackeinschlüsse, Läufer, Staubeinschlüsse) - Unprofessionally repaired - Repair and paint
14	Headlight	Headlight - right side - Scratch(es) - Replace
15	Vehicle glazing	Windscreen (Mit Rissbildung) - Stone chips - Replace
16	Roof	Roof (Verätzung Vogelkot) - Paint defect - Paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	2nd wheel set	1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction
3	2nd wheel set	1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction
4	Boot lid / rear door	Boot lid (Innenverkleidung) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Rear, Side - left, not professionally repaired, Invoice of repair done Non-existent, from 26 Jun 2025	17.293,70 €

Repainting

No.	Repainting
1	Side panel - rear left side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear left side	208 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

An unprofessionally repaired previous damage was found at the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.







Figure 38: Misc.



Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Roof: Roof rail - left side - Scratch(es) - Loss in value



Damage 3: Roof: Roof rail - left side - Scratch(es) - Loss in value




Damage 4: Rear bumper: Spoiler - Scratched - Smart repair



Damage 4: Rear bumper: Spoiler - Scratched - Smart repair



Damage 4: Rear bumper: Spoiler - Scratched - Smart repair



Damage 5: Mudguard - right side: Wheel well extension - Scratch(es) - Replace



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 7: Roof: Roof rail - right side - Scratch(es) - Replace



Damage 7: Roof: Roof rail - right side - Scratch(es) - Replace



Damage 8: Door - front right side: Brightware - lower - Scratched - Replace



Damage 8: Door - front right side: Brightware - lower - Scratched - Replace




Damage 8: Door - front right side: Brightware - lower - Scratched - Replace




Damage 8: Door - front right side: Brightware - lower - Scratched - Replace




Damage 8: Door - front right side: Brightware - lower - Scratched - Replace




Damage 9: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




Damage 9: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint




Damage 9: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 10: Door - rear right side: Door - Scratched - Paint




Damage 10: Door - rear right side: Door - Scratched - Paint



Damage 10: Door - rear right side: Door - Scratched - Paint



Damage 10: Door - rear right side: Door - Scratched - Paint




Damage 11: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 11: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 11: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 11: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 12: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint




Damage 13: Side panel - rear left side: Side panel (Lackeinschlüsse, Läufer, Staubeinschlüsse) - Unprofessionally repaired - Repair and paint




Damage 13: Side panel - rear left side: Side panel (Lackeinschlüsse, Läufer, Staubeinschlüsse) - Unprofessionally repaired - Repair and paint




Damage 13: Side panel - rear left side: Side panel (Lackeinschlüsse, Läufer, Staubeinschlüsse) - Unprofessionally repaired - Repair and paint



Damage 14: Headlight: Headlight - right side - Scratch(es) - Replace



Damage 14: Headlight: Headlight - right side - Scratch(es) - Replace



Damage 14: Headlight: Headlight - right side - Scratch(es) - Replace



Damage 14: Headlight: Headlight - right side - Scratch(es) - Replace



Damage 15: Vehicle glazing: Windscreen (Mit Rissbildung) - Stone chips - Replace



Damage 15: Vehicle glazing: Windscreen (Mit Rissbildung) - Stone chips - Replace



Damage 15: Vehicle glazing: Windscreen (Mit Rissbildung) - Stone chips - Replace




Damage 16: Roof: Roof (Verätzung Vogelkot) - Paint defect - Paint



Damage 16: Roof: Roof (Verätzung Vogelkot) - Paint defect - Paint



Damage 16: Roof: Roof (Verätzung Vogelkot) - Paint defect - Paint



Wear and tear 2: 2nd wheel set: 1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction



Wear and tear 2: 2nd wheel set: 1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction



Wear and tear 2: 2nd wheel set: 1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction



Wear and tear 3: 2nd wheel set: 1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction



Wear and tear 3: 2nd wheel set: 1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction



Wear and tear 3: 2nd wheel set: 1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction




Wear and tear 4: Boot lid / rear door: Boot lid (Innenverkleidung) - Scratch(es) - No deduction



Wear and tear 4: Boot lid / rear door: Boot lid (Innenverkleidung) - Scratch(es) - No deduction



Wear and tear 4: Boot lid / rear door: Boot lid (Innenverkleidung) - Scratch(es) - No deduction



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side