TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48377666
Order No. / Reference: 27174952
Inspection date: 27 Oct 2026

Manufacturer: Mercedes-Benz	Model: Vito 116 CDI Extralang HA BASE
VIN: W1V44760513950257	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 116 CDI Extralang HA BASE	
Vehicle Identification number	W1V44760513950257
Mileage (Read)	138,501 km
First registration	18 Aug 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	120 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Navyblau Uni
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	618 Tag(e)
Key is / should be	2 / 4	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH651643
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / BBJ 03133		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 103H	Summer tyres on Steel	Continental	7mm / 7mm
2)	205/65 R16 103H	Summer tyres on Steel	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Winter tyres on Steel	Uniroyal	9mm / 9mm
2)	205/65 R16 107T	Winter tyres on Steel	Uniroyal	9mm / 9mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/65 R16 103H C	Summer tyres on Steel	Hankook	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Screw-in towing eye front/rear
- Passenger side airbag
- ATTENTION ASSIST (ATTENTION ASSIST can assist the driver on long, monotonous journeys by monitoring attention. If signs of fatigue or increasing inattention are detected, it suggests a break.)
- Hill start assist
- Brake lights, adaptive
- Front cupholder
- Electronic tachometer
- Chassis: Standard chassis
- HVO-capable vehicle
- Electric window regulator driver/passenger (with anti-pinch protection, quick lowering and raising)
- Generator 14 V / 200 A
- Speed limit 210 km/h
- Transmission: 6-speed manual transmission TSG 380
- Weight variant 2,800 kg
- Seatbelt warning device for front passenger seat
- Seatbelt warning device for driver's seat
- Lockable glove box
- Main tank 57 liters
- Boot lid
- Interior trim of cargo area, side
- Communication module (LTE) for digital services
- Headrests (2), front
- Steering wheel adjustable for tilt and height
- Headlight range control
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Breakdown management
- Tires: 205/65 R 16
- Tires: Premium protection tires (3 years)
- Wheels: Steel rims 6.5 J x 16
- Sliding door on the right, cargo/passenger compartment
- Crosswind Assist
- Seats: Adjustable passenger seat
- 12V socket
- continuous partition wall
- Pre-installation for Remote Services Plus
- Maintenance interval indicator >>ASSYST<
- Heat-insulating glass all around
- Registration as a truck
- Axle ratio i = 3.267
- Driver's side airbag
- Outdoor temperature display
- Battery: Backup battery for starting process
- Battery: fleece battery 12 V / 92 Ah
- Fixing points in the roof frame
- third brake light
- COC documents
- Diesel particulate filter
- Electronic Stability Program (ADAPTIVE ESP) with integrated anti-lock braking system (ABS) (traction control (ASR) - electronic brake force distribution (EBD) - brake assist (BAS))
- Parking brake
- Generator management (Generator management helps reduce fuel consumption and CO2 emissions. The generator is switched off and the vehicle's electrical system is powered by the battery when it is sufficiently charged. This relieves the engine of the burden of charging the battery, for example, during acceleration. - When braking and during coasting downhill, the generator is switched on and the vehicle's kinetic energy is recuperated to charge the battery.)
- Instrument cluster with pixel matrix display (operated via the buttons on the multifunction steering wheel - round instruments for speedometer and tachometer or fuel level and coolant temperature - high-quality pixel matrix display in white and red between the large round instruments)
- Multifunction steering wheel (with trip computer)
- Package: BlueEFFICIENCY (Efficiency Package)
- Upholstery: Caluma fabric, black
- Tires: Tires without specified make
- Tires: Summer tires
- Headlights: halogen technology
- Key: 3-button remote control
- electromechanical power steering
- Start-stop function
- Cruise control
- First aid kit
- Warning triangle
- Immobiliser
- Central locking with radio remote control
- Registration certificate, Part II

Extra equipment

- 2 extra keys
- Electrically adjustable and heated exterior mirrors, left and right
- Driving light assistant (automatically switching on driving lights)
- Rear camera not foldable
- Tempmatic controlled air conditioning
- Paint finish: Special paint finish (according to sample card)
- Center console with storage compartment
- Halogen fog lights
- Radio: Digital Radio DAB
- Rain sensor
- Tire pressure monitoring (on front and rear axles (wireless))
- Spare wheel under the rear of the vehicle with jack
- Keys: 2 additional master keys
- Seats: Comfort driver's seat
- Seat heating on driver's side
- Upgrading/downgrading (upgrading to 3.05 t GVW)
- Comfort roof control unit in conjunction with rain sensor
- Burglar and theft alarm system (without interior monitoring)
- Fleet Comfort Package (Z7K)
- Generator 14 V / 250 A
- Interior lining of the cargo area up to roof height (wood)
- Large fuel tank, approx. 70 liters
- LED light strip in the cargo area
- Navigation accessories: Live Traffic Information
- Radio/Navigation: Multimedia radio and navigation system "Audio 40" (7-inch LCD touchscreen - DAB digital radio - Apple CarPlay and Android Auto - Bluetooth 3.0 - Hands-free system - Live Traffic Information - 2-way front speakers)
- High-resolution reversing camera with guide lines
- Seats: Comfort passenger seat
- Seat heating on passenger side

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Wing mirror - right side	Cap - Broken / torn - Replace
3	Body	Body - Glued / labelled - De-glue / neutralise
4	Seat - front	Seat cover - left side - Broken / torn - Replace
5	Bonnet	Bonnet - Corrosion - Repair and paint
6	Vehicle glazing	Windscreen - Broken / torn - Replace
7	Boot lid / rear door	Boot lid - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper (unpainted) - Scratch(es) - No deduction
2	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction
3	Door - front left side	Door - dent(s) - No deduction
4	Roof	Roof - dent(s) - No deduction
5	Door - front left side	Door edge - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Vehicle key (2 Schlüssel)

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 2: Wing mirror - right side: Cap - Broken / torn - Replace



Damage 2: Wing mirror - right side: Cap - Broken / torn - Replace



Damage 3: Body: Body - Glued / labelled - De-glue / neutralise



Damage 3: Body: Body - Glued / labelled - De-glue / neutralise




Damage 3: Body: Body - Glued / labelled - De-glue / neutralise



Damage 3: Body: Body - Glued / labelled - De-glue / neutralise




Damage 3: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Seat - front: Seat cover - left side - Broken / torn - Replace




Damage 4: Seat - front: Seat cover - left side - Broken / torn - Replace




Damage 4: Seat - front: Seat cover - left side - Broken / torn - Replace



Damage 5: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 5: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 5: Bonnet: Bonnet - Corrosion - Repair and paint




Damage 5: Bonnet: Bonnet - Corrosion - Repair and paint




Damage 5: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 5: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 6: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 6: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 6: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 7: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Deformed - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Deformed - Repair and paint