TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48249677
Order No. / Reference: 27156781
Inspection date: 20 Oct 2026

Manufacturer: Mercedes-Benz	Model: A 180 d 8G-DCT Entry
VIN: W1K3F1AB1SJ459039	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz A 180 d 8G-DCT Entry	
Vehicle Identification number	W1K3F1AB1SJ459039
Mileage (Read)	160,830 km
First registration	1 Jul 2024
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	85 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Nachtschwarz
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	296 Tag(e)
Last service on / at	08/2026 at 151,164 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB227389
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / AWX 00052		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,010 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96W	Summer tyres on Light alloy	Semperit	6mm / 6mm
2)	205/60 R16 96W	Summer tyres on Light alloy	Semperit	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91H	Winter tyres on Light alloy	Hankook	4mm / 4mm
2)	205/55 R17 91H	Winter tyres on Light alloy	Hankook	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Adaptive brake light flashing
- Airbag: Driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Traction control (ASR)
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Brake assist, active
- Double cup holder at the front
- ECO start/stop function
- Electronic Stability Program (ESP)
- Chassis: Comfort chassis with lowered suspension
- Electric windows (4-way)
- Luggage net on driver and passenger seatbacks
- Transmission: 8G-DCT automatic
- rear window wiper
- Heated rear window
- KEYLESS-GO start function
- THERMATIC automatic climate control
- Rear headrests (3)
- Front headrests are height-adjustable
- Steering wheel: Multifunction sports steering wheel in leather
- Navigation: MBUX Navigation Premium
- Package: Seating comfort
- Upholstery: ARTICO leatherette/Bertrix fabric
- Radio accessories: USB interface in the storage compartment & 2 USB interfaces in the rear center console
- Radio accessories: Central Media Display
- Remote Services
- Rear view camera
- Crosswind Assist
- Seats: Rear seat backrests foldable 40/20/40 split
- Seats: Heated seats for driver and front passenger
- Power outlet: 12V connection
- TIREFIT with tire inflation compressor
- Pre-installation for digital key handover
- Electronic immobilizer
- Central locking
- ABS - Anti-lock Braking System
- Airbag: Automatic passenger airbag deactivation
- Airbag: Kneebag for driver
- Airbag: Windowbag for driver and front passenger
- Foldable armrest in the center console for driver and front passenger
- Outdoor temperature display
- Basic services
- Diesel particulate filter
- Third brake light
- Door sills with the lettering "Mercedes-Benz"
- Driving light assistant
- Vehicle key with chrome decorative frame
- Velour floor mats
- Speed Limit Assistant
- Halogen headlights with integrated LED daytime running lights
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Communication module (LTE) for the use of Mercedes me connect services
- Paint finish: Solid
- Steering: Direct steering
- Mercedes-Benz emergency call system
- Package: Light and Visibility Package
- Package: USB Package Plus
- Radio accessories: Digital radio (DAB)
- Radio: Extended MBUX functions
- Radio: MBUX multimedia system
- Tire pressure monitoring system
- Wheels: 40.6 cm (16") alloy wheels, 4-spoke design
- Windscreen wipers with rain sensor
- Seat belts A-Class
- Seats: Comfort seats
- Lane Keeping Assist, active
- Cruise control
- Touchpad
- High-visibility vest for drivers
- Heat-insulating glass, green all around
- Decorative elements in dark carbon look

Extra equipment

- Package: Advanced (Mirror package (automatically dimming interior mirror, electrically folding exterior mirrors) - Parking package with reversing camera (Active Parking Assist with PARKTRONIC) - 4-way lumbar support - LED High Performance headlights - Adaptive Highbeam Assist)
- Traffic Sign Assistant
- Blind Spot Assist including Exit Warning Function (Radar-based assistance system with two radar sensors on the sides of the rear bumper; Visual warning: red illuminated triangle symbol in the right or left exterior mirror; Visual-acoustic warning: flashing triangle symbol and acoustic signal when the turn signal is activated; Visual-acoustic warning: flashing triangle symbol and acoustic signal when the door on the endangered side of the vehicle is opened)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Engine	Engine cowling - lower - Broken / torn - Replace
2	Headlight	Headlight - left side (+ Rechts) - Stone chips - Loss in value
3	Misc.	Misc. (Aluträger unterhalb) - Scratched - Replace
4	Front bumper	Front bumper (Sandstrahleffekt) - Stone chips - Paint
5	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
6	Bonnet	Bonnet (Sandstrahleffekt) - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Roof	Roof - Stone chips - No deduction
3	Rear bumper	Rear bumper - Scratch(es) - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction
5	Boot lid / rear door	Boot lid - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Damage 1: Engine: Engine cowling - lower - Broken / torn - Replace



Damage 1: Engine: Engine cowling - lower - Broken / torn - Replace




Damage 2: Headlight: Headlight - left side (+ Rechts) - Stone chips - Loss in value




Damage 2: Headlight: Headlight - left side (+ Rechts) - Stone chips - Loss in value



Damage 2: Headlight: Headlight - left side (+ Rechts) - Stone chips - Loss in value




Damage 2: Headlight: Headlight - left side (+ Rechts) - Stone chips - Loss in value



Damage 3: Misc.: Misc. (Aluträger unterhalb) - Scratched - Replace



Damage 3: Misc.: Misc. (Aluträger unterhalb) - Scratched - Replace




Damage 4: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint




Damage 4: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint




Damage 4: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint




Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 6: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 6: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 6: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 6: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




Wear and tear 2: Roof: Roof - Stone chips - No deduction



Wear and tear 2: Roof: Roof - Stone chips - No deduction



Wear and tear 5: Boot lid / rear door: Boot lid - dent(s) - No deduction



Wear and tear 5: Boot lid / rear door: Boot lid - dent(s) - No deduction