TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

# Expertise

Protocol number: 48118789
Order No. / Reference: 27085450
Inspection date: 15 Oct 2026

| | |
|---|---|
| Manufacturer: Skoda | Model: Kodiaq 2.0 TSI 4x4 DSG L&K |
| VIN: TMBLE7NS2R8010464 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Skoda Kodiaq 2.0 TSI 4x4 DSG L&K | |
| **Vehicle Identification number** | TMBLE7NS2R8010464 |
| **Mileage** (Read) | 100,328 km |
| **First registration** | 2 Aug 2023 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** | 08/2028 |
| (Report on hand) | |
| **Fuel type** | Petrol |
| **Engine displacement / Cylinder** | 1,984 ccm / 4 |
| **Power** | 140 kW |
| **Gearbox / Number of gears** | Automatic / 7 |
| **Type of drive** | All-wheel drive |
| **Type of vehicle** | SUV |
| **Colour / colour code** | Race Blau Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Leather |
| **Colour of upholstery** | Black |
| **Vehicle with smoke odor** | no |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 582 Tag(e) |
| **Last service on / at** | 05/2026 at 90,373 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GT132761 |
| **Previous damage / Accident** | Detectable | **Repainting** | Detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 8004 / ATO 03066 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,410 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 235/50 R19 99V | Summer tires (with run-flat tires) on Light alloy | Hankook | 3mm / 3mm |
| 2) | 235/50 R19 99V | Summer tires (with run-flat tires) on Light alloy | Hankook | 6mm / 6mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 235/55 R18 104H | Winter tyres on Light alloy | Pirelli | 6mm / 6mm |
| 2) | 235/55 R18 104H | Winter tyres on Light alloy | Continental | 7mm / 7mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| N | 145/85 R18 103M | Summer tyres on Steel | Sonstige | 4 mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- 12V socket in the center console and in the trunk
- Storage compartments behind the wheel arches in the trunk
- front aero windshield wipers
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Permanent all-wheel drive
- Traction control (ASR)
- Electrically folding exterior mirrors including interior and driver's side mirrors with automatic dimming
- Hill start assist
- Care Connect: Proactive services (10-year term) (Remote Access (1-year term))
- Decorative inlay Piano-Black L&K
- Tachometer
- Easy Start (start-stop button)
- Electric tailgate operation
- Electronic parking brake including auto-hold function
- ESC Electronic Stability Control
- Electric windows front and rear
- Front radar assistant including city emergency braking function with pedestrian detection
- Front footwell lighting
- Cruise control
- Tinted windows
- Isofix anchorage on the outer rear seats including top tether
- Boot cover, roll-up and removable
- Front and rear headrests are height-adjustable.
- Paint finish: Metallic / Pearl effect
- LED matrix headlights and dynamic high beam assist (Light Assist)
- LED taillights in crystal glass look with animated turn signals
- Rear center armrest with cup holders
- Engine drag torque control (MSR)
- Otto particulate filter
- Stainless steel pedal design
- Wheel arch cover
- Radio accessories: CANTON sound system (11 speakers, 1 subwoofer, digital equalizer, 575W)
- Tire pressure monitoring
- Wheels: 19" Sirius alloy wheels, diamond-cut finish (7Jx19, tires 235/50 R19 99V ET43)
- Heated windshield washer nozzles, front
- Electromechanical power steering
- Seats: Heated front seats
- Seats: Electrically adjustable front seats with memory function
- Storage compartment on the left wheel arch
- Adaptive Cruise Control (ACC) (control range up to 210 km/h) (replaces cruise control)
- Airbag, driver and passenger
- Airbag, head airbags
- Allergen filter
- Anti-lock braking system (ABS)
- Dashboard in black / black, door trim in black
- Electrically adjustable and heated exterior mirrors with integrated side indicators
- Hydraulic brake assist (HBA)
- Grey headliner
- Roof rails, anodized
- Digital Cockpit (8")
- Third brake light
- eCall (automatic emergency call function in case of an accident with airbag deployment)
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor
- High Beam Assist (Light Assist)
- front and rear floor mats
- rear footwell lighting
- Closed storage compartment on the driver's side
- Transmission: 7-speed dual-clutch transmission (DSG)
- Illuminated glove compartment
- Kessy - keyless entry and start-stop system
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger including humidity sensor and odor and allergen filter)
- LED ambient lighting (decorative strips in the door panels with selectable color climate, LED reading lights in the front, LED lighting for the make-up mirrors in the sun visors)
- Reading lights at the front of the headliner
- Front center armrest, including storage compartment
- Multi-collision brake
- Front and rear parking sensors
- Progressive steering
- Radio: Bolero infotainment system
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Wireless SmartLink
- Wheels: 18" steel spare wheel, space-saving
- Rear seat backrest split 60:40, foldable, longitudinally adjustable, backrest angle adjustable
- Headlights washer / wiper system
- Kodiaq seat belts
- Seats: Adjustable lumbar support in the front seats
- Seats: Height-adjustable front seats
- Seats: Remote release of the rear seat backrests (2nd row) in the boot
- Sun visor on driver and passenger side with illuminated vanity mirror

- Skoda Care Connect (SOS emergency call function (eCall, including automatic activation in the event of an accident with airbag deployment) - Mobility service (connection for rapid assistance in case of breakdown) - Information service (connection to the hotline for all questions regarding vehicle functions) - Free remote vehicle access for one year with access to vehicle data/functions via smartphone, e.g., parking position, activating hazard warning lights, current fuel level, etc.)
- Front door sill trims
- Variable fastening concept in the trunk
- Lashing eyes in the trunk
- Central locking with remote control
- Speed limiter
- Lane Assist, Blind Spot Detection and Parking Assist
- Sunset (rear window and rear side windows tinted dark)
- Telephone: Comfort hands-free telephone system including phone box (with inductive charging function (connection via external antenna))
- 360° surround view camera (area view) including reversing camera
- Immobiliser

### Extra equipment

- Swiveling trailer hitch (with electric release, including trailer stabilization)
- Steering wheel: Heated steering wheel (height and reach adjustable leather steering wheel with multifunction buttons including paddle shifters)
- Package: Business Columbus (L&K) (Dynamic radio navigation system Columbus - 9.2" capacitive color display - Digital Cockpit Plus (10") - Driver fatigue detection - 230V socket and one USB charging port (Type-C) - Acoustic glazing in the front doors - Luggage net partition - Infotainment Online (3-year subscription))
- Seats: Heated front and outer rear seats
- Auxiliary heating
- Traveller Plus (DSG) assistance system (Predictive Adaptive Cruise Control ACC (control range up to 210 km/h) - Lane Assist, Blind Spot Detection and Parking Assist, Exit Warning - Adaptive Lane Guidance - Park Assist - Traffic Jam and Emergency Assist - Traffic Sign Recognition)
- Package: Family (Removable waste bin for the door panel - Sunshades for the rear side windows - Door edge protectors)
- Upholstery: Glamour leather interior with ventilated Ergo front seats (including manual seat extension - seat surfaces made of fine nappa leather, combined with high-quality materials)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | 2nd wheel set | 1 alloy rim - Scratched - No deduction |
| 2 | Roof | Roof - dent(s) - Smart repair |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Vehicle glazing | Windscreen with lane departure assistant - Stone chips - No deduction |
| 2 | Front bumper | Bumper with Parktronic - Stone chips - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Front, Side right, Provided by user / customer, from 9 Sept 2024 | 5.145,82 € |

## Repainting

| No. | Repainting |
|---|---|
| 1 | Mudguard - right side, Door - front right side, Professionally carried out |

## Paint coat thickness measurement

| | | | |
|---|---|---|---|
| Mudguard - right side | 163 µm | Door - front right side | 195 µm |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres




**Figure 13:** Documents




**Figure 14:** Documents





**Figure 15:** Documents



**Figure 16:** Additional tyres




**Figure 17:** Navigation




**Figure 18:** Misc.




**Figure 19:** Misc.




**Figure 20:** Misc.




**Figure 21:** Misc.



**Figure 22:** Misc.




**Figure 23:** Misc.




**Figure 24:** Misc.




**Figure 25:** Misc.



**Figure 26:** Misc.




**Figure 27:** Misc.




**Figure 28:** Misc.




**Figure 29:** Misc.




**Figure 30:** Misc.



**Figure 31:** Misc.




**Figure 32:** Misc.




**Figure 33:** Misc.




**Damage 1:** 2nd wheel set: 1 alloy rim - Scratched - No deduction



**Damage 1:** 2nd wheel set: 1 alloy rim - Scratched - No deduction



**Damage 2:** Roof: Roof - dent(s) - Smart repair



**Damage 2:** Roof: Roof - dent(s) - Smart repair




**Mudguard - right side:** 163 µm




**Door - front right side:** 195 µm