APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	HM Tongeren
Make:	VOLKSWAGEN
Model / version:	TIGUAN
Wine:	WVGZZZ5NZNW055501
Plate:	2CKA015
Mileage:	88577
First registration:	19/08/2022
Color:	Deep Black P

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓


PICTURES
























































WINE INFORMATION

8 speakers
7 reports
Adaptive headlights
Reference letter (J)
Front width 7.0
Rear diameter 17
Forward speed index H
Rear width 215
On-board computer
1.50 liters
Pearlescent varnished effect
Phone pre-wiring
Front-wheel drive
LED spotlights
Front diameter 17
Rear width 7.0
Front height 65
Rear speed rating H
Automatic climate control
Essence
110 kW
Electrically folding mirrors
Sequential transmission
Automatic headlights
Material: alloy
Rear diameter 17
Front diameter 17
Rear height 65
Front width 215
Air conditioning refrigerant 1234YF
1498 cm3
150 hp
Automatic day/night interior rearview mirror

Fabric trim
Front parking assistance
Rearview camera
Heads-up display
Appel de secours
Vitres de custode teintées foncées
Airbag de genoux

enjoliveurs des vitres latérales blancs
tiroir sous les sièges av
réservoir à charbon actif (EVAP)
sans support de plaque immat av

galerie de pavillon chromé

Leather steering wheel
Rear parking assistance
Automatic distance control
Displaying and reading road signs
Lunette arrière teintée foncée
détecteur de pluie essuie-vitre
Freinage d'urgence assistée autonome (urbain)

radio avec récepteur numérique
console pavillon avec vide-poches
barre stabilisatrice ar 21,7x3,6 mm
entretien à intervalle flexible (Long Life)
QI6

Multifunction steering wheel
Front camera
Stop & Start Equipment
Ouverture du coffre électriquement
Vitres portes arrière teintées foncées
Airbag passager désactivable
depuis 06.22

Infotainment-System (MIB3)
dossier siège passager rabattable
services Online
ceintures de sécurité ar avec prétensionneurs

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		215/65R17 99V	Summer		?
Front right	5 mm		215/65R17 99V	Summer		?
Rear left	5 mm		215/65R17 99V	Summer		?
Rear right	5 mm		215/65R17 99V	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Bumper F	Grooved
2	Bumper grille	Broken
3	Bumper moulding F	Broken
5	Wing FL	Dent(s) and scratch(es)
6	Roof - +- 47 deuken	Hail damage
7	Bonnet	Dent(s)
8	Tailgate / Boot	Dent(s)
9	Bumper R	Grooved

Total: 8

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Bumper F - Grooved





2 - Bumper grille - Broken





3 - Bumper moulding F - Broken







5 - Wing FL - Dent(s) and scratch(es)





6 - Roof - +- 47 deuken - Hail damage



7 - Bonnet - Dent(s)




8 - Tailgate / Boot - Dent(s)






9 - Bumper R - Grooved







4 - Bodywork - Dent(s) and scratch(es) - Renta®


















SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

15/10/2026 09:33

