TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48612738
Order No. / Reference: 27249044
Inspection date: 2 Nov 2026

Manufacturer: Mercedes-Benz	Model: 315 CDI Sprinter Lang HA
VIN: W1V9071351N218759	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz 315 CDI Sprinter Lang HA	
Vehicle Identification number	W1V9071351N218759
Mileage (Read)	105,668 km
First registration	30 Sept 2022
Number of holders	1
Next periodical technical inspection	09/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Verkehrsblau
Doors / Seats	2 / 3
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	447 Tag(e)
Last service on / at	02/2026 at 87,533 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP647659
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / BAU 48373		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 119Q	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	235/65 R16 119Q	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 119Q	All-season tyres on Steel	Continental	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment above windshield
- Rear towing eye
- ADAPTIVE ESP (latest generation) with load- and speed-dependent driving dynamics control
- Outdoor temperature display
- Battery: fleece battery 12 V / 92 Ah
- Diesel particulate filter and SCR
- Driving light assistant
- Electric window regulator for driver and passenger door
- Noise measures
- Seatbelt warning device for front passenger seat
- Main tank 71 liters
- KEYLESS start
- Communication module (LTE) for digital services
- Steering wheel adjustable for tilt and height
- Longitudinal beam reinforcement
- Marker lights, side
- Without weight increase/decrease: 3,500 kg
- Upholstery: Cloth
- Radio: Pre-installation for digital radio DAB
- Tires: Premium protection tires (3 years)
- Wheels: Steel rims 6.5 J x 16
- Power steering
- Seats: Driver's seat armrest
- Seats: Driver's seat
- Start-stop function
- Daytime running light
- Pre-installation for Remote Services Plus
- Immobiliser
- Central locking with radio remote control
- Storage compartment under cockpit
- Axle ratio i = 3.923
- Driver's side airbag
- Electrically adjustable and heated exterior mirrors, left and right
- Brake lights, adaptive
- Tachometer
- Chassis stabilization stage 1
- Generator 14 V / 200 A
- Transmission: 6-speed manual ECO Gear 360
- Seatbelt warning device for driver's seat
- Instrument panel and combination instrument with various storage options
- Headrests (2), front
- Headlight range control
- Side marker lights (pre-wiring)
- Mercedes-Benz emergency call system
- Breakdown management
- Radio: Radio preparation
- Tires: Tires without specified make
- Tires: Summer tires
- Crosswind Assist
- Seats: Passenger seat armrest
- Seats: Adjustable passenger seat
- Special control communication module
- Speedometer km/h
- First aid kit
- Warning triangle
- Heat-insulating glass
- Vehicle registration certificate, Part II, prepared

Extra equipment

- COC documents
- Chassis stabilization level II
- Fleet Comfort Package Z7K
- Interior mirror
- Paintwork: Special paintwork
- MBUX multimedia system with 7-inch touchscreen (High-resolution 7-inch touchscreen (960 x 540 pixels), AM/FM radio with dual tuner, Bluetooth connectivity with audio streaming and hands-free function, smartphone integration via Android Auto or Apple CarPlay, multimedia connection unit for connecting portable devices via a USB-C interface, 4 x 25 W output power, sound adjustment, separate volume control for audio and telephone, 2-way front speakers)
- Flatbed with aluminum sideboards
- Tires: Continental brand
- Spare wheel
- Wheels: Steel rims 6.5 J x 16 (with tires 225/75 R16 C low rolling resistance tires)
- vibration damper
- Seats: Driver's seat box, low
- USB 5V socket
- Front axle with increased load capacity in conjunction with Stage II stabilization
- Additional heater
- Digital operating instructions
- Window: Back wall
- Main tank 93 liters
- Tempmatic controlled air conditioning
- Steering wheel: Multifunction steering wheel
- Navigation (linguatronic voice control, Wi-Fi hotspot, multimedia connection unit for connecting portable devices via an additional USB-C interface, center fill speaker for improved sound and voice output, improved hands-free function, dual-phone operation, digital operating instructions)
- Navigation accessories: Live Traffic Information
- Package: Acoustics in conjunction with MBUX
- Package: SMOKER
- Tires: All-season tires in category V, size 225/75 R16 C
- Tires: Tire brand, special request
- Spare wheel carrier with jack (under frame end)
- Wheels: Hydraulic jack
- Gear console optimized for passenger side
- Seats: Passenger seat, two-seater
- Seats: Suspension seat comfort version, driver's seat
- EU underride protection
- Elimination of vehicle lowering
- Heat-insulating glass with band filter on the windshield
- Registration certificate, Part II

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - Smart repair
2	Door - front left side	Door seal - Broken / torn - Replace
3	Misc.	Main inspection - Due - Perform
4	Body	B-pillar - right side - Scratched - Smart repair
5	Body	B-pillar - left side - Scratch(es) - Smart repair
6	Front bumper	Front bumper (Unlackiertes Kunststoffbauteil) - Scratch(es) - Loss in value
7	Boot lid / rear door	Boot lid (Pritschen Heckwand & verkratzt/verschürft) - Deformed - Loss in value
8	Sill - left side	Sill - Scratched - Smart repair
9	Interior	Cargo area floor (Pritschen Ladeboden & verkratzt/verschürft) - Corrosion - Loss in value
10	Side panel - rear right side	Side panel (Pritschen Bordwand rechts & verkratzt/verschürft) - Deformed - Loss in value
11	Side panel - rear left side	Side panel (Pritschen Bordwand links & verkratzt/verschürft) - Deformed - Loss in value
12	Mudguard - right side	Mudguard - right side - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Door - front right side	Door - Scratched - No deduction
2	Seat - front	Seat cover - left side (Schonbezug, nicht Bestandteil der Ausstattung) - Damaged - No deduction
3	Interior	Interior - Soiled - No deduction
4	Rear bumper	Cover - bumper - rear (Unterfahrschutz Hinten - Abdeckung) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Der verbaute Radsatz ist höherwertiger als der, in der Ausstattungsliste angegebene. Für den Radsatz wurde kein Nachweis erbracht.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.





Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 2: Door - front left side: Door seal - Broken / torn - Replace



Damage 2: Door - front left side: Door seal - Broken / torn - Replace



Damage 2: Door - front left side: Door seal - Broken / torn - Replace



Damage 3: Misc.: Main inspection - Due - Perform




Damage 4: Body: B-pillar - right side - Scratched - Smart repair



Damage 4: Body: B-pillar - right side - Scratched - Smart repair



Damage 4: Body: B-pillar - right side - Scratched - Smart repair



Damage 5: Body: B-pillar - left side - Scratch(es) - Smart repair



Damage 5: Body: B-pillar - left side - Scratch(es) - Smart repair



Damage 5: Body: B-pillar - left side - Scratch(es) - Smart repair



Damage 6: Front bumper: Front bumper (Unlackiertes Kunststoffbauteil) - Scratch(es) - Loss in value



Damage 6: Front bumper: Front bumper (Unlackiertes Kunststoffbauteil) - Scratch(es) - Loss in value



Damage 6: Front bumper: Front bumper (Unlackiertes Kunststoffbauteil) - Scratch(es) - Loss in value



Damage 6: Front bumper: Front bumper (Unlackiertes Kunststoffbauteil) - Scratch(es) - Loss in value



Damage 7: Boot lid / rear door: Boot lid (Pritschen Heckwand & verkratzt/ verschürft) - Deformed - Loss in value



Damage 7: Boot lid / rear door: Boot lid (Pritschen Heckwand & verkratzt/ verschürft) - Deformed - Loss in value



Damage 7: Boot lid / rear door: Boot lid (Pritschen Heckwand & verkratzt/ verschürft) - Deformed - Loss in value



Damage 7: Boot lid / rear door: Boot lid (Pritschen Heckwand & verkratzt/ verschürft) - Deformed - Loss in value



Damage 8: Sill - left side: Sill - Scratched - Smart repair



Damage 8: Sill - left side: Sill - Scratched - Smart repair



Damage 8: Sill - left side: Sill - Scratched - Smart repair



Damage 8: Sill - left side: Sill - Scratched - Smart repair



Damage 9: Interior: Cargo area floor (Pritschen Ladeboden & verkratzt/ verschürft) - Corrosion - Loss in value



Damage 9: Interior: Cargo area floor (Pritschen Ladeboden & verkratzt/ verschürft) - Corrosion - Loss in value




Damage 9: Interior: Cargo area floor (Pritschen Ladeboden & verkratzt/verschürft) - Corrosion - Loss in value



Damage 9: Interior: Cargo area floor (Pritschen Ladeboden & verkratzt/verschürft) - Corrosion - Loss in value



Damage 10: Side panel - rear right side: Side panel (Pritschen Bordwand rechts & verkratzt/verschürft) - Deformed - Loss in value



Damage 10: Side panel - rear right side: Side panel (Pritschen Bordwand rechts & verkratzt/verschürft) - Deformed - Loss in value



Damage 10: Side panel - rear right side: Side panel (Pritschen Bordwand rechts & verkratzt/verschürft) - Deformed - Loss in value



Damage 10: Side panel - rear right side: Side panel (Pritschen Bordwand rechts & verkratzt/verschürft) - Deformed - Loss in value



Damage 11: Side panel - rear left side: Side panel (Pritschen Bordwand links & verkratzt/verschürft) - Deformed - Loss in value




Damage 11: Side panel - rear left side: Side panel (Pritschen Bordwand links & verkratzt/verschürft) - Deformed - Loss in value




Damage 11: Side panel - rear left side: Side panel (Pritschen Bordwand links & verkratzt/verschürft) - Deformed - Loss in value



Damage 11: Side panel - rear left side: Side panel (Pritschen Bordwand links & verkratzt/verschürft) - Deformed - Loss in value



Damage 12: Mudguard - right side: Mudguard - right side - Scratched - Paint



Damage 12: Mudguard - right side: Mudguard - right side - Scratched - Paint



Damage 12: Mudguard - right side: Mudguard - right side - Scratched - Paint



Damage 12: Mudguard - right side: Mudguard - right side - Scratched - Paint



Wear and tear 1: Door - front right side: Door - Scratched - No deduction




Wear and tear 1: Door - front right side: Door - Scratched - No deduction




Wear and tear 1: Door - front right side: Door - Scratched - No deduction



Wear and tear 1: Door - front right side: Door - Scratched - No deduction



Wear and tear 1: Door - front right side: Door - Scratched - No deduction




Wear and tear 1: Door - front right side: Door - Scratched - No deduction




Wear and tear 2: Seat - front: Seat cover - left side (Schonbezug, nicht Bestandteil der Ausstattung) - Damaged - No deduction




Wear and tear 2: Seat - front: Seat cover - left side (Schonbezug, nicht Bestandteil der Ausstattung) - Damaged - No deduction



Wear and tear 2: Seat - front: Seat cover - left side (Schonbezug, nicht Bestandteil der Ausstattung) - Damaged - No deduction



Wear and tear 3: Interior: Interior - Soiled - No deduction



Wear and tear 3: Interior: Interior - Soiled - No deduction



Wear and tear 4: Rear bumper: Cover - bumper - rear (Unterfahrschutz Hinten - Abdeckung) - Scratch(es) - No deduction



Wear and tear 4: Rear bumper: Cover - bumper - rear (Unterfahrschutz Hinten - Abdeckung) - Scratch(es) - No deduction



Wear and tear 4: Rear bumper: Cover - bumper - rear (Unterfahrschutz Hinten - Abdeckung) - Scratch(es) - No deduction