TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48122421
Order No. / Reference: 27105143
Inspection date: 15 Oct 2026

Manufacturer: Opel	Model: Vivaro 2.0 D Cargo L EHZ
VIN: VXEVFEHTMPZ030147	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Vivaro 2.0 D Cargo L EHZ	
Vehicle Identification number	VXEVFEHTMPZ030147
Mileage (Read)	160,584 km
First registration	11 Jul 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	07/2027
Fuel type	Diesel
Engine displacement / Cylinder	1,997 ccm / 4
Power	106 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Kaolin Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	1,180 km
Last service on / at	05/2026 at 154,764 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS843364
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	3003 / BCD 01047		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,100 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	All-season tyres on Steel rim with wheel cover	Kumho	0 mm
	215/65 R16 102V	All-season tyres on Steel rim with wheel cover	Falken	7 mm
2)	215/65 R16 109T	All-season tyres on Steel rim with wheel cover	Kumho	0mm / 0mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 109T C	Summer tyres on Steel	Continental	9 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Driver and passenger side airbags
- On-board computer
- Diesel particulate filter, maintenance-free
- Rear parking aid (acoustic)
- Increased payload +300 kg
- Transmission: 6-speed transmission
- Paint finish: Solid color paint
- Radio: Basic Radio
- Wheels: Steel wheels 7 J x 16 with wheel hub cover (with summer tires 215/65 R 16 C 106T)
- Start/Stop System
- Partition wall, sheet metal cladding
- Doors: Rear wing doors 50/50, opening 180°, sheet metal
- Immobiliser
- Anti-lock braking system (ABS)
- third brake light
- Tachometer
- Electronic Stability Program (ESP Plus)
- Speed controller and speed limiter
- Air conditioning
- Upholstery: Cloth
- Tire pressure monitoring system
- Power steering
- Seats: Driver's seat height-adjustable, with armrest and lumbar support (double passenger seat with storage compartments under the bench seat)
- Doors: Sliding door on the right, manual
- Central locking with remote control

Extra equipment

- Flooring: Protective wooden floor (9mm, non-slip) and wooden side walls (6mm)
- Wheels: Spare wheel
- Security package
- Package: 180-degree panoramic reversing camera (reversing camera - RCC audio system - analog instrument with LCD text display)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Missing - Replace
2	Mudguard - left side	Mudguard - left side - dent(s) - Smart repair
3	Engine	Engine (Ölverlust - Mehrkosten möglich) - Leaking - Perform diagnosis
4	Wheel / tyres	Tyre - front left side - Worn - Replace
5	Side panel - rear right side	Sill - dent(s) - Smart repair
6	Front bumper	Front bumper (Unterteil) - Deformed - Loss in value
7	Wheel / tyres	Tyre - right - Porous / cracked - Replace
8	Sill - right side	Sill - front - Scratched - Paint
9	Braking system	Brake discs and pads - rear - Worn - Replace
10	Sliding door, right	Sliding door (+ Kratzer) - Corrosion - Repair and paint
11	Door - front left side	Door - dent(s) - Repair and paint
12	Rear bumper	Bumper with Parktronic (+ verformt - inkl. Stoßf. links) - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Side panel - rear left side	Side panel - dent(s) - No deduction
3	Rear bumper	Bumper - rear right side - Scratch(es) - No deduction
4	Bonnet	Bonnet - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Door - front left side, Professionally carried out

Paint coat thickness measurement

Door - front left side	386 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Damage 1: Wheel / tyres: Wheel cover - front right side - Missing - Replace



Damage 2: Mudguard - left side: Mudguard - left side - dent(s) - Smart repair



Damage 2: Mudguard - left side: Mudguard - left side - dent(s) - Smart repair



Damage 3: Engine: Engine (Ölverlust - Mehrkosten möglich) - Leaking - Perform diagnosis



Damage 3: Engine: Engine (Ölverlust - Mehrkosten möglich) - Leaking - Perform diagnosis



Damage 4: Wheel / tyres: Tyre - front left side - Worn - Replace



Damage 4: Wheel / tyres: Tyre - front left side - Worn - Replace



Damage 4: Wheel / tyres: Tyre - front left side - Worn - Replace



Damage 5: Side panel - rear right side: Sill - dent(s) - Smart repair



Damage 5: Side panel - rear right side: Sill - dent(s) - Smart repair



Damage 5: Side panel - rear right side: Sill - dent(s) - Smart repair



Damage 5: Side panel - rear right side: Sill - dent(s) - Smart repair



Damage 6: Front bumper: Front bumper (Unterteil) - Deformed - Loss in value



Damage 6: Front bumper: Front bumper (Unterteil) - Deformed - Loss in value



Damage 6: Front bumper: Front bumper (Unterteil) - Deformed - Loss in value



Damage 7: Wheel / tyres: Tyre - right - Porous / cracked - Replace




Damage 7: Wheel / tyres: Tyre - right - Porous / cracked - Replace



Damage 7: Wheel / tyres: Tyre - right - Porous / cracked - Replace



Damage 7: Wheel / tyres: Tyre - right - Porous / cracked - Replace



Damage 8: Sill - right side: Sill - front - Scratched - Paint



Damage 8: Sill - right side: Sill - front - Scratched - Paint



Damage 9: Braking system: Brake discs and pads - rear - Worn - Replace




Damage 9: Braking system: Brake discs and pads - rear - Worn - Replace



Damage 9: Braking system: Brake discs and pads - rear - Worn - Replace



Damage 9: Braking system: Brake discs and pads - rear - Worn - Replace




Damage 9: Braking system: Brake discs and pads - rear - Worn - Replace



Damage 9: Braking system: Brake discs and pads - rear - Worn - Replace



Damage 10: Sliding door, right: Sliding door (+ Kratzer) - Corrosion - Repair and paint




Damage 10: Sliding door, right: Sliding door (+ Kratzer) - Corrosion - Repair and paint



Damage 10: Sliding door, right: Sliding door (+ Kratzer) - Corrosion - Repair and paint




Damage 10: Sliding door, right: Sliding door (+ Kratzer) - Corrosion - Repair and paint



Damage 10: Sliding door, right: Sliding door (+ Kratzer) - Corrosion - Repair and paint




Damage 10: Sliding door, right: Sliding door (+ Kratzer) - Corrosion - Repair and paint



Damage 10: Sliding door, right: Sliding door (+ Kratzer) - Corrosion - Repair and paint



Damage 11: Door - front left side: Door - dent(s) - Repair and paint



Damage 11: Door - front left side: Door - dent(s) - Repair and paint



Damage 12: Rear bumper: Bumper with Parktronic (+ verformt - inkl. Stoßf. links) - Scratched - Replace



Damage 12: Rear bumper: Bumper with Parktronic (+ verformt - inkl. Stoßf. links) - Scratched - Replace



Damage 12: Rear bumper: Bumper with Parktronic (+ verformt - inkl. Stoßf. links) - Scratched - Replace



Damage 12: Rear bumper: Bumper with Parktronic (+ verformt - inkl. Stoßf. links) - Scratched - Replace



Damage 12: Rear bumper: Bumper with Parktronic (+ verformt - inkl. Stoßf. links) - Scratched - Replace




Damage 12: Rear bumper: Bumper with Parktronic (+ verformt - inkl. Stoßf. links) - Scratched - Replace



Damage 12: Rear bumper: Bumper with Parktronic (+ verformt - inkl. Stoßf. links) - Scratched - Replace



Wear and tear 4: Bonnet: Bonnet - dent(s) - No deduction



Wear and tear 4: Bonnet: Bonnet - dent(s) - No deduction



Door - front left side: 386 µm