TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Expertise

Protocol number: 48505958
Order No. / Reference: 27248236
Inspection date: 3 Nov 2026

Manufacturer: Mercedes-Benz	Model: Vito 116 CDI Lang HA Aut. PRO
VIN: W1V44760313854076	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 116 CDI Lang HA Aut. PRO	
Vehicle Identification number	W1V44760313854076
Mileage (Read)	90,341 km
First registration	30 Apr 2021
Number of holders	1
Next periodical technical inspection	04/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	120 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Selenite Grey Metallic 7992
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	182 Tag(e)
Last service on / at	04/2025 at 74,034 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FZ385524
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	short drive on the company premises	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / BBJ 00597		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 109T	Winter tyres on Steel rim with wheel cover	Continental	3mm / 6mm
2)	225/55 R17 109T	Winter tyres on Steel rim with wheel cover	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	225/55 R17 109H	Winter tyres on Steel	Continental	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (24 liters)
- Attention Assistant
- Outdoor temperature display
- Hill start assist
- Brake lights, adaptive
- Ceiling interior light (in driver and passenger area)
- ECO start/stop function
- Electrical components for trailer socket (electrical lines for power supply of the trailer - without trailer hitch control unit)
- Driving light assistant (automatically switching on driving lights)
- Electric window regulator driver/passenger (with anti-pinch protection, quick lowering and raising)
- 9G-TRONIC PLUS automatic transmission
- Lockable glove box
- Interior trim of cargo area, side
- Instrument cluster with pixel matrix display (operated via the buttons on the multifunction steering wheel - round instruments for speedometer and tachometer or fuel level and coolant temperature - high-quality pixel matrix display in white and red between the large round instruments)
- Multifunction steering wheel (with trip computer)
- Halogen fog lights
- Upholstery: Caluma fabric, black
- Full wheel cover
- Rain sensor
- Tires: 205/65 R 16
- Wheels: Steel rims 6.5 J x 16
- Key: 3-button remote control
- electromechanical power steering
- Seats: Driver's seat Plus with flat seat surface (with Rawson Plus fabric)
- 12V socket
- continuous partition wall
- Lashing eyes in the cargo area
- Warning triangle
- Immobiliser
- Airbag for driver and front passenger
- Electrically adjustable and heated exterior mirrors, left and right
- third brake light
- Comfort roof control unit
- Diesel particulate filter
- Entry grab handle for the cargo area sliding door
- Electronic Stability Program (ADAPTIVE ESP) with integrated anti-lock braking system (ABS) (traction control (ASR) - electronic brake force distribution (EBD) - brake assist (BAS))
- Parking brake
- Speed limit 210 km/h
- Seatbelt warning device for driver and front passenger seat
- Tailgate with an opening angle of approximately 90°
- Tempmatic controlled air conditioning
- Headrests (2), front
- Paint finish: Solid color paint
- Steering wheel adjustable for tilt and height
- Headlight range control
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Package: BlueEFFICIENCY (Efficiency Package)
- Radio/Telematics, Audio 10 (DAB Digital Radio - 3.5-inch LCD display - Bluetooth hands-free system - 2-way front speakers)
- Tires: Tires without specified make
- Sliding door on the right, cargo/passenger compartment
- Crosswind Assist
- Seat: Lumbar support driver's seat
- Seats: Comfort driver's seat
- Front stabilizer
- Cruise control
- First aid kit
- Pre-installation for Remote Services Plus
- Maintenance interval indicator >>ASSYST<
- Central locking with radio remote control

Extra equipment

- Towing capacity 2500 kg
- Battery: fleece battery 12 V / 92 Ah
- Wooden floor (cargo area)
- Large fuel tank, approx. 70 liters
- LED light strip in the cargo area
- Tires: 225/55R17
- Tires: M+S 225/55 R 17
- Spare wheel under the rear of the vehicle with jack
- High-resolution reversing camera with guide lines
- Seats: Passenger seat, two-seater
- Towbar (fixed ball head)
- Roof rails (instead of C-rails)
- Interior lining of the cargo area up to roof height (wood)
- Paint finish: Metallic
- Radio: Audio 30 (DAB Digital Radio - 7" LCD touchscreen - Apple CarPlay and Android Auto - Bluetooth 3.0, hands-free system - 2-way front speakers)
- Wheels: Steel rims 6.5 J x 17
- Rear door: Rear swing doors, opening to side wall

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Rear door - left side (innen) - dent(s) - Loss in value
2	Wheel / tyres	Tyre - front left side - Does not meet the leasing specifications - Replace
3	Roof	Roof (teilweise) - Dent / paintcoat damage - Smart repair
4	Interior	Cargo area floor (Holzboden) - Missing - Replace
5	Rear of vehicle	Boot floor (Teilersatz) - Holes - Repair and paint
6	Boot lid / rear door	Rear door - left side (Beulen- Teilweise) - Deformed - Repair and paint
7	Roof	Roof - Damage by hail - Smooth repair work
8	Side panel - rear left side	Side panel (Teilweise) - Dent / paintcoat damage - Repair and paint
9	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior (Laderaum) - Dent / paintcoat damage - No deduction
2	Headlight	Headlight - right side - Scratch(es) - No deduction
3	Body	Body - Scratch(es) - No deduction
4	Boot lid / rear door	Rear door - right side (+ Beule) - dent(s) - No deduction
5	Sliding door, right	Sliding door - Dent / paintcoat damage - Smart repair
6	Door - front right side	Door - Dent / paintcoat damage - Smart repair

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Damage 1: Boot lid / rear door: Rear door - left side (innen) - dent(s) - Loss in value



Damage 1: Boot lid / rear door: Rear door - left side (innen) - dent(s) - Loss in value



Damage 1: Boot lid / rear door: Rear door - left side (innen) - dent(s) - Loss in value



Damage 1: Boot lid / rear door: Rear door - left side (innen) - dent(s) - Loss in value




Damage 2: Wheel / tyres: Tyre - front left side - Does not meet the leasing specifications - Replace



Damage 2: Wheel / tyres: Tyre - front left side - Does not meet the leasing specifications - Replace




Damage 3: Roof: Roof (teilweise) - Dent / paintcoat damage - Smart repair



Damage 3: Roof: Roof (teilweise) - Dent / paintcoat damage - Smart repair




Damage 3: Roof: Roof (teilweise) - Dent / paintcoat damage - Smart repair




Damage 3: Roof: Roof (teilweise) - Dent / paintcoat damage - Smart repair




Damage 3: Roof: Roof (teilweise) - Dent / paintcoat damage - Smart repair



Damage 3: Roof: Roof (teilweise) - Dent / paintcoat damage - Smart repair



Damage 3: Roof: Roof (teilweise) - Dent / paintcoat damage - Smart repair




Damage 3: Roof: Roof (teilweise) - Dent / paintcoat damage - Smart repair



Damage 4: Interior: Cargo area floor (Holzboden) - Missing - Replace



Damage 5: Rear of vehicle: Boot floor (Teilersatz) - Holes - Repair and paint



Damage 5: Rear of vehicle: Boot floor (Teilersatz) - Holes - Repair and paint



Damage 6: Boot lid / rear door: Rear door - left side (Beulen- Teilweise) - Deformed - Repair and paint



Damage 6: Boot lid / rear door: Rear door - left side (Beulen- Teilweise) - Deformed - Repair and paint



Damage 6: Boot lid / rear door: Rear door - left side (Beulen- Teilweise) - Deformed - Repair and paint



Damage 6: Boot lid / rear door: Rear door - left side (Beulen- Teilweise) - Deformed - Repair and paint



Damage 7: Roof: Roof - Damage by hail - Smooth repair work



Damage 7: Roof: Roof - Damage by hail - Smooth repair work



Damage 7: Roof: Roof - Damage by hail - Smooth repair work




Damage 7: Roof: Roof - Damage by hail - Smooth repair work




Damage 7: Roof: Roof - Damage by hail - Smooth repair work



Damage 7: Roof: Roof - Damage by hail - Smooth repair work



Damage 7: Roof: Roof - Damage by hail - Smooth repair work



Damage 7: Roof: Roof - Damage by hail - Smooth repair work



Damage 8: Side panel - rear left side: Side panel (Teilweise) - Dent / paintcoat damage - Repair and paint



Damage 8: Side panel - rear left side: Side panel (Teilweise) - Dent / paintcoat damage - Repair and paint




Damage 8: Side panel - rear left side: Side panel (Teilweise) - Dent / paintcoat damage - Repair and paint



Damage 8: Side panel - rear left side: Side panel (Teilweise) - Dent / paintcoat damage - Repair and paint



Damage 8: Side panel - rear left side: Side panel (Teilweise) - Dent / paintcoat damage - Repair and paint



Damage 8: Side panel - rear left side: Side panel (Teilweise) - Dent / paintcoat damage - Repair and paint



Damage 8: Side panel - rear left side: Side panel (Teilweise) - Dent / paintcoat damage - Repair and paint



Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 9: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Wear and tear 2: Headlight: Headlight - right side - Scratch(es) - No deduction



Wear and tear 2: Headlight: Headlight - right side - Scratch(es) - No deduction



Wear and tear 4: Boot lid / rear door: Rear door - right side (+ Beule) - dent(s) - No deduction



Wear and tear 4: Boot lid / rear door: Rear door - right side (+ Beule) - dent(s) - No deduction



Wear and tear 4: Boot lid / rear door: Rear door - right side (+ Beule) - dent(s) - No deduction



Wear and tear 4: Boot lid / rear door: Rear door - right side (+ Beule) - dent(s) - No deduction



Wear and tear 4: Boot lid / rear door: Rear door - right side (+ Beule) - dent(s) - No deduction




Wear and tear 4: Boot lid / rear door: Rear door - right side (+ Beule) - dent(s) - No deduction




Wear and tear 4: Boot lid / rear door: Rear door - right side (+ Beule) - dent(s) - No deduction



Wear and tear 5: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Wear and tear 5: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair



Wear and tear 5: Sliding door, right: Sliding door - Dent / paintcoat damage - Smart repair

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig


Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Wear and tear 6: Door - front right side: Door - Dent / paintcoat damage - Smart repair




Wear and tear 6: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Wear and tear 6: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Wear and tear 6: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Wear and tear 6: Door - front right side: Door - Dent / paintcoat damage - Smart repair